## SO # 03-313693

## **CUSTOMER COPY CUSTOMER COPY**



Printed 02/09/2024 5:06:13 PM

**Customer No** 217025

Rachel Richter 1134 S 49th St

Milwaukee, WI 53214-3524

(414) 698-2175 Bus Home Cell (414) 698-2175 Today Email sheepygirl2@gmail.com

User

tll

24.28

Advisor Thomas Lowther Promised Shop S1 Opened Priority Cashiered	02/09/2024 5:00 PM 02/09/2024 3:34 PM 02/09/2024 5:05 PM	Tag Location PO #	686
---	--	-------------------------	-----

License ASX130		Odometer In 162481	Odometer Out 162481	InServ Date	Stock No
Year	Make	Model		Model No	Color
2008	TOYOTA	PRIUS		1220	BROWN
Vehicle	ID No	Selling	Dealer Ext	tended Warranty	Delivery Date
	20U683384		F:40		

VISA

	Term VISA	Eligine Size	1.5L DOHC EFT VVT-i 16	-valve 4-cyl FI	eet#		
Request 1TT	Description MOUNT & BALANCE 1 TIRE. REM TIRE IN THE TRUNK OF THE CAR	OVE CORROSIO	ON FROM RIM AND SEAL	TIRE TO WHEEL	<b>Job</b> 1	CSR 2954	Status Origina
Labor 1TT	Description  MOUNT & BALANCE 1 TIRE. REMOVE CORROSION FROM RIM AND SEAL TIRE TO WHEEL. TIRE IN THE TRUNK OF THE CAR.						Amount 22.50
Technician Cause	REQUESTED TO MOUNT AND BALANCE ONE To customer had blown belt from pothole in west allis.		E	Est Parts Est Labor Labor Total Request Sub-	total		0.00 22.50 22.50
Correction	MOUNT AND BALANCE ONE TIRE						22.50
				Labor			22.50
				Parts			0.00
				Supplies			0.00
				SUB-TOTAL			22.50
				STATE TAX			1.13
				COUNTY TAX			0.20
				CITY TAX			0.45
				TOTAL IN	VOICE		24.28

## Recommended/Deferred Services

1TPMS

Code Description Amount DIAGNOSE FLASHING TIRE PRESSURE MONITORING SENSOR TO DETERMINE WHICH **DTPMS** \$82.50 SENSORS NEEDS REPLACEMENT. ADVISE FOR REPAIR.

REPLACE ONE TIRE PRESSURE MONITORING SENSOR. -- VALVE STEM SEVERELY CORRODED

AND VALVE STEM CORE IS SEIZED IN THE VALVE STEM.

TOY-SMPI Toyota Maintenance Service Inspection Report

<sup>\*\*</sup> Deferred Services prices are subject to change