CITY OF WEST ALLIS 8 SEP '25 PM12:16

SAVE

PRINT

CLAIMANT CONTACT INFORMATION



Name:	David & Jessica Mudgett	Phone:	(414) 336-4862		
Address:	2674 S 118th Street	Email:	dave.mudgett@gmail.com		
	West Allis, WI 53227				
INSTRUCTIONS Complete this form, print and sign it, and serve a hard copy upon the West Allis City Clerk. If you have questions about how to fill out this form, please contact a private attorney who can assist you. NOTICE OF CLAIM					
Date of in	icident: 07/28/2025		Time of day: 17:00		
Location: 2674 S 118th Street, West Allis, WI 53227					
Some he diagram informatio circumsta		eport, pic ist of pro and any	tures of the incident or damage, a perty damage, names and contact other information relevant to the		
Cleveland Adeveloped a result, the result through toile resulted in a minutes. Deand then mowere sorry,	2025, at approximately 17:00 hours, the water may have and Lincoln Avenue suffered a catastrophalong the 16-inch main line, which subsequently loadway buckled, cracked, and collapsed, which a of the main line caused significant flooding in the ets, shower drains, and a floor drain located in mapproximately four inches of standing water and suring the cleanup process, where I had friends at oments later, it started to flood again. I walked o but the trucks were not able to get the water out	nic failure. A burst and cr also caused roadway. T y fully finish sewage thro nd family wo utside and t fast enough	a crack measuring approximately 14 feet reated a substantial hole in the roadway. As a a nearby gas line to rupture. The water then backed up into my residence red basement. Flooding continued and it roughout the entire basement in the matter of prking, we finished the cleanup of the water alked to the workers, and they stated they an and the water came back in through our line.		
During the response, I spoke extensively with City workers and representatives from WE Energies. It was explained to me that the water main failure was caused by corrosion and the age of the pipe. Although these pipes were originally represented as having a lifespan of over 100 years, this particular pipe was installed around 1968. I was further informed that the pipe originated from China during a time when such pipes were not manufactured to last. Due to its condition, the pipe could not withstand the water pressure and ruptured, blowing a hole along its side. In later learned that this specific main line is supplied directly by the municipal water tower. The rupture caused the complete emptying of the water tower, contributing to the severity and speed of the flooding.					
Check one:					
Signed:	Daw Mudget		Date: 9-8-2025		
Γο comple or repair	CLAIM AN ete this claim, attach an itemized statem to property, include at least 2 estimates amount sought is: \$ \frac{50,000.00}{2}	ent of da	mages sought. If any damages are		


CLAIMANT CONTACT INFORMATION



Name: Address:	David & Jessica Mudgett 2674 S 118th Street West Allis, WI 53227		(414) 336-4862 dave.mudgett@gmail.com		
INSTRUCTIONS Complete this form, print and sign it, and serve a hard copy upon the West Allis City Clerk. If you have questions about how to fill out this form, please contact a private attorney who can assist you. NOTICE OF CLAIM					
	cident: <u>07/28/2025</u> 2674 S 118th Street, West Allis, WI 53227	-	Time of day: <u>17:00</u>		
Some he diagram	the circumstances of your claim here. Y lpful information may be the police report the location, a list of injuries, a list of or witnesses to the incident, and notes.	ort, pict of pro	ures of the incident or damage, a perty damage, names and contact		
Cleveland A developed a result, the r The failure through toil resulted in a minutes. D and then m were sorry, During the r me that the represented informed the condition, th I later learne	2025, at approximately 17:00 hours, the water main avenue and Lincoln Avenue suffered a catastrophic along the 16-inch main line, which subsequently but be adway buckled, cracked, and collapsed, which also of the main line caused significant flooding in the rolets, shower drains, and a floor drain located in my fapproximately four inches of standing water and sequency that the cleanup process, where I had friends and boments later, it started to flood again. I walked outs but the trucks were not able to get the water out factors are water main failure was caused by corrosion and the last having a lifespan of over 100 years, this particular the pipe originated from China during a time when the pipe could not withstand the water pressure and that this specific main line is supplied directly by applying of the water tower, contributing to the seven	failure. A rst and cre o caused adway. The ully finished wage through a side and take the cough are age of the ular pipe with the municipal treptured, the municipal causes and the municipal treptured.	crack measuring approximately 14 feet eated a substantial hole in the roadway. As a an earby gas line to rupture. The water then backed up into my residence ed basement. Flooding continued and it sughout the entire basement in the matter of rking, we finished the cleanup of the water alked to the workers, and they stated they and the water came back in through our line. It tatives from WE Energies. It was explained to the pipe. Although these pipes were originally ras installed around 1968. I was further best were not manufactured to last. Due to its blowing a hole along its side.		
Check on I a wi	e: m seekin <mark>g damages at this time (completo</mark> m submitting this notice without a claim fo Il not be processed until I submit a claim fo	e Claim . or damag or damag	Amount section below) ges. This claim is not complete and ges on a later date.		
Signed:			Date:		
	CLAIM AMC ete this claim, attach an itemized statemer to property, include at least 2 estimates fo	nt of dar			
The total a	amount sought is: \$ <u>50,000.00</u>				


SAVE

PRINT




Solve Solve






where the ban

bottom of bar





re. 3




John John



A Constitution of the Cons

Laundry Rm P







Solar

15 | 15 | N

Indu Stous



South




Goral

before of the

Showere

Bath Room

X Ino




Bahan




load crack





Pipe to our






hade made






Suerin



broken ass



cracked some / solf



they crow the



Gas line to house