

Milwaukee County Transit System

1942 NORTH 17TH STREET • MILWAUKEE, WISCONSIN • 53205-1697 • (414) 937-3247

December 14, 2020

City of West Allis City Clerk 7525 W Greenfield Avenue West Allis, WI 53214

> RE: Incident Date: October 14, 2020 / Approx. 6:30PM Location: 70th Street & Greenfield Avenue

To the of West Allis City Clerk:

On this referenced date, time & location, a Milwaukee County Transit bus (# 5624) was traveling northbound on 70th Street. The bus operator began to proceed thru the Greenfield intersection. As the bus was still within the boundaries of the intersection, the right front wheel of bus ran over a stationary manhole cover plate. As bus wheel struck manhole cover plate, the cover became dislodged from its area and struck the undercarriage of the bus resulting in damages to bus. The bus operator pulled over after the incident. Bus was taken out of service.

Repairs to this bus has been completed. Final cost of repairs amounted to \$3,491.10. This is the amount the Milwaukee County Transit System is seeking for damages.

Attached is our bus operator report of the incident, the final repair estimate, photos of the bus damages and the manhole cover plate. Also, a CD is enclosed which is video of this incident taken from the bus cameras. As a reference, the incident occurred at 18:27:25 hrs.

Sincerely,

Ken Braunschweig

Risk Management Department

Milwaukee County Transit System

1942 North 17th Street

Milwaukee, WI 53205

414.937.3240

kbraunschweig@mcts.org



Milwaukee County Transit oiaccidentincident5000

Report run on: OCT-30-20 12:35 PM

Page 1

ACCIDENT REPORT

Orbcad Incident Log Id 1637714325

Orbcad Incident AC2010140260

Report Type **Route Supervisor Accident** **Report Sequence Number** 9478077

Vehicle #1 - Bus Information

Valid Report

Operator Badge: 0207

Operator Name:

ISHAG, THOMAS

Route Supervisor: STASZAK, DAVID

Bus Number:

Route Number:

76

In Motion

Run Number:

Direction: North

Number of Witness/Courtesy Cards:

5624

0

Number of Passengers (Mcts):

76352

Route Supervisor Arrival Time:

06:45 PM

Incident Date Time: On Street: 70th Street

10/14/2020 06:29:20 pm

City: West Allis

Accident Location:

Other

At Street: Greenfield Avenue

If yes, was it legally parked?

N/A

Posted Speed Limit: 30

Status of MCTS Vehicle when contact was made:

Did you strike a parked vehicle? If struck a parked vehicle, was it occupied?

If moving, how fast? 3

At layover?

No

Damage to MCTS Vehicle? Yes

Parts Damaged:

Parts Struck:

Other

Maneuver(s) at time of Accident:

Driving Straight Ahead Pulling Out Of Bus Stop

Type of Accident (Hastus Reason Codes):

Collision with Fixed Object (B4)

Responders on Scene?

Other Vehicles:



Milwaukee County Transit

Report run on: OCT-30-20 12:35 PM

Page 2

oiaccidentincident5000

ACCIDENT REPORT

Orbcad Incident Log Id 1637714325

Orbcad Incident AC2010140260

Report Type **Route Supervisor Accident** **Report Sequence Number** 9478077

Parties/Injuries/Fatalities:

Party Name: THOMAS ISHAG Party Seq #: 9484729

Phone #: 000-000-0000

Bus Operator

Injury/Fatality: None

Other Vehicle Seq #:

Address:

City:

Zip Code: 0

Tranported by Ambulance?

To:

Nature of Injury:

Wearing Reflective Clothes?

Wearing Helmet?

Party Type:

Bicycle Light?

Bicycle Reflector?

State:

Conditions When Accident Occurred:

Brake Condition:

Road Character:

Traffic Condition:

Not Applicable

Hillcrest

Green Light

Intersection Detail:

Straight

Weather Condition:

Leaving Intersection

Street Condition:

Clear

Normal

Light Condition:

Dark (Street Lit)

Property Damage:

Property Damage Seq #:

834 **Fixed Object:** Other

Property Owners Name:

CITY OF WEST ALLIS?

Property Owners Address:

Steel Plate/Cylinder Within Crosswalk

Description of Accident:

At 6:29 pm, October 14, 2020, Operator #207/Bus #5624 notified Dispatch that he had driven over an object that became lodged under bus and began to protrude through floor of bus.

I arrived at the scene at 6:45 pm. Operator was stopped NB on 70th Street farside of Greenfield Avenue. Operator stated that on a green light, he was proceeding NB with a NB car in front of him. That vehicle swerved to left to avoid something in the road. Operator stated he could not maneuver away from it due to traffic alongside him.

Investigation revealed that there were approximately eight core borings within the crosswalk, with each hole covered with a steel cylinder and steel plate. Operator stated that one of these flat plates was bent and slightly protruding from street. In the process of driving a short distance with it lodged under bus, the cylinder/plate became more bent and started to partially protrude through floor of bus.

I was eventually able to free the cylinder/plate and placed object near Bubblr Bike stand. Dispatch notified West Allis Police Department. As of 8:00 pm, no squad had arrived.

Images downloaded.

Bus was swapped out at FDL garage.

Completed By: 1621

STASZAK, DAVID

On: 10/14/2020 08:04:21 pm

MILWAUKEE TRANSPORT SERVICES "C" CHARGE 1942 North 17th Street Milwaukee, WI 53205

ORDER NUMBER: 145062-4 VEHICLE NUMBER:

5624

MAKE: NEW FLYER

MODEL YEAR:

2015

INCIDENT DATE: 10/14/20

PREPARED BY: Ronald Hicks PREPARATION DATE: 10/27/20

LABOR

PARTS

HOUDE	DESCRIPTION		UNIT	PARTS	T
	REMOVE & REPLACE SUB FLOOR	DESCRIPTION	COST	EACH	TOTAL \$
	REMOVE & REPLACE SUB FLOOR REMOVE & REPLACE RUBBER FLOOR SMOOTH	SUB FLOOR	\$172.50		\$172.50
5.00	REMOVE & REPLACE RUBBER FLOOR SMOOTH	FLOOR-SMOOTH BLACK RUBBER	\$26.94	14	\$377.22
1.50	RESTORE CORRISION PROTECTION	FLOORING - RIBBED	\$34.47	18	\$620.38
6.00	REMOVE & INSTALL SEATS AS NEEDED	MATERIALS	\$138.00		\$138.00
0.00	REWIOVE & INSTALL SEATS AS NEEDED	IVIATERIALS	ψ130.00		Ψ130.00
					A140
29.50	TOTAL HOURS		PART	S TOTAL:	\$1,308.10

\$74.00 Hourly Rate

Labor Total:

Parts Total:

\$2,183.00 \$1,308.10

TOTAL:

\$3,491.10



