

Location 1700 BLK S 945

Time 1044 AM RECEIVED

5-18-15 MAY 18 2015

CITY OF WEST ALLIS
CITY OF WEST ALLIS
CITY OF WEST ALLIS

Driving south on 947, a city tree removal Vehiale backed into the right front of my car, 2007 Honda Civieaccident report was filed by the West Allis Police Paper

Ms Bernice Richards

• 16755 W Greenfield Ave, #1

New Berlin, WI 53151

1-2627868131



WEST ALLIS POLICE DEPARTMENT

Your Signature (other driver) ADMIN/WAPDFORMS/DRIVER EXCHANGE 04/13	Completion and exchange of this form is for the purpose of facilitating the exchange of information requirement of Section 346.67 Wis. Stats. It is intended only to assist those involved in a crash and facilitate the exchange of information between drivers to assist with any insurance claim, personal reimbursement or civil action. I hereby consent to the release of my personal information to	Insurance Carrier/Phone: City of west allis Policy#:	Vehicle (Make): (Model): (Year):	Address: Thy of wiso Allis Phone #: 302-8100	Date: 3.18.15 Time: 1044m Location: 1700 BIK 5 96 57 Towing Company:	EST ALLIS POLICE DEPARTMENT EXCHANGE AND INFORMATION SHEET To be completed by drivers ONLY Pursuant to Section 346.67 Wis. Stats.
						ANN Cherik Tree

AUTO BODY SPECIALISTS LLC 6024 WEST MITCHELL STREET

WEST ALLIS, WI 53214 PHONE: (414)545-9211 FAX: (414)545-7410

TAX ID: 391922584

Insp

Secon

Appraise

*** PRELIMINARY ESTIMATE ***

Owner

Owner: Bernice Richards Address: 16755 W Greenfield Ave City State Zip: New Berlin, WI 53151

Control Information

Loss Date/Time: 05/18/2015 11:54 AM

Deductible: None

Inspection

Inspection Date: 05/18/2015 11:54 AM

Inspection Location: Auto Body Specialists LLC
Address: 6024 W Mitchell St

City State Zip: West Allis, WI 53214
Email: autobodyspecialists@hotmail.com

Primary Impact: Right Front Side

Appraiser Name: David Jambrek

Repairer: Auto Body Specialists LLC Address: 6024 W Mitchell St

City State Zip: West Allis, WI 53214

Email: autobodyspecialists@hotmail.com

Vehicle

Repairer

2007 Honda Civic LX 4 DR Sedan 4cyl Gasoline 1.8 VTEC 5 Speed Automatic

2007	Honda	Civic	LX 4	DR	Sedan	
Claim	#:					

Claim #:	. 01110								
AM/FM Anti-Loc Center (Dual Air Intermit MP3 De Power I Power V Rem Tre	ck Bra Conse bags tent V code Door I Vindo unk-L pic S	akes ole Vipers er Locks		ACC FI KO M PO R Si	Air Conditioning Automatic Trans Cruise Control Floor Mats Keyless Entry System Mud/Splash Guards Power Mirrors Rear Bench Seat Side Airbags Theft Deterrent System Velour/Cloth Seats				
Dama	aes		NICOLOGY WAS A	Tar Salt Hope I and Tar Salt Salt Salt Salt Salt Salt Salt Salt					
Line		Guide	МС	Description	MFR.Part No.				
1 Front E	RI	53 anel And 973 55		Mldg,Front Door Side Ips Headlamps Aim Lens,Headlamp RT	Additional Labor 33101SNAA02 \$2				
Front B 4 5	ody / I L	And Win 83 83		eld Panel,Hood Panel,Hood	Repair Refinish 2.5 Surface 0.6 Two-stage setup 0.5 Two-stage				
6 7	E	85 85		Hinge,Hood Panel R' Hinge,Hood Panel R'	T 60120SNAA00ZZ \$				
8	E L	104 104		Fender,Front RT Fender,Front RT	60211SNAA90ZZ \$1 Refinish 1.9 Surface 0.5 Edge				
4.5		440		0 15 1 14 15	0.5 Two-stage				

Guard, Fender Mud RT

Blade Assembly, Wiper RT

Windshield, Tinted

Sealant Kit, W/Shield

Arm, Wiper Blade RT

Panel, Cowl Side RT

MIdg,Roof Drip RT

R & I Assembly

Sublet Repair

Sublet Repair

76630SNEA01

76610SNAA02

74220SNEA00

73158SNA013

\$28

\$2

\$2

\$4

\$3

\$7

Roof

10 RI

11 SB

12 SB

13 E

14 E

15 E

16 E

116

143

144

148

146

274

316

Quarter And	Rocker	Pane	el			
22 ET 23 L 24 E 25 E 26 TE 27 L	626 626 32 35 184 202		Pillar, Wind Dam, Vent Mldg, Pilla Panel, Boo	dshield RT dshield RT t Glass RT r Finish RT dyside Front RT dyside Otr Upr RT		\$2 \$70
28 L M14 29 L M17 30 L M60 31 I M69 32 N 32 Items		Cover Car	s Waste Removal an Up	Refinish Refinish Refinish Repair Additional Labor	9	
			MC	Message		
			07 13		L PART AS IDENTIFIED B 6 HOURS FIRST PANEL T	
Estimate To	otal & E	ntries	3			
Gross Parts Other Parts Paint & Materials Parts & Material Total Tax on Parts & Material				10.2 H	ours @ \$36.00	\$1,44 \$1 \$36

Parts & Material Total Tax on Parts & Material		@ 5.600%					
Labor	Rate	Replace I Hrs	Repair Hrs	Total Hrs			
Sheet Metal (SM) Mech/Elec (ME) Frame (FR)	\$56.00 \$85.00 \$56.00	15.9 5.5	4.9	20.8 5.5	\$1,164.8 \$467.5		
Refinish (RF)	\$56.00	10.2		10.2	\$571.2		
Labor Total				36.5	Hours		
Tax on Labor Sublet Repairs		@	5.600%		\$12 \$38		
Tax on Sublet Gross Total Less: Deductible		@	5.600%		\$2		
Net Total							

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OF PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS THE MANUFACTURER OR DISTRIBUTOR OF THE REPLACEMENT PARTS IN MANUFACTURER OF YOUR MOTOR VEHICLE.

Op Codes

= User-Entered Value

EC = Replace Economy

ET = Partial Replace Labor

TE = Partial Replace Price

L = Refinish

TT = Two-Tone

BR = Blend Refinish

CG = Chipguard

AA = Appearance Allowance

E = Replace OEM

OE = Replace PXN OE Srpls

EP = Replace PXN

PM = Replace PXN Reman/Reblt PC = Replace PXN Reconditioned

SB = Sublet Repair

I = Repair

RI = R & I Assembly

RP = Related Prior Damage



This report contains proprietary information of Audatex and mathe insured, claimant and others on a need to know basis in or Audatex's prior written consent.

Copyright (C) 2015 Audatex North America, Inc.

Audatex Estimating is a trademark of Audatex North America,