

AmFam.com

AMERICAN FAMILY MUTUAL INSURANCE COMPANY, S.I. 6000 AMERICAN PARKWAY MADISON WI 53783

December 7, 2020



000024EC100KA23003422252 CLMSCN 001 CITY CLERK - REBECCA GRILL 7525 W GREENFIELD AVE ROOM 108 TO 110 WEST ALLIES WI 53214

REGARDING YOUR INSURED CITY OF WEST ALLIS

Notice of subrogation

Please review the information below and contact me with any questions

Claim number 01-002-844517	Date of loss 11/01/2020	Your claim number unknown	Our insured BRYAN M WADE	
----------------------------	--------------------------------	---------------------------	-----------------------------	--

We are notifying you that we have made payment on the above referenced claim and our supporting documentation and proof of payment are enclosed.

The following breakdown shows the damages that were incurred by our insured:

DAMAGE	AMOUNT		
Total Damages:	\$3,180.82		
American Family Mutual Insurance Company, S.I. payment(s)	\$2,680.82		
Deductible	\$500.00		
Rental Expense	\$0.00		

Our investigation and facts of this claim support that this incident was caused by your insured's negligence. We would appreciate your offer of settlement or your theory of liability.

I am here to assist you with any questions you may have about this notice. Please use the contact information listed below to reach me. Thank you.

Jack Dold Subrogation Technician 1-800-MYAMFAM (1-800-692-6326) Ext. 51264 JDOLD@amfam.com

RECEIVED

DEC 1 0 2020


CITY OF WEST ALLIS



CLAIMANT CONTACT INFORMATION



Name: Address:		nily Insurance as su an Pkwy Madison,	brogee of Bryan Wa WI 53783	de Phone: Email:			
Complete you have assist you	questions	print and sign about how to	INSTRUC it, and serve fill out this for NOTICE O	a hard copy m, please co	upon the Vontact a pri	West Allis Civate attorne	city Clerk. If By who can
Date of inc		/1/2020 h St. West Allis, WI	53214	Tin	ne of day: _	8:30 AM	
Some help diagram o	pful inform of the loca n for with	nation may be ntion, a list of	ur claim here. the police refinjuries, a lie incident, a	eport, picture st of proper	es of the interest of the inte	ncident or a	damage, a
included	photos of	the tree in au	olders parked uestion. You d is proves the	an see the	citv has alı	ready secu	red some
I am	n seeking o n submittin	g this notice w	s time (comple ithout a claim f submit a claim	or damages.	This claim	is not com	plete and
Signed:	Jai	k Dold			Date: _1	12/7/2020	
o complete or repair to	e this clain property,	n, attach an ite include at leas	CLAIM AM mized statement at 2 estimates f	nt of damag	es sought.	If any dama	ages are
The total an	nount souç	jht is: \$ <u>3,180.</u>	.82				
SAVE		PRINT					









AMERICAN PARILY AMERICAN PARILY Open | Adj: Jack Dold (Subro Auto - Team 3 - Madison)

Financials (Total Incurred: \$2,680.82): Transactions

Payments

12/03/2020 12	11/02/2020 11/02/2020	11/02/2020 11/02/2020	Scheduled Is Send Date	- ayındınd
12/04/2020	/02/2020	/02/2020	Issue Date	
\$2,680.82	(\$2,766.22)	\$2,766.22	Amount	
_	_		Exposure	
1 Comprehensiv Loss Cost	Comprehensi Loss Cost	Comprehensi Loss Cost	Coverage	
Loss Cost		Loss Cost	Cost Type	
Submitted	Submitted	Voided	Status	
Final	Partial	Partial	Pmt Type	
1151058151	0003123521	0003123521	Check	
			Рау То	

User: Jack Dold

Page 1

12/07/2020 4:24 PM





Damage - Center

File Name: Damage - Center File Date: 11/02/2020 Label: Damage - Center

Note: Heat Map

Photo Location:

Photo Taken By: Photo Analytics



Damage - Center

File Name: Damage - Center File Date: 11/02/2020 Label: Damage - Center

Note:

Photo Location: 43.0206846 (Lat), -88.0626107 (Lon) Photo Taken By: WADE, BRYAN M





Damage - Left Angle

File Name: Damage - Left Angle

File Date: 11/02/2020

Label: Damage - Left Angle

Note: Heat Map

Photo Location:

Photo Taken By: Photo Analytics



Damage - Left Angle

File Name: Damage - Left Angle

File Date: 11/02/2020

Label: Damage - Left Angle

Note:

Photo Location: 43.0206571 (Lat), -88.0626021 (Lon)

Photo Taken By: WADE, BRYAN M





Damage - Right Angle

File Name: Damage - Right Angle

File Date: 11/02/2020

Label: Damage - Right Angle

Note: Heat Map

Photo Location:

Photo Taken By: Photo Analytics





Damage - Right Angle

File Name: Damage - Right Angle

File Date: 11/02/2020

Label: Damage - Right Angle

Note:

Photo Location: 43.0205937 (Lat), -88.0626401 (Lon)

Photo Taken By: WADE, BRYAN M



DISASSEMBLY

File Name: PHOTO21 File Date: 11/20/2020 Label: DISASSEMBLY

Note: Owner:BRYAN M,WADE|Style:2020,TOYO,Highlander XLE AWD|Insured:BRYAN M,WADE|LossDate:11/01/2020|PolicyNumber:1963603 302|ClaimRepresentative:W

Photo Location: CALIBER - WEST ALLIS

Photo Taken By: Richard Verbick





Driver Side Front

Claim Reference Id: 01002844517-1

File Name: Driver Side Front

File Date: 11/02/2020

Label: Driver Side Front

Note: Heat Map

Photo Location:

Photo Taken By: Photo Analytics



Driver Side Front

Claim Reference Id: 01002844517-1

File Name: Driver Side Front File Date: 11/02/2020

Label: Driver Side Front

Note:

Photo Location: 43.0207315 (Lat), -88.0627108 (Lon)

Photo Taken By: WADE, BRYAN M





Driver Side Rear

Claim Reference Id: 01002844517-1

File Name: Driver Side Rear File Date: 11/02/2020 Label: Driver Side Rear

Note: Heat Map

Photo Location:

Photo Taken By: Photo Analytics



Driver Side Rear

File Name: Driver Side Rear File Date: 11/02/2020 Label: Driver Side Rear

Note:

Photo Location: 43.0206415 (Lat), -88.0626296 (Lon)

Photo Taken By: WADE, BRYAN M

ķ	W	ġ.
ĭ		X.
_		

	B*1000	DIRECTION OF American Ferminal Motion	PAYESENY	198	
	Shop Ma	CALIBER COLLISION			
	Shop Ad	1454 S 113TH ST		and the same of th	
	Cely	WESTALLS	Steen We	210 83214	
	This repa	ir trelity understands and agrees that payments of repairs.	Public public has been	83214	
	Vehicle .			el ligion full and fina	
		2020 loyota Highl	nder		
	behest any a	or of my vehicle and assistaction of the regime, I do and at checks, drafts, or bills of aucharge and to a my account for the claim number should be	Newby appoint the		
	de credit on	or or my reflects and selectaction of the regions, i do mid at checks, darks, or bits of exchange and to a my account for the claim number above. I undersi- adjustment for decommend and undersi-	ndorse all such che	Ore, desire for the lay	of on my
20		my account for the claim number above. I undersi- education and the claim number above. I undersi- education and bett	pust spot i sur Losbe pust spot i	mobile for early account	the state of the s
		Common Family Mutual Insurance Common	y to make excesses	Anna Wat	
	PLEASE PRI	NT VEHICLE CONNECTED AND ST	OS MILLAN	urecay to the shop.	
		4.1			
		And the second s			
	THE RE	To the same of the			
	4				
	1				
	DATE				
	En	11-16-20			
					0 2
	Draw a.				
	D-87820 May 10/00	Copy to Vancase Course & Steam Co.			
	Distable May special	Cites to Vancase Online A Shap File			

DTP

Claim Reference ld: 01002844517-1

File Name: PHOTO16 File Date: 11/20/2020 Label: DTP

Note: Owner:BRYAN M,WADE|Style:2020,TOYO,Highlander XLE AWD|Insured:BRYAN M,WADE|LossDate:11/01/2020|PolicyNumber:1963603 302|ClaimRepresentative:W

Photo Location: CALIBER - WEST ALLIS

Photo Taken By: Richard Verbick



FRONT DAMAGE

File Name: PHOTO19 File Date: 11/20/2020 Label: FRONT DAMAGE

Note: Owner:BRYAN M,WADE|Style:2020,TOYO,Highlander XLE AWD|Insured:BRYAN M,WADE|LossDate:11/01/2020|PolicyNumber:1963603 302|ClaimRepresentative:W

Photo Location: CALIBER - WEST ALLIS

Photo Taken By: Richard Verbick



HOOD

Claim Reference Id: 01002844517-1

File Name: PHOTO25 File Date: 11/20/2020 Label: HOOD

Note: Owner:BRYAN M,WADE|Style:2020,TOYO,Highlander XLE AWD|Insured:BRYAN M,WADE|LossDate:11/01/2020|PolicyNumber:1963603 302|ClaimRepresentative:\

Photo Location: CALIBER - WEST ALLIS

Photo Taken By: Richard Verbick



HOOD REPAIR

File Name: PHOTO18 File Date: 11/20/2020 Label: HOOD REPAIR

Note: Owner:BRYAN M,WADE|Style:2020,TOYO,Highlander XLE AWD|Insured:BRYAN M,WADE|LossDate:11/01/2020|PolicyNumber:1963603 302|ClaimRepresentative:W

Photo Location: CALIBER - WEST ALLIS

Photo Taken By: Richard Verbick



INTERIOR

Claim Reference Id: 01002844517-1

File Name: PHOTO11 File Date: 11/20/2020 Label: INTERIOR

Note: Owner:BRYAN M,WADE|Style:2020,TOYO,Highlander XLE AWD|Insured:BRYAN M,WADE|LossDate:11/01/2020|PolicyNumber:1963603 302|ClaimRepresentative:W

Photo Location: CALIBER - WEST ALLIS

Photo Taken By: Richard Verbick



LT FRONT

File Name: PHOTO28 File Date: 11/20/2020 Label: LT FRONT

Note: Owner:BRYAN M,WADE|Style:2020,TOYO,Highlander XLE AWD|Insured:BRYAN M,WADE|LossDate:11/01/2020|PolicyNumber:1963603 302|ClaimRepresentative:W

Photo Location: CALIBER - WEST ALLIS

Photo Taken By: Richard Verbick



LT REAR

Claim Reference id: 01002844517-1

File Name: PHOTO6 File Date: 11/20/2020 Label: LT REAR

Note: Owner:BRYAN M,WADE|Style:2020,TOYO,Highlander XLE AWD|Insured:BRYAN M,WADE|LossDate:11/01/2020|PolicyNumber:1963603 302|ClaimRepresentative:W

Photo Location: CALIBER - WEST ALLIS

Photo Taken By: Richard Verbick



Odometer

Claim Reference Id: 01002844517-1

File Name: Odometer File Date: 11/02/2020 Label: Odometer

Note:

Photo Location: 43.0207011 (Lat), -88.0627287 (Lon)

Photo Taken By: WADE, BRYAN M



ODOMETER 2469

Claim Reference Id: 01002844517-1

File Name: PHOTO13 File Date: 11/20/2020

Label: ODOMETER 2469

Note: Owner:BRYAN M,WADE|Style:2020,TOYO,Highlander XLE AWD|Insured:BRYAN M,WADE|LossDate:11/01/2020|PolicyNumber:1963603 302|ClaimRepresentative:W

Photo Location: CALIBER - WEST ALLIS

Photo Taken By: Richard Verbick



Passenger Side Front

File Name: Passenger Side Front

File Date: 11/02/2020

Label: Passenger Side Front

Note: Heat Map

Photo Location:

Photo Taken By: Photo Analytics





Passenger Side Front

File Name: Passenger Side Front

File Date: 11/02/2020

Label: Passenger Side Front

Note:

Photo Location: 43.0206366 (Lat), -88.0626279 (Lon)

Photo Taken By: WADE, BRYAN M



Passenger Side Rear

File Name: Passenger Side Rear

File Date: 11/02/2020

Label: Passenger Side Rear

Note: Heat Map

Photo Location:

Photo Taken By: Photo Analytics





Passenger Side Rear

Claim Reference Id: 01002844517-1

File Name: Passenger Side Rear

File Date: 11/02/2020

Label: Passenger Side Rear

Note:

Photo Location: 43.0205943 (Lat), -88.0626721 (Lon)

Photo Taken By: WADE, BRYAN M



Photo1

File Name: Photo1 File Date: 11/02/2020 Label: Photo1

Note:

Photo Location: 0.0 (Lat), 0.0 (Lon) Photo Taken By: WADE, BRYAN M





Photo10

File Name: Photo10 File Date: 11/02/2020 Label: Photo10

Note:

Photo Location: 0.0 (Lat), 0.0 (Lon) Photo Taken By: WADE, BRYAN M



Photo2

File Name: Photo2 File Date: 11/02/2020 Label: Photo2

Note:

Photo Location: 0.0 (Lat), 0.0 (Lon) Photo Taken By: WADE, BRYAN M





Photo3

File Name: Photo3 File Date: 11/02/2020 Label: Photo3

Note:

Photo Location: 0.0 (Lat), 0.0 (Lon) Photo Taken By: WADE, BRYAN M



Photo4

File Name: Photo4 File Date: 11/02/2020 Label: Photo4

Note:

Photo Location: 0.0 (Lat), 0.0 (Lon) Photo Taken By: WADE, BRYAN M





Photo5

File Name: Photo5 File Date: 11/02/2020 Label: Photo5

Note:

Photo Location: 0.0 (Lat), 0.0 (Lon) Photo Taken By: WADE, BRYAN M



Photo6

Claim Reference Id: 01002844517-1 File Name: Photo6 File Date: 11/02/2020

Label: Photo6

Note:

Photo Location: 0.0 (Lat), 9.0 (Lon) Photo Taken By: WADE, BRYAN M





Photo7

File Name: Photo7 File Date: 11/02/2020 Label: Photo7

Note:

Photo Location: 0.0 (Lat), 0.0 (Lon)
Photo Taken By: WADE, BRYAN M



Photo8

File Name: Photo8 File Date: 11/02/2020 Label: Photo8

Note:

Photo Location: 0.0 (Lat), 0.0 (Lon) Photo Taken By: WADE, BRYAN M




File Name: Photo9 File Date: 11/02/2020 Label: Photo9

Note:

Photo Location: 0.0 (Lat), 0.0 (Lon) Photo Taken By: WADE, BRYAN M





PRE SCAN


Claim Reference Id: 01002844517-1

File Name: PHOTO20 File Date: 11/20/2020 Label: PRE SCAN

Note: Owner:BRYAN M,WADE|Style:2020,TOYO,Highlander XLE AWD|Insured:BRYAN M,WADE|LossDate:11/01/2020|PolicyNumber:1963603 302|ClaimRepresentative:W

Photo Location: CALIBER - WEST ALLIS

Photo Taken By: Richard Verbick



PRE SCAN


Claim Reference Id: 01002844517-1

File Name: PHOTO14 File Date: 11/20/2020 Label: PRE SCAN

Note: Owner:BRYAN M,WADE|Style:2020,TOYO,HIghlander XLE AWD|Insured:BRYAN M,WADE|LossDate:11/01/2020|PolicyNumber:1963603 302|ClaimRepresentative:W

Photo Location: CALIBER - WEST ALLIS

Photo Taken By: Richard Verbick



PRE SCAN

Claim Reference Id: 01002844517-1


File Name: PHOTO27 File Date: 11/20/2020 Label: PRE SCAN

Note: Owner:BRYAN M,WADE|Style:2020,TOYO,Highlander XLE AWD|Insured:BRYAN M,WADE|LossDate:11/01/2020|PolicyNumber:1963603

302 ClaimRepresentative:W

Photo Location: CALIBER - WEST ALLIS

Photo Taken By: Richard Verbick



PRODUCTION TAG

Claim Reference Id: 01002844517-1

File Name: PHOTO1 File Date: 11/20/2020

Label: PRODUCTION TAG

Note: Owner:BRYAN M,WADE|Style:2020,TOYO,Highlander XLE AWD|Insured:BRYAN M,WADE|LossDate:11/01/2020|PolicyNumber:1963603 302|ClaimRepresentative:W

Photo Location: CALIBER - WEST ALLIS

Photo Taken By: Richard Verbick





REAR LICENSE PLATE

Claim Reference Id: 01002844517-1


File Name: PHOTO17 File Date: 11/20/2020

Label: REAR LICENSE PLATE

Note: Owner:BRYAN M,WADE|Style:2020,TOYO,Highlander XLE AWD|Insured:BRYAN M,WADE|LossDate:11/01/2020|PolicyNumber:1963603 302|ClaimRepresentative:W

Photo Location: CALIBER - WEST ALLIS

Photo Taken By: Richard Verbick



Claim Reference Id: 01002844517-1

File Name: PHOTO24 File Date: 11/25/2020

Label: RECALIBRATION & POST SCAN

Note: Owner:BRYAN M,WADE|Style:2020,TOYO,Highlander XLE AWD|Insured:BRYAN M,WADE|LossDate:11/01/2020|PolicyNumber:1963603 302|ClaimRepresentative:W

Photo Location: CALIBER - WEST ALLIS

Photo Taken By: Richard Verbick

Seed Assessables as	nako (Asiga ngimus) kili	dot	They let 1 yes	Samuel .	
Second 4.14			Pais No Paid		
Private whether a websel			Panalon Fan		-1
Phase promote and depression			throughout Fred	1	-1
Starting protect			PanaNo Fan		
Titomara			Vanish		- 1
NAME AND PARTY OF THE PARTY.			Finiti	(2003)	
Francisco Social and		160	A-mailth.		
November 18 September 1995			Paritie Fall	and the same of th	
ibadas crasse i			Paus Perk Frank		
Wedter of the T			PantNo Fan	AEIAS	
141.51			PaintNo Fau	N-	- 7
fishers			"Penalists Par		
From recognition care	-		PaniNo Fau	() AANAS	
Lanctorreel.			Parallel Fin	AUA	
Sincering sergic sensor	(5AS)		Panchi fin		
Air conditions:			Panalka Na		
The Collision by them	(PCS)		(PantNa Fas	ATTAS	
Choted garrens			Panderin	al F	
Marice swetch			Pantista Fa	No.	
Road eigo assist			Panichio Fili	E EAST	
pre					
System	Cedes	Densquine		Station	
SRS awhag.	Ulizav	Lynt community with the managed A	ex-processing	History	
Cambiosticic interes	U023AS7	Last communication with ma- module A missing manager		Confirmed	
Main holy	43023.4	Energine and a state of the sta	gir processing	Himmy	
Telimones.	BISCHA	GNSS antonia cayor open		Confirmed	
Telepanies.	RISCBIA.	Telephone main limenta circi-	in appear	Continued	
Navigationsystem	BOTE	XXII. tenes autenus disconnec	New York	Birgey	
Front calls assure	U00001	Lost construction with era- uneling message	ise count module	Confernal	
Technician note					
Post-scan Report			2020-11	-25 15:20:42	

Claim Reference Id: 01002844517-1


File Name: PHOTO9 File Date: 11/25/2020

Label: RECALIBRATION & POST SCAN

Note: Owner:BRYAN M,WADE|Style:2020,TOYO,Highlander XLE AWD|Insured:BRYAN M,WADE|LossDate:11/01/2020|PolicyNumber:1963603 302|ClaimRepresentative:W

Photo Location: CALIBER - WEST ALLIS

Photo Taken By: Richard Verbick



Claim Reference Id: 01002844517-1


File Name: PHOTO26 File Date: 11/25/2020

Label: RECALIBRATION & POST SCAN

Note: Owner:BRYAN M, WADE|Style:2020, TOYO, Highlander XLE AWD|Insured:BRYAN M, WADE|LossDate:11/01/2020|PolicyNumber:1963603 302|ClaimRepresentative:W

Photo Location: CALIBER - WEST ALLIS

Photo Taken By: Richard Verbick



Claim Reference id: 01002844517-1

File Name: PHOTO2 File Date: 11/25/2020

Label: RECALIBRATION & POST SCAN

Note: Owner:BRYAN M,WADE|Style:2020,TOYO,Highlander XLE AWD|Insured:BRYAN M,WADE|LossDate:11/01/2020|PolicyNumber:1963603

302|ClaimRepresentative:W

Photo Location: CALIBER - WEST ALLIS

Photo Taken By: Richard Verbick



ROOF

Claim Reference Id: 01002844517-1

File Name: PHOTO5 File Date: 11/20/2020 Label: ROOF

Note: Owner:BRYAN M,WADE|Style:2020,TOYO,Highlander
XLE AWD|Insured:BRYAN
M,WADE|LossDate:11/01/2020|PolicyNumber:1963603
302|ClaimRepresentative:W

Photo Location: CALIBER - WEST ALLIS

Photo Taken By: Richard Verblck



ROOF

File Name: PHOTO10 File Date: 11/20/2020 Label: ROOF

Note: Owner:BRYAN M,WADE|Style:2020,TOYO,Highlander XLE AWD|Insured:BRYAN M,WADE|LossDate:11/01/2020|PolicyNumber:1963603 302|ClaimRepresentative:W

Photo Location: CALIBER - WEST ALLIS

Photo Taken By: Richard Verbick



ROOF

Claim Reference Id: 01002844517-1

File Name: PHOTO7 File Date: 11/20/2020 Label: ROOF

Note: Owner:BRYAN M,WADE|Style:2020,TOYO,Highlander XLE AWD|Insured:BRYAN M,WADE|LossDate:11/01/2020|PolicyNumber:1963603 302|ClaimRepresentative:W

Photo Location: CALIBER - WEST ALLIS

Photo Taken By: Richard Verbick



ROOF

File Name: PHOTO4 File Date: 11/20/2020 Label: ROOF

Note: Owner:BRYAN M,WADE|Style:2020,TOYO,Highlander XLE AWD|Insured:BRYAN M,WADE|LossDate:11/01/2020|PolicyNumber:1963603 302|ClaimRepresentative:W

Photo Location: CALIBER - WEST ALLIS

Photo Taken By: Richard Verbick



ROOF REPAIR

File Name: PHOTO3 File Date: 11/20/2020 Label: ROOF REPAIR

Note: Owner:BRYAN M,WADE|Style:2020,TOYO,Highlander XLE AWD|Insured:BRYAN M,WADE|LossDate:11/01/2020|PolicyNumber:1963603 302|ClaimRepresentative:W

Photo Location: CALIBER - WEST ALLIS

Photo Taken By: Richard Verbick



RR DOOR AND HANDLE

File Name: PHOTO8 File Date: 11/20/2020

Label: RR DOOR AND HANDLE

Note: Owner:BRYAN M,WADE|Style:2020,TOYO,Highlander XLE AWD|Insured:BRYAN M,WADE|LossDate:11/01/2020|PolicyNumber:1963603 302|ClaimRepresentative:W

Photo Location: CALIBER - WEST ALLIS

Photo Taken By: Richard Verbick



RT FRONT

Claim Reference Id: 01002844517-1

File Name: PHOTO23 File Date: 11/20/2020 Label: RT FRONT

Note: Owner:BRYAN M,WADE|Style:2020,TOYO,Highlander XLE AWD|Insured:BRYAN M,WADE|LossDate:11/01/2020|PolicyNumber 302|ClaimRepresentative:W

Photo Location: CALIBER - WEST ALLIS

Photo Taken By: Richard Verbick



RT LUG RAIL

File Name: PHOTO22 File Date: 11/20/2020 Label: RT LUG RAIL

Note: Owner:BRYAN M,WADE|Style:2020,TOYO,Highlander
XLE AWD|Insured:BRYAN
M,WADE|LossDate:11/01/2020|PolicyNumber:
302|ClaimRepresentative:W

Photo Location: CALIBER - WEST ALLIS

Photo Taken By: Richard Verbick



RT REAR

File Name: PHOTO15 File Date: 11/20/2020 Label: RT REAR

Note: Owner:BRYAN M,WADE|Style:2020,TOYO,Highlander
XLE AWD|Insured:BRYAN
M,WADE|LossDate:11/01/2020|PolicyNumber
302|ClaimRepresentative:W

Photo Location: CALIBER - WEST ALLIS

Photo Taken By: Richard Verbick



VIN

Claim Reference ld: 01002844517-1

File Name: VIN

File Date: 11/02/2020

Label: VIN

Note:

Photo Location: 43.0206235 (Lat), -88.0625754 (Lon)

Photo Taken By: WADE, BRYAN M



WINDSHIELD

Claim Reference Id: 01002844517-1

File Name: PHOTO12 File Date: 11/20/2020 Label: WINDSHIELD

Note: Owner:BRYAN M,WADE|Style:2020,TOYO,Highlander XLE AWD|Insured:BRYAN M,WADE|LossDate:11/01/2020|PolicyNumber:1963603 302|ClaimRepresentative:W

Photo Location: CALIBER - WEST ALLIS

Photo Taken By: Richard Verbick

CALIBER - WEST ALLIS

Workfile iD: Federal ID: Federal EPA:

APV2AZOD 33-0730794 WI R000108381

RESTORING THE RHYTHM OF YOUR LIFE 1434 SOUTH 113TH STREET, WEST ALLIS, WI

53214

Phone: (414) 607-8810 FAX: (414) 607-8830

Supplement of Record 1 with Summary

RO Number: 3339041625

Written By: Richard Verbick, 11/25/2020 5:34:33 PM Adjuster: Witherspoon, Kyle, (720) 417-6306 Business

Insured:

WADE, BRYAN M

Policy #:

Claim #:

01002844517-1

Type of Loss:

Comprehensive

Date of Loss:

11/1/2020 8:30 AM

Days to Repair:

Point of Impact: 12 Front

Owner:

Inspection Location:

Insurance Company:

WADE, BRYAN M

WADE, BRYAN M

AMERICAN FAMILY MUTUAL INSURANCE

COMPANY S.I.

2.000

1017 S 120th St

1017 S 120th St

West Allis, WI 53214-2118

Virtual

AF4

VEHICLE

2020 TOYO Highlander XLE AWD 4D UTV 6-3.5L Gasoline Port/Direct Injection

VIN:

Interior Color:

Mileage In:

Vehicle Out: 11/25/2020

License State:

Exterior Color: Production Date: Mileage Out: Condition:

Job # :

TRANSMISSION Automatic Transmission Tilt Wheel 4 Wheel Drive **POWER** Power Steering Power Brakes

Power Windows Power Locks

Power Mirrors

Heated Mirrors Power Driver Seat Power Passenger Seat

DECOR **Dual Mirrors** Privacy Glass Console/Storage Overhead Console

CONVENIENCE

Intermittent Wipers

Cruise Control Rear Defogger Keyless Entry Alarm

Message Center Steering Wheel Touch Controls

Rear Window Wiper Telescopic Wheel Climate Control Dual Air Condition Backup Camera Remote Starter Intelligent Cruise

Home Link RADIO AM Radio

Stereo

Search/Seek Auxiliary Audio Connection Satellite Radio

SAFETY Drivers Side Air Bag Passenger Air Bag Anti-Lock Brakes (4) 4 Wheel Disc Brakes Traction Control

Stability Control Front Side Impact Air Bags Head/Curtain Air Bags

Communications System

Hands Free Device Xenon or L.E.D. Headlamps Blind Spot Detection

Lane Departure Warning

Luggage/Roof Rack **Bectric Glass Sunroof**

SEATS Bucket Seats

Redining/Lounge Seats

Leather Seats Heated Seats 3rd Row Seat WHEELS

Aluminum/Alloy Wheels

Clear Coat Paint OTHER Fog Lamps Rear Spoiler

PAINT

Signal Integrated Mirrors California Emissions

TRUCK



2020 TOYO Highlander XLE AWD 4D UTV 6-3.5L Gasoline Port/Direct Injection

Air Conditioning

RM Radio

ROOF

Power Trunk/Liftgate



Supplement of Record 1 with Summary

RO Number: 3339041625

2020 TOYO Highlander XLE AWD 4D UTV 6-3.5L Gasoline Port/Direct Injection

Line			Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	HOOD								
2	(*)		Rpr	Hood (ALU)				5.0	3.0
3		501		Add for Clear Coat					1.2
4	#		Refn	Basecoat Reduction					-0.4
5			R&I	Insulator				0.2	
6	#		Refn	Basecoat Reduction					-0.4
7	ELECTR	CAL							
8		S01	R&I	Antenna w/o JBL audio				0.3	
9	WINDS	HIELD							
10			Repl	Windshield Toyota, w/o rain sensor	561010E610	1	780.02	Incl.	
11	* *			A/M Urethane Kit		1	15.00		
12	#	S01	Subl	Remove windshield		1	99.00 T		
13	#	S01	Subl	Reinstall windshield		- 1	99.00 T		
14	ROOF								
15	4	901	Rpr	Roof panel				9.0	4.3
16				Overlap Major Non-Adj. Panel					-0.2
17		S01		Add for Clear Coat					8.0
18	#		Refn	Basecoat Reduction					-0.4
19	*	S01	R&I	RT Roof rack				<u>0.4</u>	
20	*	S01	R&I	LT Roof rack				0.4	
21		901	Repl	RT Side rail clip	9046710167	10	14.90		
				Note: 5 EACH SIDE					
22	*	S01	R&I	R&I headliner				1.0	
				Note: PARTIAL R&I FOR ANTENNA					
23	REAR D		_					0.5	
24	•	S01	Rpr	RT Outer panel (HSS)				0.5	0.0
25	VEHICL	E DIA	ENOST	Note: BUFF					
26	*	S01	Repl	Pre-repair scan		1	40.00 m	<u>0.2</u> M	
27	*	S01	Repl	Post-repair scan		1	Incl. m	Incl. M	
28	#	S01	Subl	ADAS Calibration - Forward Coll.		1	250.00 T	11101. WI	
20	#	301	Subi	Warning Note: INCLUDES POST SCAN			230.00		
29	MISCEL	LANFO	NIS OF	PERATIONS					
30	#		, 45 01	Cover Car		1	5.00		
31	#			Corrosion Protection		1	5.00		
32	#		Subl	Hazardous Waste		1	3.00		
33	#	901		American Family - COVID 19		1	Т	1.0	
				Geaning	OLID TOWAL C		4.040.00	40.5	
					SUBTOTALS		1,310.92	18.0	7.9

RO Number: 3339041625

2020 TOYO Highlander XLE AWD 4D UTV 6-3.5L Gasoline Port/Direct Injection

ESTIMATE TOTALS

Category	Basis		Rate	Cost \$
Parts				862.92
Body Labor	17.8 hrs	@	\$ 60.00 /hr	1,068.00
Paint Labor	7.9 hrs	@	\$ 60.00 /hr	474.00
Mechanical Labor	0.2 hrs	@	\$ 99.00 /hr	19.80
Paint Supplies	7.9 hrs	@	\$ 39.00 /hr	308.10
Miscellaneous				448.00
Subtotal				3,180.82
Grand Total				3,180.82
Deductible				500.00
CUSTOMER PAY				500.00
INSURANCE PAY				2,680.82



RO Number: 3339041625

2020 TOYO Highlander XLE AWD 4D UTV 6-3.5L Gasoline Port/Direct Injection

SUPPLEMENT SUMMARY

Line			Oper	Description	Part Number	Q	ty	Extended Price \$	Labor	Paint
Change	ed Items									
16	*		Ror	Roof panel					-5.0	-4.3
15	*	S01	Rpr	Roof panel					9.0	4.3
17				Overlap Major Adj. Panel						0.4
16		501		Overlap Major Non-Adj. Panel						-0.2
22	*		Ppr	RT Outer panel (HSS)					<u>-1.0</u>	-2.2
24	*	S01	Fipr	RT Outer panel (HSS)					<u>0.5</u>	0.0
				NOTE: BUFF						
Delete	d Items									
1	FRONT	вимр	ER & G	RILLE						
2			R&I	R&I burnper cover					-2:1	
3	FRONT	LAMP!	S							
4			R&I	LT Headlamp assy w/o LED-strip DRL					-0.5	
9	FENDE	R								
10	*		Rpr	LT Fender (ALU)					<u>-1.5</u>	-2.2
11				Overlap Major Adj, Panel						0.4
20			R&I	R&I sunroof assy					-1.5	
21	*		R&I	R&I headliner					<u>-2.5</u>	
				NOTE: partial drop						
24				Overlap Major Non-Adj. Panel						0.2
25	#		Refn	Basecoat Reduction						0.4
26	ħ		R&I	RT Lower molding					<u>-0.3</u>	
27			R&I	RT Outer molding					-0,3	
28	*		R&I	RT Belt molding					<u>-0.3</u>	
29	*		Rpr	RT Handle, outside white pearl					<u>-0.5</u>	-0.4
30				Overlap Minor Panel						0.2
31				Clear Coat						-2.5
32			R&I	RT Handle, outside white pearl					-0.3	
33			R&1	RT R&I trim panel					-0.5	
Added	Items									
3		S01		Add for Clear Coat						1.2
7	ELECTI	RICAL								
8		S01	R&I	Antenna w/o JBL audio					0.3	
12	#	S01	Subl	Remove windshield			1	99.00 T		
13	#	901	Subl	Reinstall windshield			1	99.00 T		
17		901		Add for Clear Coat						0.8
19	*	S01	R&I	RT Roof rack					0.4	
20	*	S01	R&I	LT Roof rack					0.4	
21		S01	Repl	RT Side rail clip	9046710	0167	10	14.90		
				NOTE: 5 EACH SIDE						

Supplement of Record 1 with Summary

RO Number: 3339041625

2020 TOYO Highlander XLE AWD 4D UTV 6-3.5L Gasoline Port/Direct Injection

S01 S01 S01	Repl Subl	Post-repair scan ADAS Calibration - Forward Coll. Warning NOTE: INCLUDES POST SCAN American Family - COVID 19 Cleaning	1 1	<u>Ind.</u> 250.00	m	<u>Incl.</u>		
		ADAS Calibration - Forward Coll. Warning	1		m			
		ADAS Calibration - Forward Coll.	1		m			
			1		m			
S01	Repl	Post-repair scan	1	Incl.				
							IAI	
901	Repi	Pre-repair scan	1	40.00	m	0.2	B./I	
ICLE DIAG	SNOST	ICS						
		NOTE: PARTIAL R&I FOR ANTENNA						
S01	R&I					<u>1.0</u>		
		ICLE DIAGNOST	NOTE: PARTIAL R&I FOR ANTENNA ICLE DIAGNOSTICS	NOTE: PARTIAL R&I FOR ANTENNA ICLE DIAGNOSTICS	NOTE: PARTIAL R&I FOR ANTENNA ICLE DIAGNOSTICS	NOTE: PARTI AL R&I FOR ANTENNA ICLE DIAGNOSTICS	NOTE: PARTIAL R&I FOR ANTENNA ICLE DIAGNOSTICS	NOTE: PARTIAL R&I FOR ANTENNA ICLE DIAGNOSTICS

TOTALS SUMMARY

INSURANCE PAY:

Category	Basis		Rate	Cost \$
Parts	****			54,90
Body Labor	-3.7 hrs	@	\$ 60.00 /hr	-222.00
Paint Labor	-3.9 hrs	@	\$ 60.00 /hr	-234.00
Mechanical Labor	0.2 hrs	@	\$ 99.00 /hr	19.80
Paint Supplies	-3.9 hrs	@	\$ 39.00 /hr	-152.10
Miscellaneous				448.00
Subtotal				-85.40
Total Supplement Amount				-85.40
NET COST OF SUPPLEMENT				-85.40

CUMULATIVE EFFECTS OF SUPPLEMENT(S)

Estimate	3,266.22	KYLE WITHERSPOON
Supplement S01	-85.40	Richard Verbick
Job Total:	\$ 3,180.82	
CUSTOMER PAY:	\$ 500.00	

2,680.82



Supplement of Record 1 with Summary

RO Number: 3339041625

2020 TOYO Highlander XLE AWD 4D UTV 6-3.5L Gasoline Port/Direct Injection

Caliber Collision is the industry leader in quality collision repair. Since day one, our highest purpose has been to get people just like you back on the road as quickly as possible and fully restored to the rhythm of your life. You can be sure we do everything possible to ensure your complete satisfaction including:

Personalized, high quality service from the largest collision repair company in the U.S.

Consistently ranked among the highest customer satisfaction scores in the industry.

Approved by every major insurance company in the U.S.

Expedited car rental and towing services to get you back on the road again in no time.

Repair work backed by a written, lifetime warranty honored at every location.

24/7/365 customer service to answer questions and put your mind at ease.

This is a preliminary estimate based on visible damage. There may be additional repairs needed once the vehicle is taken apart by our I-CAR Gold Class technicians to identify any additional damage.

If an insurance company has written an estimate for you, please provide us with a copy. Properly endorsed insurance company checks are welcome as payment for the repair of your vehicle. Caliber Collision gladly accepts all major credit cards, debit cards, cashier's and traveler's checks. See your Caliber Collision center for details on acceptance of personal checks.

Before leaving your vehicle with us, please remove all important personal and valuable items from your vehicle. Caliber Collision is not responsible for belongings left in your vehicle.

Please let us know how we can be of further assistance, and when we can schedule an appointment for your vehicle to be repaired.

Caliber Collision - Restoring The Rhythm Of Your Life?

THE INSURANCE COMPANY PROVIDING THIS ESTIMATE DOES NOT AUTHORIZE REPAIRS. AUTHORIZATION MUST COME FROM THE VEHICLE OWNER. ANY SUPPLEMENT(S) MUST HAVE PRIOR APPROVAL FROM A REPRESENTATIVE OF THE INSURANCE COMPANY PROVIDING THIS ESTIMATE.

MOTOR VEHICLE REPAIR PRACTICES ARE REGULATED BY CHAPTER ATCP 132, WIS. ADM. CODE, ADMINISTERED BY THE BUREAU OF CONSUMER PROTECTION, WISCONSIN DEPT. OF AGRICULTURE, TRADE AND CONSUMER PROTECTION, P.O. BOX 8911, MADISON, WISCONSIN 53708-8911.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE REPLACEMENT PARTS RATHER THAN BY THE MANUFACTURER OF YOUR MOTOR VEHICLE.

RO Number: 3339041625

2020 TOYO Highlander XLE AWD 4D UTV 6-3.5L Gasoline Port/Direct Injection

Estimate based on MOTOR CRASH ESTIMATING GUI DE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide ARM8471, CCC Data Date 11/13/2020, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2021 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The COC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D= Diagnostic labor category. E= Bectrical labor category. F= Frame labor category. G= Glass labor category.

M= Mechanical labor category. S= Structural labor category. (numbers) 1 through 4= User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.= Adjacent. Algn.= Align. ALU= Aluminum. A/M= Aftermarket part. Blnd= Blend. BOR= Boron steel. CAPA= Certified Automotive Parts Association. D&R= Disconnect and Reconnect. HSS= High Strength Steel. HYD= Hydroformed Steel. Incl.= Included. LKQ= Like Kind and Quality. LT= Left. MAG= Magnesium. Non-Adj.= Non Adjacent. NSF= NSF International Certified Part. O/H= Overhaul. Qty= Quantity. Refn= Refinish. Repl= Replace. R&I= Remove and Install. R&R= Remove and Replace. Rpr= Repair. RT= Right. SAS= Sandwiched Steel. Sect= Section. Subl= Sublet. UHS= Ultra High Strength Steel. N= Note(s) associated with the estimate line.

COC ONE Estimating - A product of COC Information Services Inc.

The following is a list of abbreviations that may be used in COC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR= Bureau of Automotive Repair. EPA= Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR= Paintless Dent Repair. VIN= Vehicle Identification Number.