CLAIMANT CONTACT INFORMATION

Name: Luiz Cruz
Address: 1108 s 74th st
West Allis, WI, 53214

Phone: 414-544-6086
Email: luizcruz654@gmail.com

INSTRUCTIONS

Complete this form, print and sign it, and serve a hard copy upon the West Allis City Clerk. If you have questions about how to fill out this form, please contact a private attorney who can assist you.

NOTICE OF CLAIM

Date of incident: 04/27/2026 Time of day: 01:30
Location: 1108 s 74th st, West Allis, 53214

Describe the circumstances of your claim here. You may attach additional sheets or exhibits. Some helpful information may be the police report, pictures of the incident or damage, a diagram of the location, a list of injuries, a list of property damage, names and contact information for witnesses to the incident, and any other information relevant to the circumstances.

I am submitting this claim regarding damage to my vehicle caused by a tree branch that fell during windy conditions on April 27th, 2026, at approxiamtely 01:30 pm.

The branch fell and struck my vehicle, causing damage to the windshield, hood, and side of vehicle. After the incident, city workers removed the tree completly, and they stateted the tree was rotten. Based on the condition of the tree after removal, i believe the tree may not have been properly maintained or inspected prior to the incident. The hazardous condition of the tree ultimately resulted in damage to my vehivle.

I am requesting compensation for the damages caused by this incident, inlcuding repair costs and any related expenese. City workers have pictures of damages so does the police officer who responded. These picture show the car covered in leaves, once I washed my car damages were more clealry visable.

Please contact me regarding the next steps in processing this claim.

Check one:

- [x] ..... I am seeking damages at this time (complete Claim Amount section below)
- [ ] ..... I am submitting this notice without a claim for damages. This claim is not complete and will not be processed until I submit a claim for damages on a later date.

Signed: _____ Date: 05/14/2026

CLAIM AMOUNT

To complete this claim, attach an itemized statement of damages sought. If any damages are for repair to property, include at least 2 estimates for repairs.

The total amount sought is: $ _____

SAVE PRINT

RECEIVED
MAY 15 2026
CITY OF WEST ALLIS

SAUKVILLE PORT WASHINGTON
SCHMIT BROS.
Collision Shop
Collision Repair
Auto Body Repair

SCHMIT BROS AUTO INC.

Schmit Happens
925 E GREEN BAY AVE., SAUKVILLE, WI 53080
Phone: (262) 284-1945
FAX: (262) 268-2127

Workfile ID: 538e481b
Federal ID: 39-1031133

Preliminary Estimate

Customer: Cruze, Luiz

Job Number:

Written By: Schmit Bros

Insured: Cruze, Luiz
Type of Loss:
Point of Impact: 02 Right Front Pillar (Right Side)

Policy #:
Date of Loss:

Claim #:
Days to Repair: 0

Owner:
Cruze, Luiz
(414) 544-6086 Cell

Inspection Location:
Other

Insurance Company:

VEHICLE

2018 HOND Accord Sedan Sport Automatic 4D SED 4-2.0L Turbocharged Gasoline Gasoline Direct Injection

VIN: 1HGCV2F31JA028494
License:
State: WI

Interior Color:
Exterior Color:
Production Date:

Mileage In:
Mileage Out:
Condition:

Vehicle Out:
Job #:

TRANSMISSION
Automatic Transmission
POWER
Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Heated Mirrors
Power Driver Seat
DECOR
Dual Mirrors
Tinted Glass
Console/Storage
Overhead Console
CONVENIENCE
Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Alarm
Message Center
Steering Wheel Touch Controls
Telescopic Wheel
Climate Control
Backup Camera
Intelligent Cruise
RADIO
AM Radio
FM Radio
Stereo
Search/Seek
Auxiliary Audio Connection
Satellite Radio
SAFETY
Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Front Side Impact Air Bags
Head/Curtain Air Bags
Hands Free Device
Blind Spot Detection
Lane Departure Warning
ROOF
Electric Glass Sunroof
SEATS
Cloth Seats
Bucket Seats
Reclining/Lounge Seats
Heated Seats
WHEELS
Aluminum/Alloy Wheels
PAINT
Clear Coat Paint
OTHER
Fog Lamps
Traction Control
Stability Control
Rear Spoiler
Xenon or L.E.D. Headlamps

Preliminary Estimate

Customer: Cruze, Luiz

Job Number:

2018 HOND Accord Sedan Sport Automatic 4D SED 4-2.0L Turbocharged Gasoline Gasoline Direct Injection

Line	Oper	Description	Part Number	Qty	Extended Price $	Labor	Paint
1	**FRONT BUMPER & GRILLE**						
2	R&I	R&I bumper cover				1.7	
3	**FRONT LAMPS**						
4	R&I	RT R&I headlamp assy				0.4	
5	**HOOD**						
6	* Rpr	Hood (ALU)				3.0	3.0
7		Add for Clear Coat					1.2
8	**FENDER**						
9	Repl	RT Fender	60210TVAA00ZZ	1	399.98	1.9	1.8
10		Overlap Major Adj. Panel					-0.4
11		Add for Clear Coat					0.3
12		Add for Edging					0.5
13		Add for Clear Coat					0.1
14	R&I	RT Fender liner w/o hybrid				Incl.	
15	**WINDSHIELD**						
16	Repl	Windshield Honda Sport, 2.0 liter	73111TVAA11	1	1,165.66	3.2	
17	R&I	RT Wiper arm				Incl.	
18	R&I	LT Wiper arm				Incl.	
19	R&I	RT Side molding				Incl.	
20	R&I	LT Side molding				Incl.	
21	R&I	Mirror inside w/o auto dimming				Incl.	
22	**COWL**						
23	* R&I	Cowl grille				Incl.	
24	**PILLARS, ROCKER & FLOOR**						
25	R&I	RT Rocker molding w/o chrome strip sn marino red				1.2	
26	R&I	RT Wndshld plr trim w/o Hybrid black				Incl.	
27	R&I	LT Wndshld plr trim w/o Hybrid black				Incl.	
28	**FRONT DOOR**						
29	* Rpr	RT Outer panel (HSS)				3.0	2.2
30		Overlap Major Adj. Panel					-0.4
31		Add for Clear Coat					0.4
32	R&I	RT R&I mirror				0.3	
33	R&I	RT Handle, outside w/o smart entry champagne				0.4	
34	R&I	RT R&I trim panel				0.5	
35	R&I	RT Belt molding				0.3	
36	Repl	RT Mirror cover cyrstal black	76201TVAA01ZJ	1	64.35	0.1	0.5
37		Overlap Minor Panel					-0.2
38		Add for Clear Coat					0.1
39	**REAR DOOR**						
40	* Blnd	RT Door shell (HSS)					1.0

Preliminary Estimate

Customer: Cruze, Luiz

Job Number:

2018 HOND Accord Sedan Sport Automatic 4D SED 4-2.0L Turbocharged Gasoline Gasoline Direct Injection

41		R&I	RT Belt molding			0.3		
42		R&I	RT Applique front			0.2		
43		R&I	RT Handle, outside w/o chrome kona coffee			0.4		
44	**VEHICLE DIAGNOSTICS**							
45	*		Pre-repair scan	1	m	0.5 M		
46	*		Post-repair scan	1	m		0.5	
47	**MISCELLANEOUS OPERATIONS**							
48	#		Corrosion Protection	1	5.00		0.3	
49	*	Repl	Cover car/bag	1	10.00	0.2		
50	#	Subl	Flex Additive	1	5.00			
51	#	Subl	Hazardous waste removal	1	3.00 T			
			SUBTOTALS		**1,652.99**	**17.6**	**10.9**	

ESTIMATE TOTALS

Category	Basis		Rate	Cost $
Parts				1,649.99
Body Labor	17.1 hrs	@	$ 72.00 /hr	1,231.20
Paint Labor	10.9 hrs	@	$ 72.00 /hr	784.80
Mechanical Labor	0.5 hrs	@	$ 165.00 /hr	82.50
Paint Supplies	10.9 hrs	@	$ 50.00 /hr	545.00
Miscellaneous				3.00
Subtotal				4,296.49
Sales Tax	$ 4,296.49	@	5.5000 %	236.31
Grand Total				**4,532.80**
Deductible				0.00
CUSTOMER PAY				**0.00**
INSURANCE PAY				**4,532.80**

MOTOR VEHICLE REPAIR PRACTICES ARE REGULATED BY CHAPTER ATCP 132, WIS. ADM. CODE, ADMINISTERED BY THE BUREAU OF CONSUMER PROTECTION, WISCONSIN DEPT. OF AGRICULTURE, TRADE AND CONSUMER PROTECTION, P.O. BOX 8911, MADISON, WISCONSIN 53708-8911.

CRASH CHAMPIONS
COLLISION REPAIR TEAM

CRASH CHAMPIONS #0595 MILWAUKEE

We Believe The Difference is Trust
4930 S 6th Street, Milwaukee, WI 53221
Phone: (414) 481-7576

Workfile ID:	276a0608
Federal ID:	47-1529314
State ID:	N/A
Federal EPA:	N/A
State EPA:	WIR000040220

Preliminary Estimate

Customer: CRUZ, LUIS

Written By: James Quirindongo De La Paz

Insured: CRUZ, LUIS
Type of Loss:
Point of Impact: 01 Right Front

Policy #:
Date of Loss:

Claim #:
Days to Repair: 0

Owner:
CRUZ, LUIS
(414) 544-6086 Cell

Inspection Location:
CRASH CHAMPIONS #0595 MILWAUKEE
4930 S 6th Street
Milwaukee, WI 53221
Repair Facility
(414) 481-7576 Business

Insurance Company:
CUSTOMER PAY

VEHICLE

2018 HOND Accord Sedan Sport Automatic 4D SED 4-2.0L Turbocharged Gasoline Gasoline Direct Injection Crystal Black Pearl

VIN:	1HGCV2F31JA028494	Interior Color:	Black	Mileage In:		Vehicle Out:	
License:		Exterior Color:	Crystal Black Pearl	Mileage Out:			
State:		Production Date:		Condition:		Job #:	

TRANSMISSION
Automatic Transmission
POWER
Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Heated Mirrors
Power Driver Seat
DECOR
Dual Mirrors
Tinted Glass
Console/Storage
Overhead Console
CONVENIENCE
Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Alarm
Message Center
Steering Wheel Touch Controls
Telescopic Wheel
Climate Control
Backup Camera
Intelligent Cruise
RADIO
AM Radio
FM Radio
Stereo
Search/Seek
Auxiliary Audio Connection
Satellite Radio
SAFETY
Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Front Side Impact Air Bags
Head/Curtain Air Bags
Hands Free Device
Blind Spot Detection
Lane Departure Warning
ROOF
Electric Glass Sunroof
SEATS
Cloth Seats
Bucket Seats
Reclining/Lounge Seats
Heated Seats
WHEELS
Aluminum/Alloy Wheels
PAINT
Clear Coat Paint
OTHER
Fog Lamps
Traction Control
Stability Control
Rear Spoiler
Xenon or L.E.D. Headlamps

2018 HOND Accord Sedan Sport Automatic 4D SED 4-2.0L Turbocharged Gasoline Gasoline Direct Injection Crystal Black Pearl

Line		Oper	Description	Part Number	Qty	Extended Price $	Labor	Pai
1	**FRONT BUMPER & GRILLE**							
2		R&I	R&I bumper cover				1.7	
3		R&I	RT Side support				Incl.	
4	**FRONT LAMPS**							
5		R&I	RT R&I headlamp assy				0.4	
6	**HOOD**							
7	*	Rpr	Hood (ALU)				5.0	3.0
8			Add for Clear Coat					1.2
9	**FENDER**							
10		Repl	RT Fender	60210TVAA00ZZ	1	399.98	1.9	1.8
11			Overlap Major Adj. Panel					-0.4
12			Add for Clear Coat					0.3
13			Add for Edging					0.5
14		R&I	RT Rear seal w/o hybrid LX, Sport				Incl.	
15		R&I	RT Fender ledge cvr				Incl.	
16		R&I	RT Fender liner w/o hybrid				Incl.	
17	**WINDSHIELD**							
18		Repl	Windshield Honda Sport, 2.0 liter	73111TVAA11	1	1,165.66	3.2	
19	**PILLARS, ROCKER & FLOOR**							
20		R&I	RT Rocker molding w/o chrome strip crystal black				1.2	
21	**FRONT DOOR**							
22	*	Rpr	RT Outer panel (HSS)				2.0	2.2
23			Overlap Major Adj. Panel					-0.4
24			Add for Clear Coat					0.4
25		R&I	RT R&I mirror				0.3	
26		R&I	RT Handle, outside w/smart entry, w/chrome crystal black				0.4	
27		R&I	RT R&I trim panel				0.5	
28		R&I	RT Belt molding				0.3	
29	**VEHICLE DIAGNOSTICS**							
30	*	Subl	Pre-repair scan		1	55.00 X m		
31	*	Subl	Post-repair scan		1	55.00 X m		
32	*	Subl	Calibrate front radar sensor		1	250.00 X m		
33	*	Subl	Calibrate lane keep assist camera		1	250.00 X m		
34	*	Subl	Calibrate steering angle sensor		1	95.00 X m		
35	**MISCELLANEOUS OPERATIONS**							
36	#		Cover Car		1	12.50 X	0.2	
37	#	Repl	Corrosion Protection		1	22.00 T	0.5	
38	#		Flex Additive		1	12.00		
39	#	Subl	Hazardous Waste Removal		1	10.00		
40	#		SUPPLIED PHOTOS MAY NOT INCLUDE ALL RELATED DAMAGES		1			

Preliminary Estimate

Customer: CRUZ, LUIS

2018 HOND Accord Sedan Sport Automatic 4D SED 4-2.0L Turbocharged Gasoline Gasoline Direct Injection Crystal Black Pearl

41	#	HIDDEN DAMAGES MAY BE FOUND DURING DISASSEMBLY	1		
42	#	DAMAGES NOT SHOWN IN PHOTOS COULD INCREASE OVERALL COSTS	1		
		SUBTOTALS	**2,327.14**	**17.6**	**8.6**

ESTIMATE TOTALS

Category	Basis		Rate	Cost $
Parts				1,587.64
Body Labor	17.6 hrs	@	$ 86.00 /hr	1,513.60
Paint Labor	8.6 hrs	@	$ 86.00 /hr	739.60
Paint Supplies	8.6 hrs	@	$ 62.00 /hr	533.20
Miscellaneous				739.50
Subtotal				5,113.54
Sales Tax	$ 5,113.54	@	7.9000 %	403.97
Grand Total				**5,517.51**

Our shop provides easy and accessible payment plans powered by Sunbit.
Scan this QR code to see payment options available to you.

This estimate has been repaired based on the use of crash parts supplied by a source other than the manfacturer of the motor vehicle. Warranties applicable to these replacement parts are provided by the manufacturer or distributor of these parts rather than the manufacturer of your vehicle.

NO WARRANTY ON RUST.

PART PRICES SUBJECT TO CHANGE.

MOTOR VEHICLE REPAIR PRACTICES ARE REGULATED BY CHAPTER ATCP 132, WIS. ADM. CODE, ADMINISTERED BY THE BUREAU OF CONSUMER PROTECTION, WISCONSIN DEPT. OF AGRICULTURE, TRADE AND CONSUMER PROTECTION, P.O. BOX 8911, MADISON, WISCONSIN 53708-8911.

Preliminary Estimate

Customer: CRUZ, LUIS

2018 HOND Accord Sedan Sport Automatic 4D SED 4-2.0L Turbocharged Gasoline Gasoline Direct Injection Crystal Black Pearl

PARTS SUPPLIER LIST

Line	Supplier	Description	Price
18	Schlossmann Honda City 3450 S 108th St Milwaukee WI 53227	#73111TVAA11 Windshield Honda Sport, 2.0 liter Quote: 26691556515 Expires: 05/20/26	$ 1,165.66