

RECEIVED

City of West Allis
6300 w McGeoch Ave
West Allis, WI 53219

OCT 19 2016

10/17/16

CITY OF WEST ALLIS
CITY CLERK

To whom it may concern:

As someone that works with your company, hit my car that was legally parked on 10/17/2016. Broke my back window and my back motor wiper don't work and also the body of the car has some dents.

Did went to get an estimate of how much will everything be. And I already went to get my back window put on. Everything is attached to this letter.

Hope the city of west allis pays for my damages done to my car.

Thanks,

M. Lozano
Mirna Lozano

1537 S. 64th St

West Allis

414 233 4428

cc: Amy

HEISER CHEVROLET
COLLISION REPAIR AND REFINISHING
10200 W. ARTHUR AVENUE
WEST ALLIS, WI 53227
OFFICE: 414-327-2300 FAX: 414-546-7877

*** PRELIMINARY ESTIMATE ***

10/18/2016 12:50 PM

Owner

Owner: MIRNA LOZANO
Address:

Work/Day: (414)233-6428

Inspection

Inspection Date: 10/18/2016 12:50 PM

Inspection Type:

Company: Heiser Chevy collision
Contact: CHERI L. ANDREWS
Address: 10200 W ARTHUR AVE
City State Zip: West Allis, WI 53227
Email: candrews@heiser.com

Appraiser License # :

Work/Day: (414)328-2453
FAX:

Repairer

Repairer: HEISER CHEVY BODY SHOP
Address: 10200 WEST ARTHUR AVENUE
TAX ID# 39-1655466
City State Zip: WEST ALLIS, WI 53227
Email: candrews@heiser.com

Contact: CHERI ANDREWS
Work/Day: (414)328-2453
Home/Evening: (414)327-2300
FAX: (414)546-7877

Target Complete Date/Time:

Days To Repair: 3

Vehicle

OEM Part Price Quote ID: ****

2005 Saturn Vue Red Line 4 DR Wagon
6cyl Gasoline 3.5
5 Speed Automatic

Lic Expire:
Prod Date:
Veh Insp# :
Condition:
Ext. Refinish: Two-Stage

VIN: 5GZCZ63455S811842
Mileage: 101,000
Mileage Type: Actual
Code: SN704A
Int. Refinish: Two-Stage

Options

18 Inch Alloy Wheels
Air Conditioning
Automatic Dimming Mirror
Dual Airbags
Intermittent Wipers
Lighted Entry System
Power Mirrors
Privacy Glass
Rem Trunk-L/Gate Release

4-Wheel Drive
Alarm System
Center Console
Fog Lights
Keyless Entry System
Power Brakes
Power Steering
Rear Window Defroster
Roof/Luggage Rack

AM/FM CD Player
Anti-Lock Brakes
Cruise Control
Ground Effects Package
Leather Steering Wheel
Power Door Locks
Power Windows
Rear Window Wiper/Washer
Split Folding Rear Seat

Sport Suspension	Tachometer	Tilt Steering Wheel
Tinted Glass	Velour/Cloth Seats	

Damages

Line	Op	Guide	MC	Description	MFR.Part No.	Price	ADJ%	B%	Hours	R
Tailgate										
1	E	479		Shell,Tailgate	10374333	\$1,139.47			4.2	SM
2	L	479	13	Shell,Tailgate	Refinish				5.0	RF
					2.7 Surface					
					1.0 Edge					
					0.6 Two-stage setup					
					0.7 Two-stage					
3	E	64		N/Plate,Tailgate	22697600	\$20.02			0.2	SM
4	E	305		N/Plate,Tailgate	22697601	\$56.97			0.2	SM
5	E	306		N/Plate,Tailgate	22697602	\$36.27			0.2	SM
6	SB	484		Glass,Tailgate Heated	Sublet Repair	\$140.00*				SM
7	E	507		Motor,Tailgate Wiper	19257184	\$283.32			INC	SM
7	Items									

MC	Message
13	INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

Estimate Total & Entries

Gross Parts		\$1,536.05	
Paint & Materials	5.0 Hours @ \$36.00	\$180.00	
Parts & Material Total			\$1,716.05
Tax on Parts & Material	@ 5.600%		\$96.10

Labor	Rate	Replace Hrs	Repair Hrs	Total Hrs		
Sheet Metal (SM)	\$56.00	4.8		4.8	\$268.80	
Mech/Elec (ME)	\$105.00					
Frame (FR)	\$56.00					
Refinish (RF)	\$56.00	5.0		5.0	\$280.00	
Labor Total				9.8 Hours		\$548.80
Tax on Labor		@ 5.600%			\$30.73	
Sublet Repairs					\$140.00	
Tax on Sublet		@ 5.600%			\$7.84	
Gross Total						\$2,539.52
Net Total						\$2,539.52

Alternate Parts Y/00/00/00/00 CUM 00/00/00/00/00 Zip Code: 53227 Audatex Host
 OEM Part Prices DT 10/18/2016 12:50 PM EstimateID 217701630127161344 QuoteID ****
 Rate Name Default

1.3 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE REPLACEMENT PARTS RATHER THAN BY THE MANUFACTURER OF YOUR MOTOR VEHICLE.

Op Codes

* = User-Entered Value	^ = Labor Matches System Assigned Rates	E = Replace OEM
NG = Replace NAGS	EC = Replace Economy	OE = Replace PXN OE Srpls
UE = Replace OE Surplus	ET = Partial Replace Labor	EP = Replace PXN
EU = Replace Recycled	TE = Partial Replace Price	PM = Replace PXN Reman/Reblt
UM = Replace Reman/Rebuilt	L = Refinish	PC = Replace PXN Reconditioned
UC = Replace Reconditioned	TT = Two-Tone	SB = Sublet Repair
N = Additional Labor	BR = Blend Refinish	I = Repair
IT = Partial Repair	CG = Chipguard	RI = R & I Assembly
P = Check	AA = Appearance Allowance	RP = Related Prior Damage



This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

© 2016 Audatex North America, Inc.

AUDATEX is a trademark owned by Audatex North America, Inc. All rights reserved.



LAKE AUTO GLASS, INC
4440 SOUTH 108TH STREET
GREENFIELD, WI 53228
(414) 425-2800 / Fax (414) 375-2021
Fed. ID# 392042339

Inv. #	Quote #027014	Date	10/18/2016
Cust. #	2336428	Billcode	2
P.O. #		Sold By	MATT
Fed. Tax #		Inst'l By	

MIRNA LOZANO

(414) 233-6428

Year	2005	Make	SATURN	Policy #	
Model	VUE	Body Style	4 DOOR UTILITY	Authorized By	
Lic. #		V.I.N.		Claim #	
Home Phone	(414) 233-6428	Bus. Phone	0 -	Loss Date	10/17/2016

Qty.	Part	Description	Block Size	List	Price	Total
1	DB10151YPNN	Back Window (ht)(1hl)(w/wpr)(slr contr)	35x55	249.50	122.26	122.26
1	LABOR	Labor 2.70 hours		75.00	75.00	
1	HAH000004	2.0 Urethane, Dam, Primer		20.00	20.00	20.00

Tech Note:

Pre-existing conditions

- 1-Cracked and bent wiper assembly as result of accident
- 2-Body bent as result of accident
- 3-Scratches and scuffmarks on the trunk area as result of accident
- 4-Glass was installed was extra glue compensate for rear dent and approved by customer
- 5-Glass was installed with wiper assembly and approved by customer

PAID CASH

SPECIAL INSTRUCTIONS

INSTALLATION WARRANTY. We warranty the installation of all fixed glass (non-moveable) such as windshield, back glass, etc against leakage and defects for life as long as the present owner continues to own or lease this vehicle. This means that a new windshield or back glass will be properly installed and sealed by experienced technician. It will not leak unless it is broken or the vehicle rusts around it. This warranty covers only the repair or replacement mentioned above and does not cover any, incidental, indirect or consequential damages. This warranty is limited to repair or replacement by authorized, Lake Auto Glass, Inc locations. There are no warranties that extend beyond those expressed above. All moveable glass such as door glass has limited 30 days warranty. Warranty express above is not transferable.

Labor Subtotal	75.00
Tax	142.26
Total	12.17
Balance	229.43

RECEIVED BY

The glass listed has been replaced / repaired with like kind and quality to my entire satisfaction, and I authorize my Insurance Company to pay LAKE AUTO GLASS, INC directly for the glass and installation charges, or repairs.

