

August 26, 2015

West Allis Common Council  
7525 W. Greenfield Ave.  
West Allis, WI 53214

Dear Council,

On 7/12/15 I was working at Fire Station 3 at 10830 W. Lapham St. in West Allis. During the night a storm had come through causing the basketball hoop to fall onto my vehicle. The roof, rear passenger window and rear passenger door all sustained damage.

I've attached two estimates for repair. If you have any questions, please contact me via my cell phone at 414-702-3300. Thank you

Kevin Brode

1240 RIVINGTON DR  
MUSKOGEE, WI 53149

RECEIVED  
AUG 27 2015  
CITY OF WEST ALLIS  
CITY CLERK



# Marshall Service, Inc.

Est # 65414

Page 1 of 2

22300 W. Bluemound Rd.  
Waukesha, WI 53186  
(262) 549-4300 Fax: (262) 549-2080

## Estimate of Repairs

Kevin Brode

Make: 2005 Acura

Ins. Co:

Model: TL

Style: 4D SED

Adjuster:

(414) 702-3300

License:

Claim #:

Color:

Date of Loss:

Date: 7/13/2015 2:05:03 PM

VIN No: 19UUA662X5A074457

Mileage At Estimate: 0

Line	Line Items	Parts	Labor	Refinish
C 1	ROOF			
C 2	R&I RT Drip molding		0.6 B	
C 3	PILLARS, ROCKER & FLOOR			
C 4	Repair RT Uniside assy		2.5 B	
C 5	Repair RT Uniside assy			2 R
C 6	Add for Clear Coat			0.8 R
C 7	REAR DOOR			
C 8	Repl RT Outer panel (HSS)	275.60 E	6.3 B	
C 9	Repl RT Outer panel (HSS)			2 R
C 10	Add for Edging			0.5 R
C 11	Add for Inside			0.5 R
C 12	Overlap Major Adj. Panel			-0.4 R
C 13	Add for Clear Coat			0.1 R
C 14	Add for Clear Coat			0.1 R
C 15	Add for Clear Coat			0.3 R
C 16	R&I RT Belt w/strip			
C 17	Repl RT Moveable glass NAGS	190.30 G	0.5 B	
C 18	R&I RT Handle, outside black pearl			
C 19	R&I RT R&I trim panel			
C 20	R&I RT Door w/strip		0.5 B	
C 21	BACK GLASS			
C 22	Repair Mask Back glass NAGS		0.5 B	
C 23	FRONT DOOR			
C 24	R&I RT Door w/strip		0.5 B	
C 25	Cover Car	10.00 H		
C 26	Corrosion Protection			0.4 R
C 27	Haz. Waste Disposal	5.00 W		
C 28	Preliminary estimate			
C 29	Paint Materials	226.80		



# Marshall Service, Inc.

Est # 65414

22300 W. Bluemound Rd.  
Waukesha, WI 53186  
(262) 549-4300 Fax: (262) 549-2080

Page 2 of 2

## Estimate of Repairs

Kevin Brode

Make: 2005 Acura

Ins. Co:

Model: TL

Style: 4D SED

Adjuster:

(414) 702-3300

License:

Claim #:

Color:

Date of Loss:

Date: 7/13/2015 2:05:03 PM

VIN No: 19UUA662X5A074457

Mileage At Estimate: 0

		<b>Estimate</b>
Glass Parts (G)	0 @ 0	190.30
OEM Parts (E)	0 @ 0	275.60
	<b>Parts</b>	<b>465.90</b>
Body Labor (B)	11.4 @ 56	638.40
Refinish Labor (R)	6.3 @ 56	352.80
	<b>Labor</b>	<b>991.20</b>
Hardware & Repair Materials (H)	0 @ 0	10.00
Hazardous Waste (W)	0 @ 0	5.00
Paint Materials (P)	0 @ 0	226.80
	<b>Materials</b>	<b>241.80</b>
	<b>SUBTOTAL</b>	<b>1,698.90</b>
	<b>SALE TAX</b> Rate=5.1%	86.64
	<b>TOTAL</b>	<b>1,785.54</b>
	Customer Subtotal	1,785.54
	Deductible	0.00
	Customer Total	1,785.54
	Insurance Total	0.00

### THIS IS NOT A FINAL BILL

I hereby authorize the repair work to be done along with necessary parts & materials. You and your employees may operate vehicle for purposes of testing, inspection or delivery. An express mechanics lien is acknowledged on vehicle to secure the amount of repairs thereto. Marshall Services Inc. will not be held responsible for loss or damage to articles left in vehicle in case of fire, theft or accident. I acknowledge that I am responsible for all repair charges incurred. This specifically includes any insurance company deductible payments and Betterments (depreciation). Marshall Services Inc. will work directly with the insurance company (if ins. pay), and any charges not covered by insurance will be my sole responsibility. I acknowledge that I am responsible for all costs associated with the collection of unpaid amounts including but not limited to reasonable attorney fees. I authorize Marshall Services Inc. to act as power of attorney to sign insurance checks to pay for damages to above vehicle. I Authorize you to dispose of old parts unless otherwise instructed in writing on this authorization form. I authorize Marshall Auto Body to obtain sublet services as necessary for the proper repair of said vehicle.

Signed \_\_\_\_\_ DATE \_\_\_\_\_

FLEURY'S BODY REPAIR INC.  
"WE TAKE THE DENTS OUT OF ACCIDENTS"  
1006 MAIN STREET  
MUKWONAGO, WI 53149  
PHONE: (262) 363-8555 (262) 363-8922 FAX: (262) 363-7038

\*\*\* PRELIMINARY ESTIMATE \*\*\*

07/13/2015 10:03 AM

**Owner**

**Owner:** KEVIN BRODE  
**Address:** 1240 RIVERTON DR.  
**City State Zip:** Mukwonago, WI 53149

**Work/Day:** (414)702-3300  
**FAX:**

**Control Information**

**Deductible:** None

**Inspection**

**Inspection Date:** 07/13/2015

**Inspection Type:**

**Appraiser Name:** JOHN BOTUCKI

**Appraiser License # :**

**Repairer**

**Repairer:** FLEURY'S BODY REPAIR,INC  
**Address:** 1006 MAIN STREET  
**City State Zip:** Mukwonago, WI 53149

**Contact:**  
**Work/Day:** (262)363-8555  
**FAX:** (262)363-7038  
**Work/Day:**

**Vehicle**

2005 Acura TL NAV 4 DR Sedan  
6cyl Gasoline 3.2  
5 Speed Automatic

**Lic.Plates:**  
**Lic Expire:**  
**Prod Date:**  
**Veh Insp# :**  
**Condition:**  
**Ext. Color:** BLACK  
**Ext. Refinish:** Two-Stage

**Lic State:** WI  
**VIN:** 19UUA662X5A074457  
**Mileage:** 84,737  
**Mileage Type:** Actual  
**Code:** 81633A  
**Int. Color:**  
**Int. Refinish:** Two-Stage

**Options**

Air Conditioning  
Anti-Lock Brakes  
Center Console  
Dual Airbags  
Floor Mats  
Head Airbags  
In-Dash CD Changer &Tape  
Leather Seats  
Navigation System

Alarm System  
Automatic Dimming Mirror  
Cruise Control  
Dual Power Seats  
Fog Lights  
Heated Front Seats  
Intermittent Wipers  
Leather Steering Wheel  
Overhead Console

Aluminum/Alloy Wheels  
Bose Sound System  
Digital Signal Processor  
Dual Zone Auto A/C  
Garage Door Opener  
Heated Power Mirrors  
Keyless Entry System  
Lighted Entry System  
Power Brakes

Power Door Locks	Power Moonroof	Power Steering
Power Windows	Rear Window Defroster	Rem Trunk-L/Gate Release
Side Airbags	SiriusXM Satellite Radio	Stability Cntrl Suspensn
Strg Wheel Radio Control	Tachometer	Telescopic Steering Whl
Tilt Steering Wheel	Tinted Glass	Traction Control System
Trip Computer	Wireless Phone Connect	

**Damages**

Line	Op	Guide	MC	Description	MFR.Part No.	Price	ADJ% B%	Hours	R
<b>Front Doors</b>									
1	RI	200		W/Strip,Frt Door Body RT	R & I Assembly			0.4	SM
<b>Rear Doors</b>									
2	I	288		Door Shell,Rear RT	Repair			4.0*	SM
3	L	288		Door Shell,Rear RT	Refinish			2.5	RF
					2.1 Surface				
					0.4 Two-stage				
4	RI	181		W/Strip,RR Door Body RT	R & I Assembly			0.4	SM
5	RI	334		Mldg,Rear Door Belt RT	R & I Assembly			0.2	SM
6	E	296		Glass,Rear Door T RT	73400SEPA00	\$255.47		1.2	SM
7	RI	314		Channel,Rear Glass Run RT	R & I Assembly			INC	SM
8	RI	306		Handle,RR Door Outer RT	R & I Assembly			0.5	SM
<b>Quarter And Rocker Panel</b>									
9	I	136		Panel,Bodyside Otr Upr RT	Repair			2.0*	SM
10	L	136	13	Panel,Bodyside Otr Upr RT	Refinish			2.3	RF
					1.4 Surface				
					0.6 Two-stage setup				
					0.3 Two-stage				
11	BR	390		Panel,Quarter RT	Blend Refinish			1.3	RF
					0.9 Blend				
					0.4 Two-stage				
<b>Manual Entries</b>									
12	I	M14		Corrosion Protection	Repair			0.5*	RF
13	I	M17		Cover Car Exterior	Sublet Repair	\$5.00*		0.5*	RF
14	I	M60		Hazardous Waste Removal	Sublet Repair	\$5.00*			SM
14	Items								

MC	Message
13	INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

**Estimate Total & Entries**

Gross Parts		\$255.47	
Paint & Materials	6.1 Hours @ \$38.00	\$269.80	
Parts & Material Total			\$525.27
Tax on Parts & Material	@ 5.100%		\$26.79

Labor	Rate	Replace Hrs	Repair Hrs	Total Hrs	
Sheet Metal (SM)	\$58.00	2.7	6.0	8.7	\$504.60
Mech/Elec (ME)	\$90.00				
Frame (FR)	\$68.00				
Refinish (RF)	\$58.00	6.1	1.0	7.1	\$411.80

<b>Labor Total</b>		15.8 Hours		\$916.40
<b>Tax on Labor</b>	@ 5.100%		\$46.74	
<b>Sublet Repairs</b>			\$10.00	
<b>Tax on Sublet</b>	@ 5.100%		\$0.51	
<b>Gross Total</b>				<b>\$1,525.71</b>
<b>Less: Deductible</b>				None-
<b>Net Total</b>				<b>\$1,525.71</b>

Alternate Parts No


Audatex Estimating 7.0.533 ES 08/26/2015 04:07 PM REL 7.0.533 DT 06/01/2015 DB 08/15/2015  
Copyright (C) 2015 Audatex North America, Inc.

1.7 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE REPLACEMENT PARTS RATHER THAN BY THE MANUFACTURER OF YOUR MOTOR VEHICLE.

**Op Codes**

- |                            |                                |                            |
|----------------------------|--------------------------------|----------------------------|
| * = User-Entered Value     | E = Replace OEM                | NG = Replace NAGS          |
| EC = Replace Economy       | OE = Replace PXN OE Srpls      | UE = Replace OE Surplus    |
| ET = Partial Replace Labor | EP = Replace PXN               | EU = Replace Recycled      |
| TE = Partial Replace Price | PM = Replace PXN Reman/Rebtl   | UM = Replace Reman/Rebuilt |
| L = Refinish               | PC = Replace PXN Reconditioned | UC = Replace Reconditioned |
| TT = Two-Tone              | SB = Sublet Repair             | N = Additional Labor       |
| BR = Blend Refinish        | I = Repair                     | IT = Partial Repair        |
| CG = Chipguard             | RI = R & I Assembly            | P = Check                  |
| AA = Appearance Allowance  | RP = Related Prior Damage      |                            |



This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

**Copyright (C) 2015 Audatex North America, Inc.**  
Audatex Estimating is a trademark of Audatex North America, Inc.











