

My name is Angel Soriano, I work at Ferguson Enterprises at 2030 S 116th St. At West Allis Wi. 53227
I got a call from the West Allis Police department to inform me about my truck. I have a 2002 F150 4x4
Four doors, and I park on the street. They have had call me just to let me know that my truck got
Spray paint all over the driver side and they told me that I need it to make a report so my truck can
Get fix. I also notices my co-workers car got paint on it. I am a driver and could not see my truck till
I got back from my deliveries and then I talked to my co-worker and told me he spoke to a lady from the
City. she informed him about what happen and who we need to talk step by step to make a claim in
Order to get my truck taken care of. She had talk to the West Allis Police Department to get a report.
The officer asked for mv information and mv co-workers. I went and got 2 estimate from two different
Places and on both places told me that they do not fix the step bars witch is where it got much more
Paint . so they both told me about the same place on 108th St. So I went and got an estimate from
Them also. The place call.....ultimate Truck & car and it is locate at 3515 S 108th St Milwaukee Wi. 53228
And so I attach all estimate together for you to see it.
I hope you got all the information you need about me, And I will be truly appreciate if you do
Everything in your power to help me fix this matter. And everything it is necessary to fix any damages:
That is done to mv truck.

Thank you very much in advance

Angel Soriano
6401 W Dodge Pl Unit 103
Milwaukee Wi. 53220

Any questions call me at (414) 232-8166

P.S. I am sorry for taking too long to do this. I have two jobs and hardly have time.

RECEIVED

SEP 15 2014

CITY OF WEST ALLIS
CITY CLERK

All This will take 3days to be fix; Both Places told me
I need to rent a car and add it to all this but I can't
think is necessary I can manage by taking the city bus



3515 S 108th St
 Milwaukee, WI 53228
 414-329-7400
 www.ultimate-truck.com

Quote	QTE0014220
Date	9/12/2014
Cust ID	CASH
Page	1
Terms	CASH

Bill To:

ANGEL SORIANO

Ship To:

ANGEL SORIANO

(000) 000-0000 Ext. 0000

Quote is good for 30 days

Ship VIA	Salesman	Make	Model	Year	VIN
PICKUP	BJ	FORD	F-150 X-CAB	2002	

QTY	Item Number	Description	Unit Price	Extended
-----	-------------	-------------	------------	----------

1	RAP-0103-0116	STEPBARS STAINLESS 99-03 F150 XC 4 DR	359.00	\$359.00
1	L-NERF	Installation labor	70.00	\$70.00

entered by bill jensen

Subtotal	\$429.00
Misc	\$0.00
Freight	\$0.00
Tax	\$24.03
Total	\$453.03

2002 FORD F-150 XLT 4DOOR EXT CAB
 CD LOG NO 8508-1

			0.2 TWO STAGE	
I 0207	DOOR SHELL, FRONT	LT REPAIR		4.0*1
L 0207	DOOR SHELL, FRONT	LT REFINISH		2.6 4
			2.2 SURFACE	
			0.4 TWO STAGE	
L 0460	FLARE, WHEEL OPENING	LT REFINISH		1.2 4
			1.0 SURFACE	
			0.2 TWO STAGE	
E M07	PINSTripES-TAPE	NEW PART	45.00*	0.3*1
L M14	CORROSION PROTECTION	REFINISH		0.3*4
L M17	COVER CAR EXTERIOR	REFINISH	10.00*	4

10 ITEMS

MC MESSAGE(S)
 13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

FINAL CALCULATIONS & ENTRIES

GROSS PARTS				45.00
OTHER PARTS				10.00
PAINT MATERIAL				320.40
PARTS & MATERIAL TOTAL				375.40
TAX ON PARTS & MATERIAL @			5.600%	21.02
LABOR	RATE	REPLACE HRS	REPAIR HRS	
1-SHEET METAL	56.00	0.5	5.0	308.00
2-MECH/ELEC	85.00			
3-FRAME	80.00			
4-REFINISH	56.00	8.9		498.40
5-PAINT MATERIAL	36.00			
LABOR TOTAL				806.40
TAX ON LABOR		@	5.600%	45.16
SUBLET REPAIRS				
TOWING				
STORAGE				
GROSS TOTAL				1,247.98
NET TOTAL				1,247.98

SHOPLINK U6077 ES CD LOG 8508-1 DATE 09/10/14 04:05:35PM R6.37 CD 08/14
 PXN: Y/00/00/00/00/00 CUM 00/00/00/00/00 GEOCODE 53227
 HOST LOG

(C) 1998 - 2008 AUDATEX NORTH AMERICA, INC.

1.9 HRS WERE ADDED TO THIS EST. BASED ON AUDATEX TWO-STAGE REFINISH FORMULA.

 THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE

Date: 9/ 9/2014 04:55 PM
 Estimate ID: 21873
 Estimate Version: 0
 Preliminary
 Profile ID: Mitchell

Brownell Quality Collision Center

10414 W. Greenfield Ave., West Allis, WI 53214-3930
 (414) 774-0610
 Fax: (414) 774-0760
 Email: brownellqcc@aol.com

Damage Assessed By: RICK KONKEL
 Classification: None

Condition Code: Fair
 Contact Date: 9/ 9/2014
 Payer: Customer
 Claim Number: 21873

Deductible: 0.00

Owner: ANGEL SORIANO
 Address: 6401 W DODGE PL #103, MILWAUKEE 53220
 Telephone: Home Phone: (414) 232-8166

Mitchell Service: 912623

Description: 2002 Ford Pickup F150 XLT
 Body Style: 2D PkUpXCb 7' Bed 139" WB
 VIN: 1FTRX18W32NA74312
 OEM/ALT: 0
 Color: GREEN
 Options: PASSENGER AIRBAG, DRIVER AIRBAG, POWER LOCK, POWER WINDOW, POWER STEERING
 MANUAL AIR CONDITION, CRUISE CONTROL, TILT STEERING COLUMN, ANTI-LOCK BRAKE SYS.
 LEATHER STEERING WHEEL, 4WD OR AWD, FRONT AIR DAM, TINTED GLASS
 ANTI-THEFT SYSTEM, AM/FM STEREO CD, FRONT SPLIT BENCH SEAT, KEYLESS ENTRY SYSTEM
 POWER ANTENNA, POWER DISC BRAKES, STEERING WHEEL MOUNTED CONTROLS, STEP BUMPER

Drive Train: 4.6L Inj 8 Cyl 4WD
 Search Code: None

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	200165	BDY	REPAIR	L Fender Panel	Existing		1.0* #
2	AUTO	REF	REFINISH	L Fender Outside			C 2.2
3	203619	REF	REFINISH	L Fender Wheel Opening Mldg			C 1.0
4	200185	BDY	REMOVE/INSTALL	L Fender Wheel Opening Mldg			0.3
5	200187	BDY	REMOVE/INSTALL	L Stone Shield			0.2
6	203621	BDY	REMOVE/INSTALL	L Fender Adhesive Nameplate	Existing		0.4*
7	206354	BDY	REPAIR	L Frt Door Shell	Existing		4.0* #
8	AUTO	REF	REFINISH	L Frt Door Outside			C 2.4
9	205038	BDY	REMOVE/INSTALL	L Frt Otr Belt Moulding			0.3
10	201956	BDY	REMOVE/INSTALL	L Frt Door Mirror			0.7 #
11	201275	BDY	REMOVE/INSTALL	L Frt Otr Door Handle			0.2 #
12	203456	REF	REFINISH	L Quarter Wheel Opening Mldg			C 1.0
13	201650	BDY	REMOVE/INSTALL	L Bed Wheel Opening Moulding			0.5*
14	AUTO	REF	ADD'L OPR	Clear Coat			1.8*
15	900500	BDY	ADD'L LABOR OP	MASK JAMS/ CAR COVER	New	5.00 *	0.3*
16	AUTO		ADD'L COST	Paint/Materials		285.60 *	
17	AUTO		ADD'L COST	Hazardous Waste Disposal		5.00 *	

ESTIMATE RECALL NUMBER: 09/09/2014 16:54:36 21873
 Mitchell Data Version: OEM: JUL_14_V

Software Version: 7.1.168

Copyright (C) 1994 - 2014 Mitchell International
 All Rights Reserved

Page 1 of 2

* - Judgment Item
 # - Labor Note Applies
 C - Included in Clear Coat Calc

Estimate Totals

I. Labor Subtotals	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	II. Part Replacement Summary	Amount
Body	7.9	54.00	0.00	0.00	426.60 T	Taxable Parts	5.00
Refinish	8.4	54.00	0.00	0.00	453.60 T	Sales Tax @ 5.600%	0.28
					Taxable Labor 880.20	Total Replacement Parts Amount	5.28
			@ 5.600 %		Labor Tax 49.29		
Labor Summary	16.3				929.49		
III. Additional Costs						IV. Adjustments	
				Amount		Amount	
Taxable Costs				290.60	Insurance Deductible	0.00	
Sales Tax			@ 5.600%	16.27	Customer Responsibility	0.00	
Total Additional Costs				306.87			
Paint Material Method: Rates Init Rate = 34.00 , Init Max Hours = 99.9, Addl Rate = 0.00							
						I. Total Labor:	929.49
						II. Total Replacement Parts:	5.28
						III. Total Additional Costs:	306.87
						Gross Total:	1,241.64
						IV. Total Adjustments:	0.00
						Net Total:	1,241.64

This is a preliminary estimate.
Additional changes to the estimate may be required for the actual repair.