



CLAIMANT CONTACT INFORMATION

Name: Sarah Paulik
Address: 723 S. 94th St.
West Allis, WI 53214

Phone: 414-712-1002
Email: echoofongels@gmail.com

INSTRUCTIONS

Complete this form, print and sign it, and serve a hard copy upon the West Allis City Clerk. If you have questions about how to fill out this form, please contact a private attorney who can assist you.

NOTICE OF CLAIM

Date of incident: 2/12/2021 Time of day: 11:28 AM
Location: West Allis

Describe the circumstances of your claim here. You may attach additional sheets or exhibits. Some helpful information may be the police report, pictures of the incident or damage, a diagram of the location, a list of injuries, a list of property damage, names and contact information for witnesses to the incident, and any other information relevant to the circumstances.

I was at community Memorial Hospital post C-section (C-section 2/10/2021). My boyfriend came home to snowblow/shovel the sidewalk + walkpath to the house. Bryan Marble (boyfriend) witnessed several officers inspecting the vehicle. He asked if they needed help. The officers stated the car was hit by a city plow + they were reviewing the damaged. The individual of the city plow who hit the vehicle had called the police to report the incident. The individual driving the city plow had informed Bryan Marble it was his fault (accident) for he slid on ice + hit the bumper. I was informed + called a claim.

Check one:

- I am seeking damages at this time (complete Claim Amount section below)
- I am submitting this notice without a claim for damages. This claim is not complete and will not be processed until I submit a claim for damages on a later date.

Signed: [Signature]

Date: 03/10/2021

CLAIM AMOUNT

To complete this claim, attach an itemized statement of damages sought. If any damages are for repair to property, include at least 2 estimates for repairs.

The total amount sought is: \$ _____

SAVE

PRINT

Date: 3/2/2021 04:26 PM
 Estimate ID: 29366
 Estimate Version: 0
 Preliminary
 Profile ID: Mitchell

Brownell Quality Collision Center

10414 W Greenfield Ave, West Allis, WI 53214
 (414) 774-0610
 Fax: (414) 774-0760
 Email: BrownellQCC@aol.com
 Tax ID: 39-1758646

Damage Assessed By: RYAN KONKEL
 Classification: Field

Condition Code: Excellent
 Deductible: 0.00
 Claim Number: 29366

Type of Loss: Collision

Owner: SARAH PAULIK
 Telephone: Home Phone: (414) 712-1002

Mitchell Service: 911632

Description: 2015 Toyota Corolla S
 Body Style: 4D Sed
 VIN: [REDACTED] 9
 OEM/ALT: O
 Color: WHITE
 Options:

Drive Train: 1.8L Inj 4 Cyl A FWD

Search Code: B913542

PASSENGER AIRBAG, POWER DRIVER SEAT, POWER LOCK, POWER WINDOW, POWER STEERING
 REAR WINDOW DEFOGGER, AIR CONDITION, CRUISE CONTROL, TILT STEERING COLUMN
 AM/FM STEREO, DRIVER AIRBAG, HEATED EXTERIOR MIRROR
 FRONT SIDE AIRBAG WITH HEAD PROTECTION, ANTI-LOCK BRAKE SYS., TRACTION CONTROL
 FOG LIGHTS, ALUM/ALLOY WHEELS, REARVIEW CAMERA, TIRE INFLATION/PRESSURE MONITOR
 NAVIGATION SYSTEM, AUXILIARY INPUT, BLUETOOTH WIRELESS CONNECTIVITY, HD RADIO
 LEATHER STEERING WHEEL, SATELLITE RADIO, CD PLAYER
 POWER ADJUSTABLE EXTERIOR MIRROR, AUTOMATIC TRANSMISSION, SUNROOF/MOONROOF
 AUTO AIR CONDITION, TRIP COMPUTER, FIRST ROW BUCKET SEAT, SIDE AIRBAGS
 AUTOMATIC HEADLIGHTS, SECOND ROW SIDE AIRBAG WITH HEAD PROTECTION
 REMOTE DECKLID OR TAILGATE RELEASE, MP3 PLAYER, DAYTIME RUNNING LIGHTS
 ELECTRONIC STABILITY CONTROL, FRONT HEATED SEATS, KEYLESS ENTRY SYSTEM
 REAR BENCH SEAT, REAR SPOILER, STEERING WHEEL AUDIO CONTROLS

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	101553	BDY	REPAIR	L Quarter Outer Panel Assy	Existing		6.5* #
2	AUTO	REF	REFINISH	L Quarter Panel Outside			C 2.2
3	101558	BDY	REMOVE/REPLACE	L Quarter Extension	61698-02914	70.05	1.5
4	AUTO	REF	REFINISH	L Qtr Panel Extension			C 0.5
5	100203	BDY	REMOVE/INSTALL	L Rear Combination Lamp			INC #
6	101409	BDY	REMOVE/REPLACE	L Rear Combination Lamp Assembly	81560-02751	127.83	0.8 #
7	101248	BDY	REMOVE/INSTALL	Rear Bumper Cover			INC
8	AUTO	BDY	OVERHAUL	Rear Bumper Cover Assy			1.5
9	101307	BDY	REMOVE/REPLACE	Rear Bumper Cover	52159-03901	273.85	INC
10	AUTO	REF	REFINISH	Rear Bumper Cover			C 3.0 #
11	101310	BDY	REMOVE/REPLACE	L Rear Upr Bumper Support	52563-02210	29.39	0.1 #
12	101312	BDY	REMOVE/REPLACE	L Rear Bumper Support	52576-02110	63.96	0.1 #
13	AUTO	REF	ADD'L OPR	Clear Coat			1.6
14	933005	BDY	ADD'L OPR	Restore Corrosion Protection		10.00	* 0.3*
15	933018	REF	ADD'L OPR	Mask For Overspray		5.00	* 0.3*
16	AUTO		ADD'L COST	Paint/Materials		292.00	*
17	AUTO		ADD'L COST	Hazardous Waste Disposal		5.00	*

ESTIMATE RECALL NUMBER: 03/02/2021 16:25:24 29366
 Mitchell Data Version: OEM: FEB_21_V

Software Version: 7.1.240

Copyright (C) 1994 - 2021 Mitchell International
 All Rights Reserved


Page 1 of 2

* - Judgment Item
 # - Labor Note Applies
 C - Included in Clear Coat Calc

Estimate Totals

I. Labor Subtotals	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	II. Part Replacement Summary	Amount
Body	10.8	60.00	10.00	0.00	658.00 T	Taxable Parts	565.08
Refinish	7.6	60.00	5.00	0.00	461.00 T	Sales Tax @ 5.500%	31.08
					Taxable Labor		
					Labor Tax @ 5.500 %		
					1,119.00	Total Replacement Parts Amount	596.16
					61.55		
Labor Summary	18.4				1,180.55		
III. Additional Costs					Amount	IV. Adjustments	Amount
Taxable Costs					297.00	Insurance Deductible	0.00
Sales Tax					16.34	Customer Responsibility	0.00
Total Additional Costs					313.34		
Paint Material Method: Rates							
Init Rate = 40.00 , Init Max Hours = 99.9, Addl Rate = 0.00							
						I. Total Labor:	1,180.55
						II. Total Replacement Parts:	596.16
						III. Total Additional Costs:	313.34
						Gross Total:	2,090.05
						IV. Total Adjustments:	0.00
						Net Total:	2,090.05

This is a preliminary estimate.
Additional changes to the estimate may be required for the actual repair.



CALIBER - WEST ALLIS - LINCOLN AVE

RESTORING THE RHYTHM OF YOUR LIFE
11330 W LINCOLN AVE, WEST ALLIS, WI 53227
Phone: (414) 327-7100
FAX: (414) 327-8100

Workfile ID: 739fdadc
Federal ID: 33-0730794
State ID: N/A
Federal EPA: N/A
State EPA: N/A

Preliminary Estimate

Customer: Paulik, Sarah

Written By: Kyle Nisbet

Insured: Paulik, Sarah
Type of Loss:
Point of Impact: 06 Rear

Policy #:
Date of Loss:

Claim #:
Days to Repair: 0

Owner:

Paulik, Sarah
(414) 712-1002 Cell

Inspection Location:

CALIBER - WEST ALLIS - LINCOLN AVE
11330 W LINCOLN AVE
WEST ALLIS, WI 53227
Repair Facility
(414) 327-7100 Business

Insurance Company:

CUSTOMER PAY

VEHICLE

2015 TOYO Corolla S w/Continuously Variable Transmission 4D SED 4-1.8L Gasoline Sequential MPI White

VIN: [REDACTED]9	Interior Color:	Mileage In: 59,598	Vehicle Out:
License: ACB-5123	Exterior Color: White	Mileage Out:	
State: WI	Production Date: 6/2015	Condition:	Job #:

TRANSMISSION

Automatic Transmission

POWER

Power Steering

Power Brakes

Power Windows

Power Locks

Power Mirrors

Heated Mirrors

DECOR

Dual Mirrors

Tinted Glass

Console/Storage

CONVENIENCE

Air Conditioning

Intermittent Wipers

Tilt Wheel

Cruise Control

Rear Defogger

Keyless Entry

Steering Wheel Touch Controls

Telescopic Wheel

Climate Control

Backup Camera

RADIO

AM Radio

FM Radio

Stereo

Search/Seek

CD Player

Auxiliary Audio Connection

Equalizer

SAFETY

Drivers Side Air Bag

Passenger Air Bag

Anti-Lock Brakes (4)

4 Wheel Disc Brakes

Front Side Impact Air Bags

Head/Curtain Air Bags

Hands Free Device

SEATS

Cloth Seats

Bucket Seats

WHEELS

Wheel Covers

PAINT

Clear Coat Paint

OTHER

Fog Lamps

Traction Control

Stability Control

Rear Spoiler

Signal Integrated Mirrors

Xenon or L.E.D. Headlamps

Power Trunk/Liftgate

Preliminary Estimate

Customer: Paulik, Sarah

2015 TOYO Corolla S w/Continuously Variable Transmission 4D SED 4-1.8L Gasoline Sequential MPI White

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		REAR BUMPER					
2		O/H rear bumper				1.6	
3	<>	Repl Bumper cover	5215903901	1	273.85	Incl.	2.6
4		Add for Clear Coat					1.0
5	*	R&I Step pad				<u>0.4</u>	
6		Repl LT Side support	5257602110	1	63.96	0.1	
7		REAR LAMPS					
8	**	Repl A/M CAPA LT Combo lamp assy	8156002751	1	91.00	0.3	
9		REAR BODY & FLOOR					
10	*	Rpr Rear body panel				<u>5.0</u>	1.6
11		Overlap Major Non-Adj. Panel					-0.2
12		Add for Clear Coat					0.3
13		R&I Rear panel trim				0.2	
14		MISCELLANEOUS OPERATIONS					
15	*	Repl Cover car/bag		1	<u>10.00</u>	<u>0.3</u>	
16	#	Repl Corrosion Protection Primer		1	12.00 T	0.3	
17	#	Rpr Disconnect Battery Cable				0.5	
18	#	Flex Additive		1	10.00 T		
19	#	Subl Hazardous Waste Disposal		1	5.00 X		
20	#	Mask for Primer		1	10.00 X	0.3	
21		VEHICLE DIAGNOSTICS					
22	#	Pre-repair scan		1	40.00 X	0.5	
23	#	Post-repair scan		1	80.00 X	0.5	
SUBTOTALS					595.81	10.0	5.3

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			438.81
Body Labor	10.0 hrs @	\$ 62.00 /hr	620.00
Paint Labor	5.3 hrs @	\$ 62.00 /hr	328.60
Paint Supplies	5.3 hrs @	\$ 42.00 /hr	222.60
Miscellaneous			157.00
Subtotal			1,767.01
Sales Tax	\$ 1,767.01 @	5.5000 %	97.19
Grand Total			1,864.20
Deductible			0.00
CUSTOMER PAY			0.00
INSURANCE PAY			1,864.20

Preliminary Estimate

Customer: Paulik, Sarah

2015 TOYO Corolla S w/Continuously Variable Transmission 4D SED 4-1.8L Gasoline Sequential MPI White

=====
Caliber Collision is the industry leader in quality collision repair. Since day one, our highest purpose has been to get people just like you back on the road as quickly as possible and fully restored to the rhythm of your life. You can be sure we do everything possible to ensure your complete satisfaction including:

- Personalized, high quality service from the largest collision repair company in the U.S.
- Consistently ranked among the highest customer satisfaction scores in the industry.
- Approved by every major insurance company in the U.S.
- Expedited car rental and towing services to get you back on the road again in no time.
- Repair work backed by a written, lifetime warranty honored at every location.
- 24/7/365 customer service to answer questions and put your mind at ease.

This is a preliminary estimate based on visible damage. There may be additional repairs needed once the vehicle is taken apart by our I-CAR Gold Class technicians to identify any additional damage.

If an insurance company has written an estimate for you, please provide us with a copy. Properly endorsed insurance company checks are welcome as payment for the repair of your vehicle. Caliber Collision gladly accepts all major credit cards, debit cards, cashier's and traveler's checks. See your Caliber Collision center for details on acceptance of personal checks.

Before leaving your vehicle with us, please remove all important personal and valuable items from your vehicle. Caliber Collision is not responsible for belongings left in your vehicle.

Please let us know how we can be of further assistance, and when we can schedule an appointment for your vehicle to be repaired.

Caliber Collision - Restoring The Rhythm Of Your Life®

=====
MOTOR VEHICLE REPAIR PRACTICES ARE REGULATED BY CHAPTER ATCP 132, WIS. ADM. CODE, ADMINISTERED BY THE BUREAU OF CONSUMER PROTECTION, WISCONSIN DEPT. OF AGRICULTURE, TRADE AND CONSUMER PROTECTION, P.O. BOX 8911, MADISON, WISCONSIN 53708-8911.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE REPLACEMENT PARTS RATHER THAN BY THE MANUFACTURER OF YOUR MOTOR VEHICLE.

Preliminary Estimate

Customer: Paulik, Sarah

2015 TOYO Corolla S w/Continuously Variable Transmission 4D SED 4-1.8L Gasoline Sequential MPI White

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide ARM8429, CCC Data Date 03/09/2021, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2021 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Information Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

Preliminary Estimate

Customer: Paulik, Sarah

2015 TOYO Corolla S w/Continuously Variable Transmission 4D SED 4-1.8L Gasoline Sequential MPI White

PARTS SUPPLIER LIST

Line	Supplier	Description	Price
8	All Star Auto Lights - ARO 15326 Oakwood Drive ROMULUS MI 48174 (734) 710-9460	#116640009 A/M CAPA LT Combo lamp assy Quote: 37975797 Expires: 03/25/21	\$ 91.00