RECEIVED

FEB 24 2026

CITY OF WEST ALLIS

CLAIMANT CONTACT INFORMATION

Name: Angela Artuso
Address: 1801 S. 72nd St
West Allis, WI 53214

Phone: 414-544-5750
Email: aartuso29@gmail.com

INSTRUCTIONS

Complete this form, print and sign it, and serve a hard copy upon the West Allis City Clerk. If you have questions about how to fill out this form, please contact a private attorney who can assist you.

NOTICE OF CLAIM

Date of incident: 12/2/25
Location: 1700 Block of S. 72nd St
Time of day: 1:00 p.m.

Describe the circumstances of your claim here. You may attach additional sheets or exhibits. Some helpful information may be the police report, pictures of the incident or damage, a diagram of the location, a list of injuries, a list of property damage, names and contact information for witnesses to the incident, and any other information relevant to the

nd

Signed: [signature]
Date: 12/30/25

CLAIM AMOUNT

To complete this claim, attach an itemized statement of damages sought. If any damages are for repair to property, include at least 2 estimates for repairs.

The total amount sought is: $ 1279.74

ST ALLIS
30 DEC '25 PM3:09

SAVE PRINT

MARSHALL AUTO BODY

22300 W BLUEMOUND RD, 22300 W Bluemound Rd, WAUKESHA, WI 53186
Phone: (262) 549-4300
FAX: (262) 549-2080

Workfile ID:	dfd60ab5
Federal ID:	39-1417071
State ID:	N/A in WI

Preliminary Estimate

Customer: Artuso, Angela **Job Number:**

Written By: Ryan Martin

Insured:	Artuso, Angela	Policy #:		Claim #:	
Type of Loss:		Date of Loss:		Days to Repair:	0
Point of Impact:	06 Rear				

Owner:
Artuso, Angela

Inspection Location:
MARSHALL AUTO BODY
22300 W BLUEMOUND RD
22300 W Bluemound Rd
WAUKESHA, WI 53186
Repair Facility
(262) 549-4300 Day

Insurance Company:

VEHICLE

2018 JEEP Compass Latitude FWD 4D UTV 4-2.4L Gasoline Sequential MPI Gray

VIN:	3C4NJCBB5JT102188	Interior Color:	Black	Mileage In:	96,528	Vehicle Out:	
License:	AJZ8200	Exterior Color:	Gray	Mileage Out:			
State:	WI	Production Date:	7/2017	Condition:		Job #:	

TRANSMISSION
Automatic Transmission

POWER
Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Heated Mirrors

DECOR
Dual Mirrors
Privacy Glass
Console/Storage
Overhead Console

CONVENIENCE
Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Message Center
Steering Wheel Touch Controls
Rear Window Wiper
Telescopic Wheel
Backup Camera

RADIO
AM Radio
FM Radio
Stereo
Search/Seek
Auxiliary Audio Connection

SAFETY
Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Traction Control
Stability Control
Front Side Impact Air Bags
Head/Curtain Air Bags
Hands Free Device

SEATS
Cloth Seats
Bucket Seats
Reclining/Lounge Seats

WHEELS
Aluminum/Alloy Wheels

PAINT
Clear Coat Paint

OTHER
Fog Lamps
Rear Spoiler
California Emissions

Preliminary Estimate

Customer: Artuso, Angela **Job Number:**

2018 JEEP Compass Latitude FWD 4D UTV 4-2.4L Gasoline Sequential MPI Gray

Line		Oper	Description	Part Number	Qty	Extended Price $	Labor	Paint
1	**QUARTER PANEL**							
2		R&I	RT Wheel opng mldg				0.3	
3		R&I	LT Wheel opng mldg				0.3	
4	**REAR LAMPS**							
5		Repl	LT Tail lamp assy	55112839AC	1	302.00	0.3	
6	**REAR BUMPER**							
7		R&I	R&I bumper cover				1.1	
8	* <>	Rpr	Bumper cover w/o prk sensor				2.5	2.4
9			Add for Clear Coat					1.0
10		R&I	Lower cover w/o accent, w/o hitch w/o park sensors				0.5	
11		R&I	RT Reflector				Incl.	
12		R&I	LT Reflector				Incl.	
13	**VEHICLE DIAGNOSTICS**							
14	*	Rpr	Pre-repair scan			m	0.5 M	
15	*	Rpr	Post-repair scan			m	0.5 M	
16	#		Flex Paint Additive		1	7.00		
17	#		Haz. Waste Disposal		1	5.00		
				SUBTOTALS		**314.00**	**6.0**	**3.4**

ESTIMATE TOTALS

Category	Basis		Rate	Cost $
Parts				314.00
Body Labor	5.0 hrs	@	$ 70.00 /hr	350.00
Paint Labor	3.4 hrs	@	$ 70.00 /hr	238.00
Mechanical Labor	1.0 hrs	@	$ 140.00 /hr	140.00
Paint Supplies	3.4 hrs	@	$ 52.00 /hr	176.80
Subtotal				1,218.80
Sales Tax	$ 1,218.80	@	5.0000 %	60.94
Grand Total				**1,279.74**

MOTOR VEHICLE REPAIR PRACTICES ARE REGULATED BY CHAPTER ATCP 132, WIS. ADM. CODE, ADMINISTERED BY THE BUREAU OF CONSUMER PROTECTION, WISCONSIN DEPT. OF AGRICULTURE, TRADE AND CONSUMER PROTECTION, P.O. BOX 8911, MADISON, WISCONSIN 53708-8911.

AUTO BODY SPECIALISTS LLC

6024 W MITCHELL STREET, WEST ALLIS, WI 53214
Phone: (414) 545-9211
FAX: (414) 545-7416

Workfile ID:	0f65fda9
Federal ID:	391922584
State ID:	n/a
Federal EPA:	n/a
State EPA:	n/a

Preliminary Estimate

Customer: Artuso, Angela **Job Number:**

Written By: David Jambrek

Insured:	Artuso, Angela	Policy #:		Claim #:	
Type of Loss:	Liability	Date of Loss:		Days to Repair:	0
Point of Impact:	07 Left Rear				

Owner:
Artuso, Angela
(414) 544-5750 Cell

Inspection Location:
AUTO BODY SPECIALISTS LLC
6024 W MITCHELL STREET
WEST ALLIS, WI 53214
Repair Facility
(414) 545-9211 Business

Insurance Company:

VEHICLE

2018 JEEP Compass Latitude FWD 4D UTV 4-2.4L Gasoline Sequential MPI Grey

VIN:	3C4NJCBB5JT102188	Interior Color:		Mileage In:	96,746	Vehicle Out:	
License:	AJZ-8200	Exterior Color:	Grey	Mileage Out:			
State:	WI	Production Date:	7/2017	Condition:		Job #:	

TRANSMISSION
Automatic Transmission

POWER
Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Heated Mirrors

DECOR
Dual Mirrors
Privacy Glass
Console/Storage
Overhead Console

CONVENIENCE
Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Message Center
Steering Wheel Touch Controls
Rear Window Wiper
Telescopic Wheel
Backup Camera

RADIO
AM Radio
FM Radio
Stereo
Search/Seek
Auxiliary Audio Connection

SAFETY
Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Traction Control
Stability Control
Front Side Impact Air Bags
Head/Curtain Air Bags
Hands Free Device

SEATS
Cloth Seats
Bucket Seats
Reclining/Lounge Seats

WHEELS
Aluminum/Alloy Wheels

PAINT
Clear Coat Paint

OTHER
Fog Lamps
Rear Spoiler
California Emissions

Get live updates at www.carwise.com/e/5fApLN

Preliminary Estimate

Customer: Artuso, Angela

Job Number:

2018 JEEP Compass Latitude FWD 4D UTV 4-2.4L Gasoline Sequential MPI Grey

Line		Oper	Description	Part Number	Qty	Extended Price $	Labor	Paint
1	**REAR LAMPS**							
2		Repl	LT Tail lamp assy	55112839AC	1	302.00	0.3	
3	**REAR BUMPER**							
4	* <>	Rpr	Bumper cover w/o prk sensor				1.5	2.4
5			Add for Clear Coat					1.0
6			O/H bumper assy				2.0	
7	#	Subl	Hazardous waste removal		1	5.00 T		
8	#	Repl	Flex additive		1	10.00 T		
9	**VEHICLE DIAGNOSTICS**							
10	*	Rpr	Pre-repair scan			m	0.5 M	
11	*	Rpr	Post-repair scan			m	0.5 M	
				SUBTOTALS		**317.00**	**4.8**	**3.4**

ESTIMATE TOTALS

Category	Basis		Rate	Cost $
Parts				302.00
Body Labor	3.8 hrs	@	$ 72.00 /hr	273.60
Paint Labor	3.4 hrs	@	$ 72.00 /hr	244.80
Mechanical Labor	1.0 hrs	@	$ 124.00 /hr	124.00
Paint Supplies	3.4 hrs	@	$ 51.00 /hr	173.40
Miscellaneous				15.00
Subtotal				1,132.80
Sales Tax	$ 1,132.80	@	5.9000 %	66.84
Grand Total				**1,199.64**

MOTOR VEHICLE REPAIR PRACTICES ARE REGULATED BY CHAPTER ATCP 132, WIS. ADM. CODE, ADMINISTERED BY THE BUREAU OF CONSUMER PROTECTION, WISCONSIN DEPT. OF AGRICULTURE, TRADE AND CONSUMER PROTECTION, P.O. BOX 8911, MADISON, WISCONSIN 53708-8911.