

May 22, 2015
City of West Allis
Clerk's Office

RECEIVED
MAY 26 2015
CITY OF WEST ALLIS
CITY CLERK

To whom it may concern,

On May 14, 2015 at approximately 9:30 am, I was engaged in my job as a City of West Allis Building Inspector. I was parked in my vehicle on the east side of City Hall on 14** s 75th St. I drive my private vehicle during the day and park my car on the roadway daily during my office hours. As I was sitting in my vehicle logging in my mileage, a City pickup truck towing a trailer pulled in front of me along the curb and the rear trailer contacted my front bumper. The driver got out of the pickup truck and apologized explaining she was in a hurry to use the bathroom and thought she had enough room to just pull in quickly. The WAPD was called to the scene. Two police officers responded. One took statements and the other took photographs of the vehicles involved.

I am submitting 3 estimates to repair the damage done to my vehicle by the City's pickup truck when it contacted my parked vehicle. I hope this matter can be resolved quickly as I use my personal vehicle to perform building inspections on behalf of the City of West Allis.

Thanks for your time and consideration in this matter.



Ron Bailey

6231 S. 120th St.

Hales Corners, WI 53130

c. 414.870.0078

w. 414.302.8410

GOFF'S COLLISION REPAIR CENTER

"OUR REPUTATION IS NO ACCIDENT"
11330 W Lincoln ave, WEST ALLIS, WI 53227
Phone: (414) 327-7100
FAX: (414) 327-8100

Workfile ID: 3d091a1c
Federal ID: 46-2266428
State ID: 456-1027985607-03

Preliminary Estimate

Customer: Bailey, Ron

Job Number:

Written By: HILMAN COPPERNALL

Insured: Bailey, Ron
Type of Loss:
Point of Impact:

Policy #:
Date of Loss:

Claim #:
Days to Repair: 0

Owner:

Bailey, Ron
6231 S 120th St
Hales Corners, WI 53130
(414) 870-0078 Day

Inspection Location:

GOFF'S COLLISION REPAIR CENTER
11330 W Lincoln ave
WEST ALLIS, WI 53227
Repair Facility
(414) 327-7100 Business

Insurance Company:

CUSTOMER PAY

VEHICLE

| | | | |
|------------------------|-------------------------|-------------------------|--------------------|
| Year: 2008 | Body Style: 4D UTV | VIN: 1GNDDT13S682251222 | Mileage In: 132434 |
| Make: CHEV | Engine: 6-4.2L-FI | License: | Mileage Out: |
| Model: TRAILBLAZER 4X4 | Production Date: 7/2008 | State: | Vehicle Out: |
| Color: Int: | Condition: | Job #: | |

TRANSMISSION

Automatic Transmission
Overdrive
4 Wheel Drive

POWER

Power Steering
Power Brakes
Power Windows
Power Locks

DECOR

Dual Mirrors
Console/Storage

CONVENIENCE

Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Window Wiper

RADIO

AM Radio
FM Radio
Stereo
Search/Seek
CD Player

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Traction Control
Stability Control
Head/Curtain Air Bags
Communications System

ROOF

Luggage/Roof Rack

SEATS

Cloth Seats
Bucket Seats
Reclining/Lounge Seats

WHEELS

Aluminum/Alloy Wheels

PAINT

Clear Coat Paint
Metallic Paint

TRUCK

Trailer Hitch
Trailer Package

Preliminary Estimate

Customer: Bailey, Ron

Job Number:

Vehicle: 2008 CHEV TRAILBLAZER 4X4 4D UTV 6-4.2L-FI

| Line | Oper | Description | Part Number | Qty | Extended Price \$ | Labor | Paint |
|------------------|------|--|-------------|-----|-------------------|------------|------------|
| 1 | | FRONT BUMPER | | | | | |
| 2 | | O/H front bumper | | | | 1.6 | |
| 3 | R&I | R&I bumper cover | | | | Incl. | |
| 4 | * <> | Rpr Bumper cover w/o fog lamp | | | | 4.0 | 2.6 |
| | | Note: BUMPER COVER MAY REQUIRE REPLACEMENT | | | | | |
| 5 | | Add for Clear Coat | | | | | 1.0 |
| 6 | R&I | License mount | | | | 0.2 | |
| 7 | Repl | Air deflector w/o fog lamp | 15008771 | 1 | 78.95 | Incl. | |
| 8 | # | Subl Hazardous Waste Removal | | 1 | 5.00 | | |
| 9 | # | Repl Flex | | 1 | 7.00 | | |
| SUBTOTALS | | | | | 90.95 | 5.8 | 3.6 |

ESTIMATE TOTALS

| Category | Basis | Rate | Cost \$ |
|----------------------|-------------|--------------|---------------|
| Parts | | | 90.95 |
| Body Labor | 5.8 hrs @ | \$ 58.00 /hr | 336.40 |
| Paint Labor | 3.6 hrs @ | \$ 58.00 /hr | 208.80 |
| Paint Supplies | 3.6 hrs @ | \$ 38.00 /hr | 136.80 |
| Subtotal | | | 772.95 |
| Sales Tax | \$ 772.95 @ | 5.6000 % | 43.29 |
| Grand Total | | | 816.24 |
| Deductible | | | 0.00 |
| CUSTOMER PAY | | | 0.00 |
| INSURANCE PAY | | | 816.24 |

MOTOR VEHICLE REPAIR PRACTICES ARE REGULATED BY CHAPTER ATCP 132, WIS. ADM. CODE, ADMINISTERED BY THE BUREAU OF CONSUMER PROTECTION, WISCONSIN DEPT. OF AGRICULTURE, TRADE AND CONSUMER PROTECTION, P.O. BOX 8911, MADISON, WISCONSIN 53708-8911.

Preliminary Estimate

Customer: Bailey, Ron

Job Number:

Vehicle: 2008 CHEV TRAILBLAZER 4X4 4D UTV 6-4.2L-FI

Estimate based on MOTOR CRASH ESTIMATING GUIDE. Unless otherwise noted all items are derived from the Guide DR1GN02, CCC Data Date 5/14/2015, and the parts selected are OEM-parts manufactured by the vehicles Original Equipment Manufacturer. OEM parts are available at OE/Vehicle dealerships. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships. OPT OEM or ALT OEM parts may reflect some specific, special, or unique pricing or discount. OPT OEM or ALT OEM parts may include "Blemished" parts provided by OEM's through OEM vehicle dealerships. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor information provided by MOTOR may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM or A/M. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2015 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a complete list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Information Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

HOLZ MOTORS, INC. BODY SHOP
5961 S.108TH PLACE PO BOX 226
HALES CORNERS, WI 53130
DIRECT LINE: (414) 529-7848 & (414) 425-2400 FAX: (414) 529-7533
FEDERAL I.D. #39-0792093

*** PRELIMINARY ESTIMATE ***

05/18/2015 03:10 PM

Owner

Owner: RON BAILEY
Address: 6231 S 120TH ST
City State Zip: Hales Corners, WI 53130

Work/Day: (414)870-0078
FAX:

Inspection

Inspection Date: 05/18/2015 03:10 PM
Primary Impact: Left Front Corner

Inspection Type:
Secondary Impact:

Appraiser Name: JIM OSWALD

Appraiser License # :

Repairer

Repairer: HOLZ MOTORS
Address: 5961 S. 108TH PLACE
City State Zip: Hales Corners, WI 53130
Email: rgriese@holzmotors.com

Contact:
Work/Day: (414)529-7848
Work/Day:

Vehicle

2008 Chevrolet Trailblazer STD 4 DR Wagon
6cyl Gasoline 4.2
4 Speed Automatic

Lic.Plate: 946-RRD
Lic Expire:
Prod Date:
Veh Insp# :
Condition:
Ext. Color: MAROON
Ext. Refinish: Two-Stage

Lic State: WI
VIN: 1GNDDT13S682251222
Mileage: 132,247
Mileage Type: Actual
Code: U8433A
Int. Color:
Int. Refinish: Two-Stage

Options

4-Wheel Drive
Aluminum/Alloy Wheels
Bucket Seats
Cruise Control
Head Airbags
OnStar System
Power Steering
Rem Trunk-L/Gate Release
Tachometer
Tinted Glass
Velour/Cloth Seats

AM/FM CD Player
Anti-Lock Brakes
Camper/Towing Package
Dual Airbags
Intermittent Wipers
Power Brakes
Power Windows
Roof/Luggage Rack
Theft Deterrent System
Traction Control System
XM Satellite Radio

Air Conditioning
Auto Locking Hubs (4WD)
Center Console
Electronic Transfer Case
Lighted Entry System
Power Door Locks
Rear Window Wiper/Washer
Stability Cntrl Suspensn
Tilt Steering Wheel
Trailer Hitch

Damages

| Line | Op | Guide | MC | Description | MFR.Part No. | Price | ADJ% | B% | Hours | R |
|------|-------|-------|----|-------------------------|---------------------|-----------|------|----|-------|----|
| 1 | N | 170 | | Front Bumper Overhaul | Additional Labor | | | | 2.0 | SM |
| 2 | E | 4 | | Cover,Front Bumper | 88937008 GM Part | \$288.00* | | | 0.2 | SM |
| | | | | >> GM CONQUEST PRICE | | | | | | |
| 3 | L | 4 | 13 | Cover,Front Bumper | Refinish | | | | 3.1 | RF |
| | | | | | 2.1 Surface | | | | | |
| | | | | | 0.6 Two-stage setup | | | | | |
| | | | | | 0.4 Two-stage | | | | | |
| 4 | E | 74 | | Defl,Front Bumper | 15213549 GM Part | \$51.57 | | | INC | SM |
| 5 | N | M03 | | Flex Additive | Additional Labor | \$5.00* | | | | RF |
| 6 | SB | M60 | | Hazardous Waste Removal | Sublet Repair | \$3.00* | | | | SM |
| 6 | Items | | | | | | | | | |

MC Message

13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

Estimate Total & Entries

| | | |
|-------------------------|----------|----------|
| Gross Parts | \$339.57 | |
| Other Parts | \$5.00 | |
| Paint & Materials | \$111.60 | |
| Parts & Material Total | | \$456.17 |
| Tax on Parts & Material | @ 5.600% | \$25.55 |

| Labor | Rate | Replace Hrs | Repair Hrs | Total Hrs | | |
|--------------------|---------|-------------|------------|-----------|----------|-----------------|
| Sheet Metal (SM) | \$56.00 | 0.2 | 2.0 | 2.2 | \$123.20 | |
| Mech/Elec (ME) | \$90.00 | | | | | |
| Frame (FR) | \$56.00 | | | | | |
| Refinish (RF) | \$56.00 | 3.1 | | 3.1 | \$173.60 | |
| Paint & Materials | \$36.00 | | | | | |
| Labor Total | | | | 5.3 Hours | | \$296.80 |
| Tax on Labor | | @ 5.600% | | | \$16.62 | |
| Sublet Repairs | | | | | \$3.00 | |
| Tax on Sublet | | @ 5.600% | | | \$0.17 | |
| Gross Total | | | | | | \$798.31 |
| Net Total | | | | | | \$798.31 |

Alternate Parts Y/00/00/00/00 CUM 00/00/00/00/00 Zip Code: 53130 Default
 Recycled Parts NOT REQUESTED

Audatex Estimating 7.0.417 ES 05/18/2015 03:16 PM REL 7.0.417 DT 04/01/2015 DB 05/15/2015
 Copyright (C) 2015 Audatex North America, Inc.

1.0 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.

Date: 5/20/2015 10:46 AM
 Estimate ID: 22955
 Estimate Version: 0
 Preliminary
 Profile ID: Mitchell

Brownell Quality Collision Center

10414 W. Greenfield Ave., West Allis, WI 53214-3930
 (414) 774-0610
 Fax: (414) 774-0760
 Email: brownellqcc@aol.com

Damage Assessed By: RYAN KONKEL
 Classification: Field

Deductible: 0.00
 Claim Number: 22955

Owner: RON BAILEY
 Address: 6231 S 120TH ST, HALES CORNERS, WI 53130
 Telephone: Home Phone: (414) 870-0078

Mitchell Service: 910501

Description: 2008 Chevrolet TrailBlazer LT
 Body Style: 4D Ut
 VIN: 1GNDT13S682251222
 OEM/ALT: O
 Color: PURPLE

Drive Train: 4.2L Inj 6 Cyl 4WD
 License: 946RRD WI
 Search Code: None

Options: PASSENGER AIRBAG, POWER DRIVER SEAT, POWER LOCK, POWER WINDOW, POWER STEERING
 REAR WINDOW DEFOGGER, AIR CONDITIONING, CRUISE CONTROL, AM/FM STEREO
 DRIVER AIRBAG, HEATED EXTERIOR MIRROR, REAR (DUAL-ZONE) AC, LEATHER SEAT
 FRONT SIDE AIRBAG WITH HEAD PROTECTION, LUGGAGE RACK, ANTI-LOCK BRAKE SYS.
 TRACTION CONTROL, FOG LIGHTS, ALUM/ALLOY WHEELS, TIRE INFLATION/PRESSURE MONITOR
 ANTI-THEFT SYSTEM, LEATHER STEERING WHEEL, SATELLITE RADIO, CD PLAYER
 TOW HITCH RECEIVER, POWER ADJUSTABLE EXTERIOR MIRROR, 4WD OR AWD, PRIVACY GLASS
 AUTO AIR CONDITION, TRIP COMPUTER, FIRST ROW BUCKET SEAT, TELEMATIC SYSTEMS
 UNIVERSAL GARAGE DOOR OPENER, REAR HEATING, VENTILATION & AIR CONDITIONING
 4 WHEEL DRIVE, AUTOMATIC HEADLIGHTS, SECOND ROW SIDE AIRBAG WITH HEAD PROTECTION
 INTERIOR AUTOMATIC DAY/NIGHT OR ELECTROCHROMATIC MIRROR, DAYTIME RUNNING LIGHTS
 DRIVER SEAT WITH POWER LUMBAR SUPPORT, ELECTRONIC STABILITY CONTROL
 KEYLESS ENTRY SYSTEM, REAR AUDIO CONTROLS, STEERING WHEEL AUDIO CONTROLS

| Line Item | Entry Number | Labor Type | Operation | Line Item Description | Part Type/ Part Number | Dollar Amount | Labor Units |
|-----------|--------------|------------|----------------|------------------------------|---------------------------|---------------|-------------|
| 1 | AUTO | BDY | OVERHAUL | Frnt Bumper Cover Assy | | | 1.7 # |
| 2 | 000015 | BDY | REMOVE/REPLACE | Frnt Bumper Cover | ** QUAL REPL PART | 288.00 * | INC # |
| 3 | AUTO | REF | REFINISH | Frnt Bumper Cover | | | C 2.5 |
| 4 | AUTO | BDY | REMOVE/INSTALL | Grille Assy | | | 0.4 |
| 5 | 000018 | BDY | REMOVE/REPLACE | Frnt Bumper Impact Bar (HSS) | ** QUAL REPL PART | 279.00 * | 0.2 # |
| 6 | AUTO | BDY | REMOVE/INSTALL | Frnt Bumper Cover | | | INC # |
| 7 | 004446 | BDY | REMOVE/REPLACE | L Frnt Bumper Brace | ** QUAL REPL PART | 17.00 * | INC |
| 8 | 004448 | BDY | REMOVE/REPLACE | Frnt Bumper Air Deflector | ** QUAL REPL PART | 44.00 * | INC |
| 9 | 000309 | BDY | REPAIR | L Fender Panel | Existing | | 1.0* # |
| 10 | AUTO | REF | REFINISH | L Fender Outside | | | C 2.2 |
| 11 | AUTO | REF | ADD'L OPR | Clear Coat | | | 1.4* |
| 12 | 900500 | BDY * | REMOVE/REPLACE | FLEX ADDITIVE | New | 12.00 * | 0.0* |
| 13 | 900500 | BDY * | ADD'L LABOR OP | MASK JAMS/ CAR COVER | New | 5.00 * | 0.3* |
| 14 | AUTO | | ADD'L COST | Paint/Materials | | 219.60 * | |
| 15 | AUTO | | ADD'L COST | Hazardous Waste Disposal | | 5.00 * | |

ESTIMATE RECALL NUMBER: 05/20/2015 10:43:13 22955
 Mitchell Data Version: MAR_15_V

Software Version: 7.1.177

Copyright (C) 1994 - 2015 Mitchell International
 All Rights Reserved

Page 1 of 2

* - Judgment Item
 # - Labor Note Applies
 C - Included in Clear Coat Calc

Estimate Totals

| I. Labor Subtotals | Units | Rate | Add'l Labor Amount | Sublet Amount | Totals | II. Part Replacement Summary | Amount |
|---|-------|-------|--------------------------|------------------|------------------------------|--------------------------------|----------|
| Body | 3.6 | 56.00 | 0.00 | 0.00 | 201.60 T | Taxable Parts | 645.00 |
| Refinish | 6.1 | 56.00 | 0.00 | 0.00 | 341.60 T | Sales Tax @ 5.600% | 36.12 |
| | | | | | 543.20 | Total Replacement Parts Amount | 681.12 |
| | | | @ 5.600 % | | 30.42 | | |
| Labor Summary | 9.7 | | | | 573.62 | | |
| | | | | | | | |
| III. Additional Costs | | | | | Amount | IV. Adjustments | Amount |
| Taxable Costs | | | | | 224.60 | Insurance Deductible | 0.00 |
| Sales Tax | | | @ 5.600% | | 12.58 | Customer Responsibility | 0.00 |
| Total Additional Costs | | | | | 237.18 | | |
| | | | | | | | |
| Paint Material Method: Rates | | | | | | | |
| Init Rate = 36.00 , Init Max Hours = 99.9, Addl Rate = 0.00 | | | | | | | |
| | | | | | | | |
| | | | | | I. Total Labor: | | 573.62 |
| | | | | | II. Total Replacement Parts: | | 681.12 |
| | | | | | III. Total Additional Costs: | | 237.18 |
| | | | | | Gross Total: | | 1,491.92 |
| | | | | | IV. Total Adjustments: | | 0.00 |
| | | | | | Net Total: | | 1,491.92 |

This is a preliminary estimate.
Additional changes to the estimate may be required for the actual repair.