# **CLAIMANT CONTACT INFORMATION**



Name: Kathteen Malison Address: 3101 5, Told+ PKWY. West Allis W 53227	Phone: (414) 578-9322 Email:					
INSTRUCTIONS  Complete this form, print and sign it, and serve a hard copy upon the West Allis City Clerk. If you have questions about how to fill out this form, please contact a private attorney who can						
assist you.  NOTICE OF	CLAIM					
Date of incident:	Time of day:					
Describe the circumstances of your claim here. Y Some helpful information may be the police repdiagram of the location, a list of injuries, a list information for witnesses to the incident, an circumstances.	port, pictures of the incident or damage, a t of property damage, names and contact					
108 st						
She was trying to  pull out onto  twy 100 and  then reversed  and backed  into me  City  vehicle  y  my  car	Parking Community medical Bldg.					
Check one:						
Signed:  CLAIM AMO  To complete this claim, attach an itemized stateme for repair to property, include at least 2 estimates for the total amount sought is:  Signed:  CLAIM AMO  To the total amount sought is:  CLAIM AMO  To the total amount sought is:  CLAIM AMO  The total amount sought is:	or damages. This claim is not complete and for damages on a later date.  Date: 4-7-25  DUNT  nt of damages sought. If any damages are					

SAVE

**PRINT** 

#### WEST ALLIS AUTO BODY 8808 W. NATIONAL AVE. WEST ALLIS, WISC 53227

PHONE: 414-327-4140 FAX: 414-327-0033

## \*\*\* PRELIMINARY ESTIMATE \*\*\*

04/07/2025 01:21 PM

Owner

Owner: KATHLEEN MALISON

**Control Information** 

Loss Date/Time: 01:21 PM

Loss Type:

Inspection

Inspection Date: 04/07/2025 01:21 PM

Assigned Date/Time: 01:21 PM First Contact Date/Time: 01:21 PM

Appraiser Name: Glenn

Second Contact Date/Time: 01:21 PM

Inspection Type:

Received Date/Time: 01:21 PM Appointment Date/Time: 01:21 PM

Appraiser License #2:

Repairer

Repairer: WEST ALLIS AUTO BODY

Address: 8808 W NATIONAL AVE

City State Zip: West Allis, WI 53227

Email: waab6@aol.com

Contact: Glenn

Work/Day: (414)327-4140 Home/Evening: (414)327-4143

FAX: (414)327-0033

Repair Start Date/Time: 01:21 PM Repair Complete Date/Time: 01:21 PM Target Complete Date/Time: 01:21 PM

Vehicle Drop Off Date/Time: 01:21 PM Vehicle Pick Up Date/Time: 01:21 PM

Days To Repair: 5

Vehicle

2007 Toyota Highlander STD 4 DR Wagon 4cyl Gasoline 2.4

4 Speed Automatic

Lic Expire:

Veh Insp#:

Condition:

Ext. Refinish: Two-Stage

VIN: Unreadable VIN

Mileage Type: Actual Code: Y6513A

Int. Refinish: Two-Stage

**Options** 

Air Conditioning **Bodyside Moldings** Compact Disc W/Tape

Head Airbags Lighted Entry System Power Door Locks **Power Windows** 

Alarm System Center Console Cruise Control Intermittent Wipers

Overhead Console **Power Mirrors** Rear Window Defroster Anti-Lock Brakes Color-Keyed Bumper(s)

**Dual Airbags** Keyless Entry System Power Brakes

Power Steering Rear Window Wiper/Washer Roof/Luggage Rack Split Folding Rear Seat Tachometer Traction Control System Side Airbags Stability Cntrl Suspensn Tilt Steering Wheel Velour/Cloth Seats

Skid Plates Styled Steel Wheels Tonneau/Cargo Cover

Damages									
Line Op	Guide	МС	Description		MFR.Part No.	Price	ADJ% B%	Hours	R
Front Bum									
1 EC 2 L	6 6	13	Cover,Front I		Replace Economy Refinish 2.6 Surface 0.6 Two-stage setup 0.5 Two-stage	\$260.00*		1.9 3.7	SM RF
3 E 4 L	15 15		Reinf,Front B Reinf,Front B		5206248010 Refinish 0.4 Surface 0.1 Two-stage	\$67.74		0.2 0.5	SM RF
5 E 6 L	395 395	01		look Access LT look Access LT	5212748030A0 Refinish 0.3 Surface 0.1 Two-stage	\$9.31		0.4	SM RF
Front End	Panel And	d Lan	nps						
7 OE 8 L	28 28	01	Grille Assem Grille Assem		Replace PXN OE Srpls Refinish 0.7 Surface 0.1 Two-stage	\$251.00		!NC 0.8	SM RF
9 EC 10 N	41 973		Headlamp As Headlamps A	ssy,Halogen LT Aim	Replace Economy Additional Labor	\$300.00*		0.1 0.4	SM SM
Front Body	And Wir	dshi	eld						
11 EC 12 L			Fender,Front Fender,Front		Replace Economy Refinish 2.1 Surface 0.5 Edge 0.5 Two-stage	\$350.00*		1.4 3.1	SM RF
Front Door 13 BR			Door Shell,Fr	ont LT	Blend Refinish 0.8 Blend 0.4 Two-stage			1.2	RF
14 RI 15 RI	229 227		Mirror,Outer Handle,Front		R & I Assembly R & I Assembly			0.3 0.7	SM SM
Manual Ent 16 EC 17 EC 18 EC 18			COVER CAR CORROSION FLEX ADDIT	N PROTECTION	Replace Economy Replace Economy Replace Economy	\$5.00* \$5.00* \$5.00*			RF RF
			MC	Message					
			01 13		FOR EXACT PART # / PRI HOURS FIRST PANEL TW		/ANCE		2 •

**Estimate Total & Entries** 

		-					0470172020 01.211 W
OEM Parts Other Parts Paint & Materials Parts & Material Total Tax on Parts & Material		9.7	Hours @ @	\$45.00 5.900%	\$77.05 \$1,176.00 \$350.00**	\$1,603.05 \$94.58	
Labor	Rate	Replace Hrs	Repair Hrs	s Total Hrs			
Sheet Metal (SM) Mech/Elec (ME) Frame (FR) Refinish (RF)	\$65.00 \$80.00 \$65.00 \$65.00	4.6 9.7	0.4	5.0	\$325.00 \$630.50		
Labor Total				····		44	
Labor Total Tax on Labor Gross Total Net Total		@	5.900%	14.7 F	\$56.37	\$955.50 <b>\$2,709.50</b> <b>\$2,709.50</b>	

Alternate Parts Y/05/01/00/04/04 Cumulative 05/01/00/04/04 Zip Code: 53227 Audatex Host Rate Name Default

Audatex Estimating 8.2.446 ES 04/07/2025 01:23 PM REL 8.2.446 DT 03/01/2025

State Disclosure: Not Selected

© 2025 Audatex North America, LLC.

A 50% Blend Refinish calculation of basecoat refinish labor was used for applicable panels on this estimate.

\*\* USER-ESTABLISHED THRESHOLD FOR PAINT AND MATERIALS HAS BEEN REACHED AND CALCULATED IN THIS ESTIMATE.

ANY ADDITIONAL MATERIALS MAY REQUIRE FURTHER APPROVAL. \*\*

2.3 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.

## Op Codes

* = User-Entered Value	^ = Labor Matches System Assigned Rates	
NG = Replace NAGS	EC = Replace Economy	OE = Replace PXN OE Srpls
UE = Replace OE Surplus	ET = Partial Replace Labor	EP = Replace PXN
EU = Replace Recycled	TE = Partial Replace Price	PM= Replace PXN Reman/Reblt
UM= Replace Reman/Rebuilt	L = Refinish	PC = Replace PXN Reconditioned
UC = Replace Reconditioned	TT = Two-Tone	SB = Sublet Repair
N = Additional Labor	BR = Blend Refinish	I = Repair
IT = Partial Repair	CG= Chipguard	RI = R & I Assembly
P = Check	AA = Appearance Allowance	RP = Related Prior Damage



This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

© 2025 Audatex North America, LLC. AUDATEX is a trademark owned by Audatex North America, LLC. All rights reserved.

# **BROWNELL QUALITY COLLISION CENTER**

Workfile ID: Federal ID:

87892017 39-1758646



10414 W GREENFIELD AVE, MILWAUKEE, WI

53214

Phone: (414) 774-0610 FAX: (414) 774-0760

#### **Preliminary Estimate**

**Customer: MALISON, KATHLEEN** 

Job Number:

Written By: Ryan Konkel

Insured:

MALISON, KATHLEEN

Policy #: Date of Loss: Claim #:

Type of Loss:

Point of Impact: 11 Left Front

Days to Repair: 4

Owner:

MALISON, KATHLEEN

(414) 578-9322 Cell

Inspection Location:

**Insurance Company:** 

10414 W GREENFIELD AVE

BROWNELL QUALITY COLLISION CENTER

MILWAUKEE, WI 53214

Repair Facility

(414) 774-0610 Business

**GREEN** 

#### **VEHICLE**

2007 TOYO Highlander 4D UTV 4-2.4L Gasoline SFI GREEN

VIN:

JTEGD21A770164129

Interior Color:

Mileage In:

Vehicle Out:

License:

Exterior Color:

Mileage Out:

State:

Production Date:

Condition:

Good

Job #:

TRANSMISSION

Automatic Transmission

Overdrive

**POWER** 

**Power Steering** 

Power Brakes

Power Windows

Power Locks

**Power Mirrors** 

**DECOR** 

**Dual Mirrors Body Side Moldings** 

Console/Storage

Overhead Console

CONVENIENCE

Air Conditioning

**Intermittent Wipers** 

Tilt Wheel

Cruise Control

Rear Defogger

Keyless Entry

Rear Window Wiper

**RADIO** 

AM Radio

FM Radio Stereo

Search/Seek

CD Player

Cassette

**SAFETY** 

Drivers Side Air Bag Passenger Air Bag

Anti-Lock Brakes (4) 4 Wheel Disc Brakes

Traction Control

Stability Control

Front Side Impact Air Bags

Head/Curtain Air Bags

ROOF

Luggage/Roof Rack

SEATS

Cloth Seats

**Bucket Seats** 

WHEELS

Styled Steel Wheels

PAINT

Clear Coat Paint

OTHER

California Emissions

## **Customer: MALISON, KATHLEEN**

Job Number:

2007 TOYO Highlander 4D UTV 4-2.4L Gasoline SFI GREEN

Line	C	per	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	FRONT BUMPER	2						
2	** F	Repl	A/M Bumper cover	5211948917	1	285.00	2.0	2.8
3			Add for Clear Coat					1.1
4			Add for fog lamps				0.4	
5	** F	Repl	A/M CAPA LT Side support	5206248010	1	56.00	0.1	
6	** F	Repl	A/M CAPA Energy absorber	5261148050	1	93.00	0.1	
7	, F	Repl	LT Side support plug green	5212748902	1	16.84	Incl.	0.2
8			Add for Clear Coat					0.1
9	GRILLE							
10	**	Repl	A/M Grille green	5310148914G0	1	179.22	Incl.	1.3
11			Add for Clear Coat					0.3
12	FRONT LAMPS							
13	** F	Repl	A/M LT Headlamp assy	8117048550	1	195.00	0.3	
14			Aim headlamps				0.5	
15	FENDER							
16	*	Rpr	LT Fender w/o antenna				6.0	2.0
17			Add for Clear Coat					0.8
18	J	R&I	LT Fender liner				0.4	
19	# F	Repl	Cover Car		1	5.00 T	0.2	
20	# F	Repl	Corrosion protection primer		1	5.00 T	0.3	
21	# F	Repl	Flex additive		1	8.00 T		
22	# 9	Subl	Hazardous waste removal		1	3.00 T		
				SUBTOTALS		846.06	10.3	8.6

#### **ESTIMATE TOTALS**

Category	Basis		Rate	Cost \$
Parts				825.06
Body Labor	10.3 hrs	@	\$ 70.00 /hr	721.00
Paint Labor	8.6 hrs	@	\$ 70.00 /hr	602.00
Paint Supplies	8.6 hrs	@	\$ 50.00 /hr	430.00
Miscellaneous				21.00
Subtotal				2,599.06
Sales Tax	\$ 2,599.06	@	5.9000 %	153.34
Grand Total				2,752.40

MOTOR VEHICLE REPAIR PRACTICES ARE REGULATED BY CHAPTER ATCP 132, WIS. ADM. CODE, ADMINISTERED BY THE BUREAU OF CONSUMER PROTECTION, WISCONSIN DEPT. OF AGRICULTURE, TRADE AND CONSUMER PROTECTION, P.O. BOX 8911, MADISON, WISCONSIN 53708-8911.

#### **Customer: MALISON, KATHLEEN**

Job Number:

2007 TOYO Highlander 4D UTV 4-2.4L Gasoline SFI GREEN

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE REPLACEMENT PARTS RATHER THAN BY THE MANUFACTURER OF YOUR MOTOR VEHICLE.

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide AEM8436, CCC Data Date 04/01/2025, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (\*) or Double Asterisk (\*\*) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2024 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

#### SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

#### SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

#### OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. CFC=Carbon Fiber.

D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. STS=Stainless Steel. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

# **Customer: MALISON, KATHLEEN**

Job Number:

2007 TOYO Highlander 4D UTV 4-2.4L Gasoline SFI GREEN

CCC ONE Estimating - A product of CCC Intelligent Solutions Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

# **Customer: MALISON, KATHLEEN**

Job Number:

2007 TOYO Highlander 4D UTV 4-2.4L Gasoline SFI GREEN

## **PARTS SUPPLIER LIST**

Line	Supplier	Description	Price
2	Keystone, Inc	#TO1000278	\$ 285.00
	4410 N. 132ND STREET, SUITE A	A/M Bumper cover	
	BUTLER WI 53007	Quote: 2928616731	
	(414) 463-1019	Expires: 05/22/25	
5	Keystone, Inc	#TO1042102C	\$ 56.00
	4410 N. 132ND STREET, SUITE A	A/M CAPA LT Side support	
	BUTLER WI 53007	Quote: 2928617607	
	(414) 463-1019	Expires: 05/22/25	
6	Keystone, Inc	#TO1070148C	\$ 93.00
	4410 N. 132ND STREET, SUITE A	A/M CAPA Energy absorber	
	BUTLER WI 53007	Quote: 2928618082	
	(414) 463-1019	Expires: 05/22/25	
10	KSI Trading Corp.	#7165312	\$ 179.22
	5414A West Roosevelt Road	A/M Grille green	
	Chicago IL 60644	Quote: 172020134	
	(800) 244-2639	Expires: 04/14/25	
13	Pam's Auto	#388452-53214	\$ 195.00
	7505 Ridgewood Road	A/M LT Headlamp assy	
	St. Cloud MN 56303	Quote: 163647072	
		Expires: 04/14/25	