

17.



# City of West Allis Matter Summary

7525 W. Greenfield Ave.  
West Allis, WI 53214

File Number	Title	Status
2006-0232	Communication	In Committee
	Communication from City Engineer regarding the alley condition at 7920 W. Hayes Avenue.	
	Introduced: 4/18/2006	Controlling Body: Public Works Committee

## COMMITTEE RECOMMENDATION *PLACE ON FILE*

ACTION DATE:	MOVER	SECONDER		AYE	NO	PRESENT	EXCUSED
<u>4-18-06</u>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Barczak				
	<input type="checkbox"/>	<input type="checkbox"/>	Czaplewski				
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Dobrowski	<input checked="" type="checkbox"/>			
	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Kopplin	<input checked="" type="checkbox"/>			
	<input type="checkbox"/>	<input type="checkbox"/>	Lajsic				
	<input type="checkbox"/>	<input type="checkbox"/>	Narlock	<input type="checkbox"/>			
	<input type="checkbox"/>	<input type="checkbox"/>	Reinke				<input checked="" type="checkbox"/>
	<input type="checkbox"/>	<input type="checkbox"/>	Sengstock				
	<input type="checkbox"/>	<input type="checkbox"/>	Vitale	<input type="checkbox"/>			
	<input type="checkbox"/>	<input type="checkbox"/>	Weigel				
			TOTAL	<u>4</u>	<u>-</u>		<u>1</u>

### SIGNATURE OF COMMITTEE MEMBER

*Paul F. ...* \_\_\_\_\_  
 Chair Vice-Chair Member

## PLACE ON FILE

### COMMON COUNCIL ACTION

ACTION DATE:	MOVER	SECONDER		AYE	NO	PRESENT	EXCUSED
<u>APR 18 2006</u>	<input type="checkbox"/>	<input type="checkbox"/>	Barczak				<input checked="" type="checkbox"/>
	<input type="checkbox"/>	<input type="checkbox"/>	Czaplewski	<input checked="" type="checkbox"/>			
	<input type="checkbox"/>	<input type="checkbox"/>	Dobrowski	<input checked="" type="checkbox"/>			
	<input type="checkbox"/>	<input type="checkbox"/>	Kopplin	<input checked="" type="checkbox"/>			
	<input type="checkbox"/>	<input type="checkbox"/>	Lajsic	<input checked="" type="checkbox"/>			
	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Narlock	<input checked="" type="checkbox"/>			
	<input type="checkbox"/>	<input type="checkbox"/>	Reinke	<input checked="" type="checkbox"/>			
	<input type="checkbox"/>	<input type="checkbox"/>	Sengstock				<input checked="" type="checkbox"/>
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Vitale	<input checked="" type="checkbox"/>			
	<input type="checkbox"/>	<input type="checkbox"/>	Weigel	<input checked="" type="checkbox"/>			
			TOTAL	<u>8</u>	<u>-</u>		<u>2</u>





# CITY OF WEST ALLIS

WISCONSIN



Engineering Department

**MICHAEL G. LEWIS**  
*City Engineer*

## Memorandum

**TO:** Richard Narlock, Chair, Board of Public Works  
Vincent Vitale, First District  
Kurt Kopplin, Second District  
Linda Dobrowski, Fourth District  
James Sengstock, Fifth District

**FROM:** Michael Lewis, City Engineer

**DATE:** April 12, 2006

**RE:** **Alley at 7920 W. Hayes Avenue**

Alderman Kurt Kopplin received a complaint from the homeowner at 7920 W. Hayes Avenue about the condition of the alley right next to his house. The homeowner claims that water leaks from the center of the alley toward his property. The catch basin needs to be rebuilt and the adjacent alley pavement replaced. The rest of the alley is in good condition.

The problem is that the Engineering Department really doesn't have a program for this type of small maintenance work and there are many similar locations. Is the Board interested in starting such a program through Engineering? Special assessments if any?

The following pictures illustrate the problem.

