



CLAIMANT CONTACT INFORMATION

Name: Paula John Phone: 414 426 8477
Address: 2229 So 77th St Email: pjohn0111@yahoo.com
West Allis, WI 53219

INSTRUCTIONS

Complete this form, print and sign it, and serve a hard copy upon the West Allis City Clerk. If you have questions about how to fill out this form, please contact a private attorney who can assist you.

NOTICE OF CLAIM

Date of incident: 7-26-23 Time of day: 12:45-1:30 pm
Location: So 2200 Block So 77th St

Describe the circumstances of your claim here. You may attach additional sheets or exhibits. Some helpful information may be the police report, pictures of the incident or damage, a diagram of the location, a list of injuries, a list of property damage, names and contact information for witnesses to the incident, and any other information relevant to the circumstances.

West Allis work truck backed into my parked car. Driver side quarter panel was damaged.

Check one:

- ☒ I am seeking damages at this time (complete Claim Amount section below)
☐ I am submitting this notice without a claim for damages. This claim is not complete and will not be processed until I submit a claim for damages on a later date.

Signed: Paula John

Date: 7-27-23

CLAIM AMOUNT

To complete this claim, attach an itemized statement of damages sought. If any damages are for repair to property, include at least 2 estimates for repairs.

The total amount sought is: \$ 3897.90

SAVE

PRINT

Angie DeLaPang

414-745-0601

Witness

Tina Torres

414 759 0495



**WEST ALLIS POLICE DEPARTMENT
DRIVER EXCHANGE AND INFORMATION SHEET**

**To be completed by drivers ONLY
Pursuant to Section 346.67 Wis. Stats.**

DATE: 7/26/23 TIME: _____ LOCATION: 2200blk S. 77

TOWING COMPANY: _____

DRIVER'S NAME: _____ PHONE #: _____

ADDRESS: _____ CITY/STATE/ZIP: _____

VEHICLE (MAKE): _____ (MODEL): _____ YEAR: _____

LICENSE PLATE #: _____ ACCIDENT OR CALL #: 23-028895

INSURANCE CARRIER/PHONE: _____

POLICY #: _____

Completion and exchange of this form is for the purpose of facilitating the exchange of information requirement of Section 346.67 Wis. Stats. It is intended only to assist those involved in a crash and facilitate the exchange of information between drivers to assist with any insurance claim, personal reimbursement or civil action

I hereby consent to the release of my personal information to _____
(other driver)

Your Signature _____



Braeger's Lake Auto Body

4100 S 27TH ST, MILWAUKEE, WI 53221

Phone: (414) 281-0454

FAX: (414) 921-9720

Workfile ID:

PartsShare:

a91e6995

7th7Sp

Preliminary Estimate

Customer: JOHN, PAULA

Written By: Matthew Woodrum

Insured: JOHN, PAULA

Type of Loss: Collision

Point of Impact: 07 Left Rear

Policy #: 000802687365

Date of Loss: 7/26/2023 12:30 PM

Claim #: 000723023156D01

Days to Repair: 8

Owner:

JOHN, PAULA

2229 S 77TH ST

WEST ALLIS, WI 53219-1832

(414) 426-8477 Cell

Inspection Location:

2229 S 77TH ST

WEST ALLIS, WI 53219

Other

Insurance Company:

ALLSTATE PROPERTY AND CASUALTY
INSURANCE COMPANY

Allstate Property and Cas

HOME OFFICE CLAIMS

Northbrook

VEHICLE

2017 FORD Fusion Hybrid Platinum FWD 4D SED 4-2.0L Hybrid Sequential MPI RED

VIN: 3FA6P0RUXHR279941

License: AMT6609

State: WI

Interior Color:

Exterior Color: RED

Production Date: 12/2016

Mileage In: 102,556

Mileage Out:

Condition: Good

Vehicle Out:

Job #:

TRANSMISSION

Automatic Transmission

POWER

Power Steering

Power Brakes

Power Windows

Power Locks

Power Mirrors

Heated Mirrors

Power Driver Seat

Power Passenger Seat

Memory Package

DECOR

Dual Mirrors

Tinted Glass

Console/Storage

Overhead Console

CONVENIENCE

Air Conditioning

Intermittent Wipers

Tilt Wheel

Cruise Control

Rear Defogger

Keyless Entry

Alarm

Message Center

Steering Wheel Touch Controls

Telescopic Wheel

Heated Steering Wheel

Climate Control

Navigation System

Remote Starter

Backup Camera

Parking Sensors

Intelligent Cruise

Home Link

RADIO

AM Radio

FM Radio

Stereo

Search/Seek

CD Player

Premium Radio

Satellite Radio

SAFETY

Drivers Side Air Bag

Passenger Air Bag

Anti-Lock Brakes (4)

4 Wheel Disc Brakes

Front Side Impact Air Bags

Head/Curtain Air Bags

Hands Free Device

Blind Spot Detection

Lane Departure Warning

ROOF

Electric Glass Sunroof

SEATS

Bucket Seats

Reclining/Lounge Seats

Leather Seats

Heated Seats

Ventilated Seats

WHEELS

Aluminum/Alloy Wheels

PAINT

Three Stage Paint

OTHER

Fog Lamps

Traction Control

Stability Control

Rear Spoiler

Signal Integrated Mirrors

Xenon or L.E.D. Headlamps

California Emissions

Power Trunk/Liftgate

Preliminary Estimate

Customer: JOHN, PAULA

2017 FORD Fusion Hybrid Platinum FWD 4D SED 4-2.0L Hybrid Sequential MPI RED

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		WHEELS					
2	R&I	LT/Rear R&I wheel			m	0.1 M	
3	#	Subl Tire Mount and Balance		1	20.00 T		
4	#	Subl 4 Wheel Alignment		1	99.95 T		
5		SEATS & TRACKS					
6	R&I	LT R&I rear seat seat back				Incl.	
7	R&I	R&I rear seat seat cushion				0.2	
8		PILLARS, ROCKER & FLOOR					
9	R&I	LT Rocker molding				0.7	
10		REAR DOOR					
11	R&I	LT R&I door assy				1.0	
12	Blnd	LT Outer panel					1.6
13	R&I	LT W'strip on body				Incl.	
14	R&I	LT Door check				0.2	
15		BACK GLASS					
16	*	R&I Back glass Ford Hermosillo plant				Incl.	
17	#	Repl Urethane Glass Kit		1	20.00 T		
18		QUARTER PANEL					
19	Sect	LT Quarter panel	HS7Z5427841A	1	726.88	19.0	3.5
20		Add for Three Stage					2.5
21	#	Rpr Tie Down				1.0	
22	#	Rpr Body Pulls				1.0	
23	#	Refn Clear Coat LT Roof Rail					0.5
24	R&I	Fuel door				Incl.	
25	Blnd	Fuel door					0.3
26	R&I	Filler pocket w/o ENERGI				0.5	
27	R&I	LT Wheelhouse liner w/o 2.7 liter turbo				Incl.	
28	R&I	LT Vent grille				0.1	
29	R&I	LT Qtr glass FORD bright/black				Incl.	
30	#	Repl Urethane Glass Kit		1	20.00 T		
31	R&I	LT Upper qtr trim ebony				Incl.	
32	R&I	LT Lower qtr trim w/o inflatable rear seat belts ceramic/cocoa				Incl.	
33	R&I	LT Rear trim ebony				Incl.	
34		REAR BODY & FLOOR					
35	R&I	Package tray w/4 speaker audio ebony				Incl.	
36	R&I	Rear sill plate				Incl.	
37	R&I	LT Side trim panel w/HYBRID				0.2	
38	R&I	Floor cover w/HYBRID				Incl.	
39		REAR LAMPS					
40	R&I	LT Tail lamp assy				Incl.	

Preliminary Estimate

Customer: JOHN, PAULA

2017 FORD Fusion Hybrid Platinum FWD 4D SED 4-2.0L Hybrid Sequential MPI RED

41	REAR BUMPER			
42		R&I	R&I bumper cover	Incl.
43	VEHICLE DIAGNOSTICS			
44	*	Rpr	Pre-repair scan	m 0.5 M
45	*	Rpr	Post-repair scan	m 0.5 M
46	#		**** ADD ONS ****	
47	#	Repl	Seam Sealer	1 10.00 T
48	#	Repl	Corrosion Protection	1 15.00 T
49	#	Repl	Flex Additive	1
50	#	Subl	Cover Car	1 5.00
51	#	Rpr	De-nib & Polish	0.3
52	#	Rpr	Mask For Prime/Block	0.2
53	#	Subl	Hazardous Waste Disposal	1 5.00 T
SUBTOTALS				921.83 25.5 8.4

ESTIMATE TOTALS

Category	Basis		Rate	Cost \$
Parts				731.88
Parts Discount	\$ 726.88		-5.0 %	-36.34
Body Labor	24.4 hrs	@	\$ 70.00 /hr	1,708.00
Paint Labor	8.4 hrs	@	\$ 70.00 /hr	588.00
Mechanical Labor	1.1 hrs	@	\$ 100.00 /hr	110.00
Paint Supplies	8.4 hrs	@	\$ 48.00 /hr	403.20
Miscellaneous				189.95
Subtotal				3,694.69
Sales Tax	\$ 3,694.69	@	5.5000 %	203.21
Grand Total				3,897.90
Deductible				500.00
CUSTOMER PAY				500.00
INSURANCE PAY				3,397.90

MyPriceLink Estimate ID / Quote ID:

1113857977514729472 / 127014509

MOTOR VEHICLE REPAIR PRACTICES ARE REGULATED BY CHAPTER ATCP 132, WIS. ADM. CODE, ADMINISTERED BY THE BUREAU OF CONSUMER PROTECTION, WISCONSIN DEPT. OF AGRICULTURE, TRADE AND CONSUMER PROTECTION, P.O. BOX 8911, MADISON, WISCONSIN 53708-8911.