

Gina M. Master
6285 Parkview Road
Greendale, WI 53129
414-234-7410
mknives4u@me.com

November 8, 2016

Attn: Clerks Office
West Allis Common Council
7525 West Greenfield Avenue
West Allis, WI 53214

RECEIVED
NOV 10 2016
CITY OF WEST ALLIS
CITY CLERK

To Whom it May Concern:

Last week Thursday, November 3, 2016, while driving my son home from school, I ran over debris in the road which was unavoidable. I was heading south thru the intersection of 76th and Oklahoma on 76th street in the left lane. There were cars in front of me and on the side. There was no way to avoid whatever was in the road and with the car in front of me, by the time I saw it, if I would've swerved, I would've hit the car next to me!

By the time I got to 76th and Layton my tire pressure sensor had gone off in my truck. I pulled over in the Barnes and Nobles parking lot and my son heard air rushing out from the back driver side tire. I immediately called the West Allis police department at 3:24pm to explain what had happened and what I should do to seek reimbursement if my tires were damaged. The officer gave me the number for the clerks office and I called at 3:29pm to get further information.


When we got home we found 12 large contractor staples in my tire as well as a large bolt. After putting on the spare on Friday, I took my truck to Girards Service in Franklin, WI to get a new tire and inspect the other tires to make sure there was no other damage. There was nothing in the other tires thank goodness!

I've enclosed the photos of the staples, tire, and my receipt from Girards. I hope I will be able to be reimbursed. I noticed yesterday on my way home with my son that there are cameras at that intersection. I wonder if you would be able to look back to catch the irresponsible person because I'm sure I was not the only one who got a flat tire that day!

Sincerely,



Gina Masters



GIRARDS SERVICE OF FRANKLIN

5517 W. Rawson Avenue

Franklin WI 53132

414-421-6202

11/4/2016 6:33 PM

page 1

Invoice #147021

MASTERS, CASH & GINA
6285 PARKVIEW RD
GREENDALE WI 53129

Day Phone : 414-423-7879
Cell Number : 414-791-7256 CASH

Vehicle : 2015 Ford Truck Explorer 3.5 L 213 CID V6 Duratec 35
VIN : 1FM5K8GT3FGC35373
Created : 11/4/2016 9:50:57 AM
Complete : 11/4/2016 5:10:03 PM
Invoiced : 11/4/2016 6:32:48 PM
Srv Writer: MGR

Tag/State : KNIVES / WI
Odometer In : 17851
Odometer Out : 17851

Qty	Code/Tech*	Reference	Description	Condition	Unit Price	Price
1			P255/50HR20 HANKOOK OPTIMO H426	New	\$216.39	\$216.39
1			TPMS SENSOR RUBBER VALVE STEM	New	\$6.99	\$6.99
0.7	HADA*		MOUNT & BAL TIRE ON ALUMINUM WHEEL W/TPMS 1		\$42.50	\$29.75
WHEELS TIGHTENED TO: TORQUE: 100 FT. LBS. HUBCAP/LUGNUT KEY: N/A TECH: HADA RECHECK: TONP						
DOT NUMBERS: 5MYP PDLH 2216						
1			WHEEL WEIGHT - CLIP ON	New	\$2.00	\$2.00
1			WHEEL WEIGHT - TAPE ON	New	\$1.50	\$1.50
1			TIRE DISPOSAL		\$3.50	\$3.50
Labor						\$29.75
Parts						\$226.88
Sublet/Misc.						\$0.00
Shop Supplies						\$0.00
Charges						\$3.50
Sales Tax						\$14.57
Tax @ \$260.13 * 5.6000%						\$14.57
VISA \$274.70						Paid \$274.70

Tech Certification #
HADA

I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express garagekeeper's lien is hereby acknowledged on above vehicle to secure the amount or repairs thereto. All Vehicles left over 48 hrs. after repairs are completed WILL INCUR A \$10.00 PER DAY STORAGE FEE. 12 Month or 12,000 Mile Warranty On Repairs.

Customer Signature _____