

Moving → new address is:
W147N7105 Woodland DR.
Menomonie Falls, WI 53051



CLAIMANT CONTACT INFORMATION

Name: Caley Hincak Phone: 414-254-3010
Address: 8520 W. Arthur Ave Email: hatchell.caley@gmail.com
West Allis, WI 53227

INSTRUCTIONS

Complete this form, print and sign it, and serve a hard copy upon the West Allis City Clerk. If you have questions about how to fill out this form, please contact a private attorney who can assist you.

NOTICE OF CLAIM

Date of incident: 11/08/2024 Time of day: 12:00
Location: 8520 W. Arthur Ave, West Allis, WI 53227

Describe the circumstances of your claim here. You may attach additional sheets or exhibits. Some helpful information may be the police report, pictures of the incident or damage, a diagram of the location, a list of injuries, a list of property damage, names and contact information for witnesses to the incident, and any other information relevant to the circumstances.

We had our lateral inspected as part of a home inspection by Milestone Plumbing, Inc. During the inspection Milestone Plumbing opened the main cleanout & ran a camera thru. From their report, the lateral was in really good condition & at about 60', where lateral drops into city sewer, a large root ball was stuck. Here is the sewer camera inspection video: <https://youtu.be/AiuOnnmt-Kc>. After this inspection, I then reached out to Alexander Weislak, the Principal Engineer of the City of West Allis, to let him know about our findings & how I would go about a reimbursement if we proceeded with getting the lateral cleaned. He said the root ball seen at the 2 min & 31 sec mark in the video appears to be coming from the connection from the sanitary lateral to the City's sewer under the roadway & that the City does not currently have access to the equipment required to clean this so we should advise our plumber to cut the rootball out of the lateral. And then once we receive the invoice for the work, to please submit a claim to the City for reimbursement. I believe Alexander prepped the City Engineer and Attorney's Office to expect a claim to be submitted for this work. Milestone came out to the house on 11/8 & completed the cleaning of the lateral. Their invoice is attached to the claim form.

Check one:

- I am seeking damages at this time (complete Claim Amount section below)
- I am submitting this notice without a claim for damages. This claim is not complete and will not be processed until I submit a claim for damages on a later date.

Signed: Caley Hincak Date: 11/14/24

CLAIM AMOUNT

To complete this claim, attach an itemized statement of damages sought. If any damages are for repair to property, include at least 2 estimates for repairs.

The total amount sought is: \$ 471.26

SAVE

PRINT



JOB INVOICE

"Quality Conscious, Customer Focused...Every Job, Every Day"
 www.milestoneplumbinginc.com
 11801 W Dearbourn Ave.
 Wauwatosa, WI 53226
 414-988-4565

PHONE: (414) 254-3010

DATE OF ORDER: 11/8/2024

DAY WORK NIGHT WORK WEEKEND

JOB NAME:

JOB LOCATION:

JOB DATE:

TO: Caley Hincak

8520 W Arthur Ave

West Allis WI 53227-2517

ARRIVAL TIME: 12:00 PM

DEPARTURE TIME: 2:15 PM

DESCRIPTION OF WORK

Jake - Jake Peterson - Nov 08, 2024 2:11 PM
 Was able to clear sewer lateral where it met city sewer. Pulled back a bunch of roots. Ran camera to confirm blockage was gone. Filled laundry tub numerous times to confirm operation.

QUANTITY:	MATERIAL:	UNIT:	AMOUNT:
	Sewer cleaning		\$445
HOURS:	TECHNICIAN:	RATE:	AMOUNT:
2.25	Jake	\$0	\$ 0.00
		\$0	\$ 0.00
		\$0	\$ 0.00

CHECK #:	CHECK AMOUNT:	CASH AMOUNT:
CARD AMOUNT:	\$471.26	AUTHORIZATION CODE: 867287864
X	<i>Caley Hincak</i>	DATE: 11/8/2024

TOTAL MATERIALS:	
TOTAL LABOR:	\$ 0.00
TRUCK CHARGE:	\$0
SUBTOTAL:	\$445.00
TAX:	\$26.26
GRAND TOTAL:	\$471.26

I hereby acknowledge the satisfactory completion of the above described work.

Thank You