To whom it may concern,


Enclosed is as follows:

- Claimant contact form
- 2. Description of claim
- 3. Accident report
- 4. Estimate from Brownell Quality Collision Center
- 5. Estimate from West Allis Auto Body
- 6. Picture of damage

Please let me know if anything else is needed.

My phone number is

Harlan Stephens





CLAIMANT CONTACT INFORMATION



Name: Hoclon Stephens Phone: Address: 8750 W. Not onal floe #204 Email: West Allis, WI 53227
INSTRUCTIONS Complete this form, print and sign it, and serve a hard copy upon the West Allis City Clerk. If you have questions about how to fill out this form, please contact a private attorney who can assist you. NOTICE OF CLAIM
Date of incident: 5-/3 2020 Time of day: Location: 8756 W. Not coel Ave
Describe the circumstances of your claim here. You may attach additional sheets or exhibits. Some helpful information may be the police report, pictures of the incident or damage, a diagram of the location, a list of injuries, a list of property damage, names and contact information for witnesses to the incident, and any other information relevant to the circumstances.
See paged
Check one:X I am seeking damages at this time (complete Claim Amount section below) I am submitting this notice without a claim for damages. This claim is not complete and will not be processed until I submit a claim for damages on a later date.
Signed: Date: 6-15-2020
CLAIM AMOUNT To complete this claim, attach an itemized statement of damages sought. If any damages are for repair to property, include at least 2 estimates for repairs. The total amount sought is: \$ 83389 or 856.67
SAVE

(2)

Case # 20-016413 for Harlan Stephens. My address is <u>8750 W</u>. National Ave. #204, West Allis, WI 53227. This happened on May 13th, possibly in the middle of the night. A fire truck hit my car in the parking lot where i reside. I was given a card for a patrol officer - Peter Borree, which said to call him regarding damage to his vehicle. I also had a phone call, when this happened, but I was sleeping. If pictures are needed, I will get them. I do have 2 estimates for the repair.

Please let me know if anything else is needed.

Harlan Stephens



Tuesday, June 9, 2020 11:30:00 ** For official use only **

West Allis Police Department



20.016413

Accident/PDO

Disposition Cleared/No Report

Unit **231**

Case #: 20-016413

05/13/20 22:0539

8750 W National Ave

Officer PB9897

CAD Comments

fire involved

Dispatched: 214, 231 Dispatched: 231 Call PreEmpt Unit#231 Dispatched: 231

Prime Unit Changed to - 231 Case created - 20-016413

Borree reports... On 05/13/20 at 10:05pm, a minor non-reportable PDO crash at Sunrise Apartments, 8750 W National Ave.

I was dispatched to Sunrise Apartments at the request of the West Allis Fire Department for a report of a minor crash involving a WAFD vehicle. I arrived at the scene and observed that WAFD Tower Truck 62, a 95 foot Fire Apparatus (Wisconsin registration 99756) driven by WAFD Equipment Operator Matthew Schmidz had made contact with a parked blue 2004 Ford Taurus four-door (Wisconsin registration 861KCW) while making a turn in the tight parking lot. The front left corner of the WAFD Apparatus and struck the left rear corner of the parked Ford causing scratches to the WAFD Apparatus and scrapes to the bumper cover of the Ford. I made contact with the owner of the Ford and advised him of this incident. Several photographs were taken of the scene and each vehicle. The photographs were uploaded to the WAPD DIMS system for safekeeping.

Stephens, Harlan H

Schmitz Matthew

Date: Estimate ID:

6/ 9/2020 11:39 AM 28652

Estimate Version:

BROWNELL QCC 68518866

Preliminary Profile ID: **Bwnell Quality Collision Center** Quote ID:

10414 W Greenfield Ave, West Allis, WI 53214 (414) 774-0610 Fax: (414) 774-0760 Email: BrownellQCC@aol.com Tax ID: 39-1758646

Damage Assessed By: RYAN KAEL Classification: Field

Type of Loss: Deductible: 0.00 Collision Claim Number:

Owner: HARLON STIHENS Telephone:

Cell Phone:

Mitchell Service: 912626

Description: 2004 For Taurus SE Body Style: VIN

OEM/ALT

Color

Color:—BLUE
Options: PASSENGER AIRBAG, POWER LOCK, POWER WINDOW, POWER STEERING, REAR WINDOW DEFOGGER
AIR COMPITION ORDING CONTROL THE STEERING COLUMN AM/EM STEREO DRIVER AIRBAG ANSOENGER AIRBAG, PUVVER LUCK, PUVVER VVIINDUVV, PUVVER STEERING, REAR VVIINDUVV DE AIR CONDITION, CRUISE CONTROL, TILT STEERING COLUMN, AM/FM STEREO, DRIVER AIRBAG

Lin Ite 1 2 3 4 5 6	204882 BDY REMOVE/REPLACE AUTO REF AUTO REF AUTO REF AUTO REF AUTO AUTO AUTO AUTO ADD'L OPR AUTO ADD'L COST	Line Item Description L Rear Combination Lamp Rear Bumper Cover Rear Bumper Cover Clear Coat		Dollar Labor Amount Units
	ADD'L COST	Paint/Materials Hazardous Waste Disposal	artr Certified	45.00 0.3 250.00 1.4 C 2.9 1.2 164.00 * 5.00 *

** QRP Certified - Quality Replacement Parts - Certified ** QUAL REPL PART - Quality Replacement Parts

C - Included in Clear Coat Calc

VIVERSAL AUTO (KSI) 14A W. ROOSEVELT RD. 30644

3) 921-4444 (800) 244-2639

** 216639AN ** 216652AQ 45.00

250.00 MATE RECALL NUMBER: 06/09/2020 11:37:38 28652

OEM: MAY_20_V MAPP:MAY_20_V

re Version:

7.1.238

Copyright (C) 1994 - 2020 Mitchell International All Rights Reserved

of

3

WEST ALLIS AUTO BODY 8808 W. NATIONAL AVE. WEST ALLIS, WISC 53227 PHONE: 414-327-4140 FAX: 414-327-0033

*** PRELIMINARY ESTIMATE ***

06/09/2020 11:24 AM

Owner

Owner: HARLAN STEPHENS

Inspection

Inspection Date: 06/09/2020 11:24 AM

Appraiser Name: Glenn

Inspection Type:

Appraiser License #:

Repairer

Repairer: WEST ALLIS AUTO BODY

Address: 8808 W NATIONAL AVE

City State Zip: West Allis, WI 53227

Email: waab6@aol.com

Contact: Glenn

Work/Day: (414)327-4140 Home/Evening: (414)327-4143

FAX: (414)327-0033

Target Complete Date/Time:

Days To Repair: 2

Vehicle

OEM Part Price Quote ID: ****

2005 Ford Taurus SE 4 DR Sedan

6cyl Gasoline 3.0 4 Speed Automatic

Lic Expire:

Veh Insp#:

Condition:

Ext. Refinish: Two-Stage

VIN: Unreadable VIN

Mileage Type: Actual

Code: P3533C

Int. Refinish: Two-Stage

Options

AM/FM Stereo Tape Center Console

Dual Airbags

Intermittent Wipers
Power Brakes

Power Steering

Rear Window Defroster

Steel Wheels Tilt Steering Wheel Velour/Cloth Seats Air Conditioning Compact Spare Tire

Floor Mats

Keyless Entry System Power Door Locks Power Windows

Rem Trunk-L/Gate Release

Tachometer Tinted Glass Bodyside Moldings Cruise Control

Halogen Headlights Lighted Entry System

Power Mirrors Rear Bench Seat

Split Front Bench Seat Theft Deterrent System

Trip Computer

Damages

Line Op Guide MC Description

MFR.Part No.

Price

ADJ% B%

Hours

R

06/09/2020 11:25 AM

Page 1 of 3

						-	-	
Rear Bumper 1 EP 566 2 L 566	Cover,Rear 13 Cover,Rear	Bumper Bumper	Replace PX Refinish 2.6 Surf 0.6 Two 0.5 Two	face -stage setu	\$256.67 p		1.6 3.7	SM RF
Rear Body, Lamps And	Floor Pan Taillamp As	sembly LT	Replace PX	N	\$51.00		0.5	SM
Manual Entries 4 EC 4 Items	FLEX ADDI	TIVE	Replace Ec	onomy	\$5.00*			RF
	MC	Message						
	13	INCLUDES	0.6 HOURS	FIRST PAN	EL TWO-STAGE	ALLOWANCE		
Estimate Total & Entrie	3S	T William Commence Commence	**************************************	A C A	and the second s	10000 00 1 10000000 000000000000000000	W WWW W W W	
Other Parts Paint & Materials Parts & Material Total Tax on Parts & Material		3.1	7 Hours @	\$38.00	5.600%	\$312.67 \$140.60	\$453.27 \$25.38	
Labor	Rate	Replace Hrs	Repair Hrs	Total Hrs	;			
Sheet Metal (SM) Mech/Elec (ME) Frame (FR)	\$58.00 \$65.00 \$58.00	2.1		2.1	\$121.80			
Refinish (RF)	\$58.00	3.7		3.7	\$214.60			
Labor Total Tax on Labor Gross Total Net Total		(0 5.600%	5.8	Hours \$18.84	\$336.40 \$833.89 \$833.89		

Alternate Parts Y/02/02/02/00/00 CUM 02/02/02/00/00 Zip Code: 53227 Audatex Host OEM Part Prices DT 06/09/2020 11:24 AM EstimateID 699656409423290368 QuoteID **** Rate Name Default

Audatex Estimating 8.0.818 ES 06/09/2020 11:25 AM REL 8.0.818 DT 04/01/2020 © 2020 Audatex North America, Inc.

1.1 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.

Op Codes

* = User-Entered Value
NG = Replace NAGS
UE = Replace OE Surplus
EU = Replace Recycled
UM = Replace Reman/Rebuilt
UC = Replace Reconditioned
N = Additional Labor
IT = Partial Repair

EC = Replace Economy ET = Partial Replace Labor TE = Partial Replace Price L = Refinish TT = Two-Tone BR = Blend Refinish CG = Chipquard AA = Appearance Allowance

^ = Labor Matches System Assigned Rates E = Replace OEM OE = Replace PXN OE Srpls EP = Replace PXN PM = Replace PXN Reman/Rebit PC = Replace PXN Reconditioned SB = Sublet Repair I = Repair RI = R & I Assembly RP = Related Prior Damage



P = Check

Audatex

This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

© 2020 Audatex North America, Inc. AUDATEX is a trademark owned by Audatex North America, Inc. All rights reserved.

