

CITY OF WEST ALLIS
5 FEB 26 PM 13



CLAIMANT CONTACT INFORMATION

Name: María Espinoza
Address: 8227 W. Becker St
West Allis, WI, 53215

Phone: 747-250-2904
Email: F.Espinoza251@gmail.com

INSTRUCTIONS

Complete this form, print and sign it, and serve a hard copy upon the West Allis City Clerk. If you have questions about how to fill out this form, please contact a private attorney who can assist you.

NOTICE OF CLAIM

Date of incident: 12-14-25 Time of day: 7:21 PM
Location: 8227 W. Becker St West Allis, WI, 53215

Describe the circumstances of your claim here. You may attach additional sheets or exhibits. Some helpful information may be the police report, pictures of the incident or damage, a diagram of the location, a list of injuries, a list of property damage, names and contact information for witnesses to the incident, and any other information relevant to the circumstances.

I had two vehicles get hit by a city plow truck on the date above (12-14-25) Both vehicles were on the same side street. I have video of the incident as well. They were parked when the plow truck struck the vehicles. Two license plate numbers of both vehicles that were struck are # Bcc-1875 (Jeep compass 2019) and # ASU-4170 (Hummer H3 2006). Hummer was struck on rear left side (corner) and the Jeep was hit on the side view mirror

Check one:

- I am seeking damages at this time (complete Claim Amount section below)
- I am submitting this notice without a claim for damages. This claim is not complete and will not be processed until I submit a claim for damages on a later date.

Signed: María A Espinoza

Date: _____

CLAIM AMOUNT

To complete this claim, attach an itemized statement of damages sought. If any damages are for repair to property, include at least 2 estimates for repairs.

The total amount sought is: \$ 7,991.99

SAVE

PRINT



**Gerber Collision & Glass -
Milwaukee/13th St.**

Highly Wreck - ommended!
3940 S 13th St, Milwaukee, WI 53221
Phone: (414) 481-9449

Workfile ID: 02b66318
Federal ID: 51-0394062
State ID: N/A
Federal EPA: N/A
State EPA: N/A

Preliminary Estimate

Customer: ESPINOZA, MARIA

Written By: Orlando Arce

Insured: ESPINOZA, MARIA Policy #: Claim #:
Type of Loss: Date of Loss: Days to Repair: 0
Point of Impact: 10 Left Front Pillar (Left Side)

Owner: ESPINOZA, MARIA
8227 W BECHER ST
WEST ALLIS, WI 53219
(747) 250-2904 Cell

Inspection Location: Gerber Collision & Glass - Milwaukee/13th St.
3940 S 13th St
Milwaukee, WI 53221
Repair Facility
(414) 481-9449 Business

Insurance Company: SELF PAY

VEHICLE

2019 JEEP Compass Trailhawk 4WD 4D UTV 4-2.4L Gasoline Sequential MPI RED

VIN: 3C4NJDD89KT650201 Interior Color: Mileage In: 123,321 Vehicle Out:
License: BAC-1875 Exterior Color: RED Mileage Out:
State: WI Production Date: 10/2018 Condition: Job #:

TRANSMISSION

Automatic Transmission
4 Wheel Drive

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Heated Mirrors

DECOR

Dual Mirrors
Privacy Glass
Console/Storage
Overhead Console

CONVENIENCE

Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Message Center
Steering Wheel Touch Controls
Rear Window Wiper
Telescopic Wheel

Climate Control
Backup Camera

RADIO

AM Radio

FM Radio

Stereo
Search/Seek
Auxiliary Audio Connection
Satellite Radio

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Traction Control
Stability Control
Front Side Impact Air Bags
Head/Curtain Air Bags
Hands Free Device

SEATS

Cloth Seats
Bucket Seats
Reclining/Lounge Seats

WHEELS

Aluminum/Alloy Wheels

PAINT

Clear Coat Paint

OTHER

Fog Lamps
Rear Spoiler
Signal Integrated Mirrors

Get live updates at www.carwise.com/e/5fs3g9

Preliminary Estimate

Customer: ESPINOZA, MARIA

2019 JEEP Compass Trailhawk 4WD 4D UTV 4-2.4L Gasoline Sequential MPI RED

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DR3WC17, CCC Data Date 12/15/2025, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2024 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. CFC=Carbon Fiber. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. STS=Stainless Steel. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Solutions Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

Preliminary Estimate

Customer: ESPINOZA, MARIA

2019 JEEP Compass Trailhawk 4WD 4D UTV 4-2.4L Gasoline Sequential MPI RED

RECALL INFO

2019 JEEP Compass Trailhawk 4WD 4D UTV 4-2.4L Gasoline Sequential MPI RED

VIN: 3C4NJDDDB9KT650201	Interior Color:	Mileage In: 123,321	Vehicle Out:
License: BAC-1875	Exterior Color: RED	Mileage Out:	
State: WI	Production Date: 10/2018	Condition:	Job #:

The National Highway Transportation and Safety Administration (NHTSA) has issued 1 safety-related recall notice(s) that may apply to the selected vehicle.

NHTSA ID: 18V523000

Issued: Aug 8, 18

Number of Vehicles: 00154335

SERVICE BRAKES, HYDRAULIC:FOUNDATION COMPONENTS:DISC:CALIPER Chrysler (FCA US LLC) is recalling certain 2018-2019 Dodge Grand Caravan and Jeep Compass, 2018 Dodge Journey, and 2019 Jeep Cherokee vehicles. The rear brake caliper pistons on these vehicles may have an insufficient coating causing gas pockets to form, potentially reducing rear brake performance. A reduction of braking performance can increase the risk of a crash. Chrysler will notify owners, and dealers will bleed the vehicle's brake system, free of charge. The recall began September 29, 2018. Owners may contact Chrysler customer service at 1-800-853-1403. Chrysler's number for this recall is U86.



CARSTAR GREENFIELD AUTO BODY

Workfile ID: 94f96b90
Federal ID: 26-4390418

Where we meet by accident!

mariusz@carstar.us

4739 S 27TH ST, GREENFIELD, WI 53221

Phone: (414) 282-8580

FAX: (414) 282-8533

Preliminary Estimate

Customer: Espinoza, Maria

Written By: Mariusz Stanisz

Insured: Espinoza, Maria
Type of Loss:
Point of Impact:

Policy #:
Date of Loss:

Claim #:
Days to Repair: 0

Owner:
Espinoza, Maria
8200 W BECHER ST
WEST ALLIS, WI 53219
(747) 250-2904 Cell

Inspection Location:
CARSTAR GREENFIELD AUTO BODY
4739 S 27TH ST
GREENFIELD, WI 53221
Repair Facility
(414) 282-8580 Business

Insurance Company:
CUSTOMER PAY

VEHICLE

2006 HUMM H3 SUV 4WD 4D UTV 5-3.5L Gasoline MFI WHITE

VIN: 5GTDN136X68288007	Interior Color:	Mileage In: 189,731	Vehicle Out:
License: ASU4170	Exterior Color: WHITE	Mileage Out:	
State: WI	Production Date:	Condition:	Job #:

TRANSMISSION

Overdrive
5 Speed Transmission
4 Wheel Drive

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors

DECOR

Dual Mirrors
Privacy Glass

Console/Storage

CONVENIENCE

Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Alarm
Message Center
Rear Window Wiper
Climate Control

RADIO

AM Radio

FM Radio

Stereo

Search/Seek

CD Player

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Traction Control
Communications System
Hands Free Device

ROOF

Luggage/Roof Rack

SEATS

Cloth Seats
Bucket Seats
Reclining/Lounge Seats

WHEELS

Aluminum/Alloy Wheels

PAINT

Clear Coat Paint

OTHER

Fog Lamps

Get live updates at www.carwise.com/e/5hfr8m

Preliminary Estimate

Customer: Espinoza, Maria

2006 HUMM H3 SUV 4WD 4D UTV 5-3.5L Gasoline MFI WHITE

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DE1GS06, CCC Data Date 02/02/2026, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2024 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. CFC=Carbon Fiber. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. STS=Stainless Steel. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Solutions Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

Preliminary Estimate

Customer: Espinoza, Maria

2006 HUMM H3 SUV 4WD 4D UTV 5-3.5L Gasoline MFI WHITE

RECALL INFO

2006 HUMM H3 SUV 4WD 4D UTV 5-3.5L Gasoline MFI WHITE

VIN: 5GTDN136X68288007	Interior Color:	Mileage In: 189,731	Vehicle Out:
License: ASU4170	Exterior Color: WHITE	Mileage Out:	
State: WI	Production Date:	Condition:	Job #:

The National Highway Transportation and Safety Administration (NHTSA) has issued 1 safety-related recall notice(s) that may apply to the selected vehicle.

NHTSA ID: 05V552000

Issued: Dec 12, 05

Number of Vehicles: 00032068

EQUIPMENT:OTHER:LABELS CERTAIN TRUCKS AND SPORT UTILITY VEHICLES FAIL TO CONFORM TO THE REQUIREMENTS OF FEDERAL MOTOR VEHICLE SAFETY STANDARD NO. 110, "TIRE SELECTION AND RIMS". THESE VEHICLES WERE SHIPPED WITH TIRE AND LOADING INFORMATION LABELS LISTING AN INACCCURATE VEHICLE CAPACITY WEIGHT. A MISPRINTED LABEL COULD LEAD TO IMPROPER VEHICLE LOADING SPECIFICATIONS OR TIRE INFLATION WHICH COULD RESULT IN A TIRE FAILURE, INCREASING THE RISK OF A CRASH. OWNERS WILL BE PROVIDED WITH CORRECTED LABELS AND INSTALLATION INSTRUCTIONS. AT THE CUSTOMER'S OPTION, A DEALER CAN INSTALL THE LABEL FOR THEM. THE MANUFACTURER HAS NOT YET PROVIDED AN OWNER NOTIFICATION SCHEDULE. OWNERS SHOULD CONTACT BUICK AT 1-866-608-8080, CADILLAC AT 1-866-982-2339, CHEVROLET AT 1-800-630-2438, GMC AT 1-866-996-9463, HUMMER AT 1-800-732-5493, PONTIAC AT 1-800-620-7668, SATURN AT 1-800-972-8876, OR ISUZU AT 1-800-255-6727.



CARSTAR GREENFIELD AUTO BODY

Workfile ID: dfd7abde
Federal ID: 26-4390418

Where we meet by accident!
mariusz@carstar.us
4739 S 27TH ST, GREENFIELD, WI 53221
Phone: (414) 282-8580
FAX: (414) 282-8533

Preliminary Estimate

Customer: Espinosa, Maria

Written By: Mariusz Stanisz

Insured: Espinosa, Maria
Type of Loss:
Point of Impact:

Policy #:
Date of Loss:

Claim #:
Days to Repair: 0

Owner:

Espinosa, Maria
8200 W BECHER ST
WEST ALLIS, WI 53219
(747) 250-2904 Cell

Inspection Location:

CARSTAR GREENFIELD AUTO BODY
4739 S 27TH ST
GREENFIELD, WI 53221
Repair Facility
(414) 282-8580 Business

Insurance Company:

CUSTOMER PAY

VEHICLE

2019 JEEP Compass Trailhawk 4WD 4D UTV 4-2.4L Gasoline Sequential MPI

VIN: 3C4NJDD9KT650201
License:
State: WI

Interior Color:
Exterior Color:
Production Date:

Mileage In:
Mileage Out:
Condition:

Vehicle Out:
Job #:

TRANSMISSION

Automatic Transmission
4 Wheel Drive

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Heated Mirrors

DECOR

Dual Mirrors
Privacy Glass
Console/Storage
Overhead Console

CONVENIENCE

Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Message Center
Steering Wheel Touch Controls
Rear Window Wiper
Telescopic Wheel
Climate Control
Backup Camera

RADIO

AM Radio

FM Radio

Stereo
Search/Seek
Auxiliary Audio Connection
Satellite Radio

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Traction Control
Stability Control
Front Side Impact Air Bags
Head/Curtain Air Bags
Hands Free Device

SEATS

Cloth Seats
Bucket Seats
Reclining/Lounge Seats

WHEELS

Aluminum/Alloy Wheels

PAINT

Clear Coat Paint

OTHER

Fog Lamps
Rear Spoiler
Signal Integrated Mirrors

Get live updates at www.carwise.com/e/5h7eKK

Preliminary Estimate

Customer: Espinosa, Maria

2019 JEEP Compass Trailhawk 4WD 4D UTV 4-2.4L Gasoline Sequential MPI

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		FRONT DOOR					
2	Repl	LT Mirror cover w/o body color neutral gray	6LL31XS9AA	1	62.65	Incl.	
3	Repl	LT Mirror w/signal lamp, w/o chrome accent w/o blind spot	68365141AA	1	435.00	0.5	
4	R&I	LT R&I trim panel				0.5	
5	#	HAZARDOUS WASTE DISPOSAL		1	3.00		
SUBTOTALS					500.65	1.0	0.0

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			500.65
Body Labor	1.0 hrs @	\$ 78.00 /hr	78.00
Body Supplies	1.0 hrs @	\$ 7.00 /hr	7.00
Subtotal			585.65
Sales Tax	\$ 585.65 @	5.9000 %	34.55
Grand Total			620.20
Deductible			0.00
CUSTOMER PAY			0.00
INSURANCE PAY			620.20

MOTOR VEHICLE REPAIR PRACTICES ARE REGULATED BY CHAPTER ATCP 132, WIS. ADM. CODE, ADMINISTERED BY THE BUREAU OF CONSUMER PROTECTION, WISCONSIN DEPT. OF AGRICULTURE, TRADE AND CONSUMER PROTECTION, P.O. BOX 8911, MADISON, WISCONSIN 53708-8911.

Preliminary Estimate

Customer: Espinosa, Maria

2019 JEEP Compass Trailhawk 4WD 4D UTV 4-2.4L Gasoline Sequential MPI

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DR3WC17, CCC Data Date 01/16/2026, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2024 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. CFC=Carbon Fiber. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. STS=Stainless Steel. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Solutions Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

Preliminary Estimate

Customer: Espinosa, Maria

2019 JEEP Compass Trailhawk 4WD 4D UTV 4-2.4L Gasoline Sequential MPI

RECALL INFO

2019 JEEP Compass Trailhawk 4WD 4D UTV 4-2.4L Gasoline Sequential MPI

VIN: 3C4NJDD9KT650201	Interior Color:	Mileage In:	Vehicle Out:
License:	Exterior Color:	Mileage Out:	
State: WI	Production Date:	Condition:	Job #:

The National Highway Transportation and Safety Administration (NHTSA) has issued 1 safety-related recall notice(s) that may apply to the selected vehicle.

NHTSA ID: 18V523000 **Issued: Aug 8, 18** **Number of Vehicles: 00154335**

SERVICE BRAKES, HYDRAULIC:FOUNDATION COMPONENTS:DISC:CALIPER Chrysler (FCA US LLC) is recalling certain 2018-2019 Dodge Grand Caravan and Jeep Compass, 2018 Dodge Journey, and 2019 Jeep Cherokee vehicles. The rear brake caliper pistons on these vehicles may have an insufficient coating causing gas pockets to form, potentially reducing rear brake performance. A reduction of braking performance can increase the risk of a crash. Chrysler will notify owners, and dealers will bleed the vehicle's brake system, free of charge. The recall began September 29, 2018. Owners may contact Chrysler customer service at 1-800-853-1403. Chrysler's number for this recall is U86.



**Gerber Collision & Glass -
Milwaukee/13th St.**

Highly Wreck - ommended!
3940 S 13th St, Milwaukee, WI 53221
Phone: (414) 481-9449

Workfile ID: 3c3b3653
Federal ID: 51-0394062
State ID: N/A
Federal EPA: N/A
State EPA: N/A

Preliminary Estimate

Customer: ESPINOZA, MARIA

Written By: Orlando Arce

Insured: ESPINOZA, MARIA
Type of Loss:
Point of Impact: 07 Left Rear

Policy #:
Date of Loss:

Claim #:
Days to Repair: 0

Owner:
ESPINOZA, MARIA
8227 W BECHER ST
WEST ALLIS, WI 53215
(747) 250-2904 Cell

Inspection Location:
Gerber Collision & Glass - Milwaukee/13th St.
3940 S 13th St
Milwaukee, WI 53221
Repair Facility
(414) 481-9449 Business

Insurance Company:
SELF PAY

VEHICLE

2006 HUMM H3 SUV 4WD 4D UTV 5-3.5L Gasoline MFI WHITE

VIN: 5GTDN136X68288007 Interior Color: Mileage In: 189,272 Vehicle Out:
License: ASU-4170 Exterior Color: WHITE Mileage Out:
State: WI Production Date: 4/2006 Condition: Job #:

TRANSMISSION

Overdrive
5 Speed Transmission
4 Wheel Drive

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors

DECOR

Dual Mirrors
Privacy Glass

Console/Storage

CONVENIENCE

Air Conditioning
Intermittent Wipers
Tilt Wheel

Cruise Control
Rear Defogger

Keyless Entry
Alarm

Message Center

Rear Window Wiper

Climate Control

RADIO

AM Radio

FM Radio

Stereo

Search/Seek

CD Player

SAFETY

Drivers Side Air Bag

Passenger Air Bag

Anti-Lock Brakes (4)

4 Wheel Disc Brakes

Traction Control

Communications System

Hands Free Device

ROOF

Luggage/Roof Rack

SEATS

Cloth Seats
Bucket Seats
Reclining/Lounge Seats

WHEELS

Aluminum/Alloy Wheels

PAINT

Clear Coat Paint

OTHER

Fog Lamps

Get live updates at www.carwise.com/e/5frRye

Preliminary Estimate

Customer: ESPINOZA, MARIA

2006 HUMM H3 SUV 4WD 4D UTV 5-3.5L Gasoline MFI WHITE

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	#	**ADDITIONAL DAMAGE MAY BE PRESENT**		1			
2	GRILLE						
3	R&I	Grille assy prime				0.4	
4	FENDER						
5	R&I	LT R&I fender assy				2.0	
6	*	Rpr LT Fender				<u>1.5</u>	1.6
7		Add for Clear Coat					0.6
8	R&I	LT Flare				1.2	
9	R&I	LT Mud guard w/wheel opng mldg				0.2	
10	R&I	LT Inlet cover primed				0.1	
11	WINDSHIELD						
12	Repl	LT Outer molding	15909801	1	234.87	0.3	
13	PILLARS, ROCKER & FLOOR						
14	Sect	LT Uniside panel quarter panel	20801598	1	328.20 s	18.0	3.4
15		Overlap Major Non-Adj. Panel					-0.2
16		Add for Clear Coat					0.6
17	FRONT DOOR						
18	*	Rpr LT Door shell				<u>1.5</u>	2.1
19		Overlap Major Adj. Panel					-0.4
20		Add for Clear Coat					0.3
21	R&I	LT Belt w'strip				0.2	
22	R&I	LT Handle, outside w/o chrome				0.4	
23	Repl	LT Nameplate "H3"	15094459	1	131.23	0.2	
24	R&I	LT Mirror assy w/o chrome				0.3	
25	R&I	LT Weatherstrip				0.3	
26	*	R&I LT Run channel				<u>0.3</u>	
27	R&I	LT R&I trim panel				0.6	
28	R&I	LT Water deflector				0.1	
29	REAR DOOR						
30	R&I	LT R&I door assy				1.3	
31	*	Blnd LT Door shell					<u>1.1</u>
32	R&I	LT Belt w'strip				0.2	
33	R&I	LT Flare				0.3	
34	R&I	LT Fixed glass GM w/privacy				1.3	
35	R&I	LT Weatherstrip				0.2	
36	R&I	LT Handle, outside w/o chrome				0.4	
37	R&I	LT R&I trim panel				0.5	
38	R&I	LT Water deflector				0.1	
39	QUARTER PANEL						
40	R&I	LT Wheelhouse liner				0.4	
41	R&I	LT Flare				1.5	
42	R&I	Fuel pocket				0.2	

Preliminary Estimate

Customer: ESPINOZA, MARIA

2006 HUMM H3 SUV 4WD 4D UTV 5-3.5L Gasoline MFI WHITE

43	R&I	LT Corner cover				0.2	
44	R&I	LT Qtr glass GM w/privacy				1.5	
45	R&I	LT Lower qtr trim w/o premium speaker				Incl.	
46	R&I	LT Window molding w/o head air bag				Incl.	
47	Repl	LT Bracket	15853261	1	57.85		
		Note: DISCONTINUED					
48	Repl	LT Upper panel	15843104	1	189.22	3.0	0.8
		Note: DISCONTINUED					
49	REAR BODY & FLOOR						
50	R&I	Floor cover				0.2	
51	Repl	LT Applique panel	20907428	1	224.53	0.3	
		Note: DISCONTINUED					
52	R&I	Scuff plate				0.3	
53	REAR LAMPS						
54	Repl	LT Tail lamp assy	19259479	1	201.90	0.4	
55	REAR BUMPER						
56	R&I	R&I bumper assy				1.2	
57	VEHICLE DIAGNOSTICS						
58	*	Rpr	Pre-repair scan			m	0.5 M
59	*	Rpr	Post-repair scan			m	0.5 M
60	#	Subl	Hazardous Waste	1	10.00	T	
61	#		Cover Car	1	15.00	T	
62	#	Repl	Corrosion Protection	1	15.00		
63	#	Rpr	Set up - Floor				1.5
64	#	Rpr	Body Pull				
65	#	Repl	Clips, Fasteners, Retainers	1	35.00	T	
66	#	Repl	Seam Sealer / Caulk	1	25.00	T	
67	#	Repl	Cavity Wax	2	13.90	T	0.5
SUBTOTALS					1,481.70	44.1	9.9

Preliminary Estimate

Customer: ESPINOZA, MARIA

2006 HUMM H3 SUV 4WD 4D UTV 5-3.5L Gasoline MFI WHITE

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			1,382.80
Body Labor	43.1 hrs @	\$ 80.00 /hr	3,448.00
Paint Labor	9.9 hrs @	\$ 80.00 /hr	792.00
Mechanical Labor	1.0 hrs @	\$ 130.00 /hr	130.00
Paint Supplies	9.9 hrs @	\$ 60.00 /hr	594.00
Body Supplies	28.2 hrs @	\$ 10.00 /hr	282.00
Miscellaneous			98.90
Subtotal			6,727.70
Sales Tax	\$ 6,727.70 @	7.9000 %	531.49
Grand Total			7,259.19

MyPriceLink Estimate ID / Quote ID:

1432736115663577088 /

MOTOR VEHICLE REPAIR PRACTICES ARE REGULATED BY CHAPTER ATCP 132, WIS. ADM. CODE, ADMINISTERED BY THE BUREAU OF CONSUMER PROTECTION, WISCONSIN DEPT. OF AGRICULTURE, TRADE AND CONSUMER PROTECTION, P.O. BOX 8911, MADISON, WISCONSIN 53708-8911.

Preliminary Estimate

Customer: ESPINOZA, MARIA

2006 HUMM H3 SUV 4WD 4D UTV 5-3.5L Gasoline MFI WHITE

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DE1GS06, CCC Data Date 12/15/2025, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2024 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. CFC=Carbon Fiber. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. STS=Stainless Steel. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Solutions Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

Preliminary Estimate

Customer: **ESPINOZA, MARIA**

2006 HUMM H3 SUV 4WD 4D UTV 5-3.5L Gasoline MFI WHITE

PARTS SUPPLIER LIST

Line	Supplier	Description	Price
12	Kunes Buick GMC of Greenfield Inc. 3615 S.108th Street Greenfield, WI 53228	#15909801 LT Outer molding Quote: 18748452180 Expires: 01/22/26	\$ 234.87
14	Kunes Buick GMC of Greenfield Inc. 3615 S.108th Street Greenfield, WI 53228	#20801598 LT Uniside panel quarter panel Quote: 18748852560 Expires: 01/22/26	\$ 328.20
23	Kunes Buick GMC of Greenfield Inc. 3615 S.108th Street Greenfield, WI 53228	#15094459 LT Nameplate "H3" Quote: 18749051921 Expires: 01/22/26	\$ 131.23
47	Kunes Buick GMC of Greenfield Inc. 3615 S.108th Street Greenfield, WI 53228	#15853261 LT Bracket Quote: 18746752508 Expires: 01/22/26	\$ 57.85
48	Kunes Buick GMC of Greenfield Inc. 3615 S.108th Street Greenfield, WI 53228	#15843104 LT Upper panel Quote: 18750152035 Expires: 01/22/26	\$ 189.22
51	Kunes Buick GMC of Greenfield Inc. 3615 S.108th Street Greenfield, WI 53228	#20907428 LT Applique panel Quote: 18748452842 Expires: 01/22/26	\$ 224.53
54	Kunes Buick GMC of Greenfield Inc. 3615 S.108th Street Greenfield, WI 53228	#19259479 LT Tail lamp assy Quote: 18750451921 Expires: 01/22/26	\$ 201.90

Preliminary Estimate

Customer: ESPINOZA, MARIA

2006 HUMM H3 SUV 4WD 4D UTV 5-3.5L Gasoline MFI WHITE

RECALL INFO

2006 HUMM H3 SUV 4WD 4D UTV 5-3.5L Gasoline MFI WHITE

VIN: 5GTDN136X68288007	Interior Color:	Mileage In: 189,272	Vehicle Out:
License: ASU-4170	Exterior Color: WHITE	Mileage Out:	
State: WI	Production Date: 4/2006	Condition:	Job #:

The National Highway Transportation and Safety Administration (NHTSA) has issued 1 safety-related recall notice(s) that may apply to the selected vehicle.

NHTSA ID: 05V552000

Issued: Dec 12, 05

Number of Vehicles: 00032068

EQUIPMENT:OTHER:LABELS CERTAIN TRUCKS AND SPORT UTILITY VEHICLES FAIL TO CONFORM TO THE REQUIREMENTS OF FEDERAL MOTOR VEHICLE SAFETY STANDARD NO. 110, "TIRE SELECTION AND RIMS". THESE VEHICLES WERE SHIPPED WITH TIRE AND LOADING INFORMATION LABELS LISTING AN INACCCURATE VEHICLE CAPACITY WEIGHT. A MISPRINTED LABEL COULD LEAD TO IMPROPER VEHICLE LOADING SPECIFICATIONS OR TIRE INFLATION WHICH COULD RESULT IN A TIRE FAILURE, INCREASING THE RISK OF A CRASH. OWNERS WILL BE PROVIDED WITH CORRECTED LABELS AND INSTALLATION INSTRUCTIONS. AT THE CUSTOMER'S OPTION, A DEALER CAN INSTALL THE LABEL FOR THEM. THE MANUFACTURER HAS NOT YET PROVIDED AN OWNER NOTIFICATION SCHEDULE. OWNERS SHOULD CONTACT BUICK AT 1-866-608-8080, CADILLAC AT 1-866-982-2339, CHEVROLET AT 1-800-630-2438, GMC AT 1-866-996-9463, HUMMER AT 1-800-732-5493, PONTIAC AT 1-800-620-7668, SATURN AT 1-800-972-8876, OR ISUZU AT 1-800-255-6727.

Office DEPOT OfficeMax[®]

MILWAUKEE - (414) 383-8777
02/05/2026 1:38 PM



VPVTQAAUQXQ44CBCC

SALE 6359-24-7623-1111-24.8.1
901337 SS B&W Ltr Ema
7 @ 0.22 1.54

You Pay 1.54SS

Subtotal: 1.54
Local Sales and Use T 0.12
Total: 1.66
Visa 0680: 1.66

AUTH CODE 034343
TDS Chip Read
AID A000000031010 VISA DEBIT
CVS No Signature Required

Shop online at www.officedepot.com