

To whom it My Concern.

ON the Date 07-18-14.

My Car were Park at my
Place of employment.
(2095 S 116th Street West Allis, WI)
When I arrive back on my work
site, I notice that the City
employee were spraying Water
on my Car.

They said that white paint
from the work truck spray all
over my Car ~~and~~ two other
Cars. Myself + another Guy
said it was OK, for them to
wash it OK.

My Car were Damage in the
Process:

ELGIE L GRANT
7133 W Congress ST
Milwaukee WI 53218

DON'S AUTO BODY
2201 SOUTH 116TH STREET
WEST ALLIS, WI 53227-1007
PHONE: 414-541-5155 FAX: 414-541-4343

RECEIVED

SEP 22 2014

CITY OF WEST ALLIS
CITY CLERK

CD LOG NO 8365-1 DATE 07/22/14

SHOP: DON'S AUTO BODY INSP DATE: 07/22/14
CITY STATE: WEST ALLIS, WI PHONE 1: (414) 541-5155
ZIP: 53227-1007 PHONE 2: (414) 541-2344
FAX: (414) 541-4343

OWNER: GRANT

POINT OF IMPACT: 0

LIC#: STATE: VIN:
BODY COLOR: MILEAGE:
CONDITION: ACCTNG CTL#:

*=USER-ENTERED VALUE E=REPLACE OEM NG=REPLACE NAGS
EC=REPLACE ECONOMY UE=REPLACE OE SURPLUS UC=RECONDITIONED PRT
UM=REMAN/REBUILT PRT EU=REPLACE SALVAGE EP=REPLACE PXN
OE=REPLACE PXN OE SRPLS PC=PXN RECONDITIONED PM=PXN REMAN/REBUILT
TE=PARTL REPL PRICE ET=PARTL REPL LABOR IT=PARTIAL REPAIR
I=REPAIR L=REFINISH BR=BLEND REFINISH
TT=TWO-TONE CG=CHIPGUARD SB=SUBLET
N=ADDITIONAL LABOR RI=R&I ASSEMBLY P=CHECK
AA=APPEAR ALLOWANCE RP=RELATED PRIOR UP=UNRELATED PRIOR

2000 PONTIAC GRAND PRIX SE 4DOOR SEDAN 6CYL GASOLINE 3.1
CODE: W3263A/D OPTNS M/24DQR

OPTIONS:
TWO-STAGE - EXTERIOR SURFACES TWO-STAGE - INTERIOR SURFACES
HEATED BACK GLASS ANTI-LOCK BRAKE SYSTEM
TRACTION CONTROL SYSTEM

OP	GDE	MC	DESCRIPTION	MFG. PART NO.	PRICE	AJ%	B%	HOURS	R
I	0182		MLDG, FRONT DOOR SID LT REPAIR					0.5*	1
L	0182	13	MLDG, FRONT DOOR SID LT REFINISH					1.3	4
				0.6 SURFACE					
				0.6 TWO STAGE SETUP					
				0.1 TWO STAGE					
L	M17		COVER CAR EXTERIOR REFINISH		10.00*				4

3 ITEMS

MC MESSAGE(S)
13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

FINAL CALCULATIONS & ENTRIES

2000 PONTIAC GRAND PRIX SE 4DOOR SEDAN
CD LOG NO 8365-1

OTHER PARTS				10.00
PAINT MATERIAL				46.80
PARTS & MATERIAL TOTAL				56.80
TAX ON PARTS & MATERIAL @			5.600%	3.18

LABOR	RATE	REPLACE HRS	REPAIR HRS	
1-SHEET METAL	56.00		0.5	28.00
2-MECH/ELEC	85.00			
3-FRAME	80.00			
4-REFINISH	56.00	1.3		72.80
5-PAINT MATERIAL	36.00			
LABOR TOTAL				100.80
TAX ON LABOR		@	5.600%	5.64
SUBLET REPAIRS				
TOWING				
STORAGE				

GROSS TOTAL 166.42

NET TOTAL 166.42

SHOPLINK U6077 ES CD LOG 8365-1 DATE 07/22/14 04:37:16PM R6.37 CD 06/14
PXN: Y/00/00/00/00/00 CUM 00/00/00/00/00 GEOCODE 53227
HOST LOG
(C) 1998 - 2008 AUDATEX NORTH AMERICA, INC.

0.7 HRS WERE ADDED TO THIS EST. BASED ON AUDATEX TWO-STAGE REFINISH FORMULA.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE REPLACEMENT PARTS RATHER THAN BY THE MANUFACTURER OF YOUR MOTOR VEHICLE.







