



THE HARTFORD  
CENTRAL RECOVERY OFFICE  
P.O. BOX 14272  
LEXINGTON KY 40512

August 2, 2024

CITY OF WEST ALLIS  
Attention: 05/27/2024  
7525 W GREENFIELD AVE RM 108  
MILWAUKEE WI 53214 US

Re: Our Insured: Andrew Williams Jr. & Connie Mccants  
Claimant: Andrew Williams Jr. & Connie Mccants  
Date of Loss: 2024-05-27  
Event Number: PA0020448492  
Claim Number: Y4M MD 56870  
Responsible party: West Allis Fire Dept  
Amount of Loss: \$1325.06

Dear CITY OF WEST ALLIS:

Your Claim No: 05/27/2024  
Deductible: \$250

Enclosed are copies of our supporting documents which are evidence of our subrogation demand. Our investigation reveals that your insured was negligent. Therefore, we are seeking to recover \$1325.06 in damages.

We are requesting that you please review the enclosed documents as soon as possible and advise us of your position on settlement of our claim and the insured's deductible. If you have already reimbursed our insured his/her deductible and/or any other expenses, please contact us at the telephone number provided below.

PLEASE REMIT ALL PAYMENTS TO: Hartford Fire Insurance Company ("The Hartford"), PO BOX 7247-7744, PHILADELPHIA, PA 19170-7744.

Thank You,  
The Hartford

*Central Recovery Operations*

Central Recovery Operations  
Subrogation Handler  
Toll Free Number: (866) 509 - 3574  
CROclaims.edm@thehartford.com

Writing Company Name: Hartford Fire Insurance Company

Enclosures:

CRO00017

Y4M MD 56870

Exposure

Exposure Owner

Approved By Group

Approved By User

Created By

Check Number

(1) 1st Party Vehicle - Andrew Williams Jr. & Connie Mccants

Aneesa Hassan

Invoice Number

Check Payee

Optional parameters

Check Total

From

To

Status



Pay To


Search For Date

All Payments

SearchReset

Search Results

Exposure	Coverage		Pay To	Net Amount	Scheduled Send Date	Issue Date	Pay Method	Check Number	Status	Bank Paid Date	Created On	Created By	Comments
(1) 1st Party Vehicle - Andrew Williams Jr. & Connie Mccants	Comprehensive		Crest Cadillac	\$1,075.06	06/20/2024	06/20/2024	EFT	934107633	Cleared	06/21/2024	06/20/2024	Aneesa Hassan	

Exposure	Coverage		Pay To	Net Amount	Scheduled Send Date	Issue Date	Pay Method	Check Number	Status	Bank Paid Date	Created On	Created By	Comments
Checks Total													

# HARTFORD FIRE INSURANCE CO.

## CENTRAL REGION

Supplements will require photos and invoices. Please submit supplement requests using CCC estimate share. If you do not have access to CCC, send all documentation (including claim number) to the following email:  
autosupplements@thehartford.com

PO Box 14268  
Lexington, KY 40512  
Phone: (800) 280-0555  
Fax: (866) 809-9794

Claim #: PA0020448492-01  
Workfile ID: 7549b3f9

### Estimate of Record

Written By: BRADLEY REVERMAN, 6/17/2024 5:58:11 PM  
Adjuster: HASSAN, ANEESA, (800) 236-0398 Business

Insured:	Andrew Williams Jr. Mccants	Owner Policy #:	55100118625	Claim #:	PA0020448492-01
Type of Loss:	Comprehensive	Date of Loss:	05/27/2024 04:01 AM	Days to Repair:	0
Point of Impact:	16 Non-Collision	Deductible:	250.00		

#### Owner (Insured):

Andrew Williams Jr. Mccants  
PO Box 100342  
Cudahy, WI 53110-6105  
(414) 687-2100 Cellular  
olyasavage1@gmail.com

#### Inspection Location:

12800 W Capitol Dr  
Brookfield, WI 53005  
Desk  
(877) 230-3084 Day

#### Appraiser Information:

Bradley.Reverman@TheHartford.com  
(317) 249-3803

#### Repair Facility:

### VEHICLE

2005 CADI DeVille Livery 4D SED 8-4.6L Gasoline SFI

VIN:	1G6KD54Y95U136222	Production Date:	09/2004	Interior Color:	Shale
License:		Odometer:		Exterior Color:	
State:		Condition:			

#### TRANSMISSION

Automatic Transmission  
Overdrive

#### POWER

Power Steering  
Power Brakes  
Power Locks  
Power Mirrors  
Heated Mirrors  
Power Driver Seat  
Power Passenger Seat

#### DECOR

Dual Mirrors

Tinted Glass

#### CONVENIENCE

Air Conditioning  
Intermittent Wipers  
Tilt Wheel  
Cruise Control  
Rear Defogger  
Keyless Entry  
Message Center  
Steering Wheel Touch Controls  
Climate Control

#### RADIO

AM Radio  
FM Radio  
Stereo  
Search/Seek  
CD Player

#### SAFETY

Drivers Side Air Bag  
Passenger Air Bag  
Anti-Lock Brakes (4)  
4 Wheel Disc Brakes  
Front Side Impact Air Bags

Communications System

#### SEATS

Leather Seats

#### WHEELS

Aluminum/Alloy Wheels

#### PAINT

Clear Coat Paint

#### OTHER

Traction Control  
Signal Integrated Mirrors  
Power Trunk/Liftgate

## Estimate of Record

2005 CADI DeVille Livery 4D SED 8-4.6L Gasoline SFI

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		<b>STEERING COLUMN</b>					
2	*	Repl Case	26089434	1	123.78	<u>Incl.</u>	
3	#	Rpr Keys	84870459			<u>Incl.</u>	
4	#	Subl Key Cut		1	5.00 X		
5	#	Subl Code Keys		1	54.95 X		
6	#	Repl Cylinder Kit	15298923	1	119.16		
7	#	Subl Labor to replace steering column and cylinder.		1	755.02 X		
8	#	Subl Towing		1	255.00 X		
<b>SUBTOTALS</b>					<b>1,312.91</b>	<b>0.0</b>	<b>0.0</b>

### ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			242.94
Miscellaneous			1,069.97
Subtotal			1,312.91
Sales Tax	\$ 242.94 @	5.0000 %	12.15
<b>Total Cost of Repairs</b>			<b>1,325.06</b>
Deductible			250.00
<b>Total Adjustments</b>			<b>250.00</b>
<b>Net Cost of Repairs</b>			<b>1,075.06</b>

MyPriceLink Estimate ID / Quote ID:  
 1232082363551326208 / 137354775

THIS ESTIMATE IS NOT AN AUTHORIZATION TO REPAIR. REPAIRS MUST BE AUTHORIZED BY THE VEHICLE OWNER. NO SUPPLEMENTS WILL BE HONORED WITHOUT REINSPECTION OR PRIOR APPROVAL BY THE HARTFORD INSURANCE GROUP.

IF THE VEHICLE IS DETERMINED TO BE A TOTAL LOSS, PAYMENT WILL NOT BE BASED ON THIS ESTIMATE OR COST OF REPAIRS.

Supplements will require photos and invoices. Please submit supplement requests using CCC estimate share. If you do not have access to CCC send all documentation (including claim number) to the following email: [autosupplements@thehartford.com](mailto:autosupplements@thehartford.com)

Supplements will require photos and invoices. Please submit supplement requests using CCC estimate share. If you do not have access to CCC, send all documentation (including claim number) to the following email: [autosupplements@thehartford.com](mailto:autosupplements@thehartford.com)

## Estimate of Record

---

2005 CADI DeVille Livery 4D SED 8-4.6L Gasoline SFI

MOTOR VEHICLE REPAIR PRACTICES ARE REGULATED BY CHAPTER ATPC 132, WIS. ADM. CODE, ADMINISTERED BY THE BUREAU OF CONSUMER PROTECTION, WISCONSIN DEPT. OF AGRICULTURE, TRADE AND CONSUMER PROTECTION, P.O. BOX 8911, MADISON, WISCONSIN 53708-8911.

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DE1BA00, CCC Data Date 06/10/2024, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (\*) or Double Asterisk (\*\*) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2024 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

### SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category.  
X=Miscellaneous Non-Taxed charge category.

### SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category.  
M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

### OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel.  
CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel.  
HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non  
Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace.  
R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel.  
Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

## Estimate of Record

---

2005 CADi DeVille Livery 4D SED 8-4.6L Gasoline SFI

CCC ONE Estimating - A product of CCC Intelligent Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

### Estimate of Record

2005 CADI DeVille Livery 4D SED 8-4.6L Gasoline SFI

#### ALTERNATE PARTS USAGE

2005 CADI DeVille Livery 4D SED 8-4.6L Gasoline SFI

VIN:1G6KD54Y95U136222

Production Date:09/2004

Interior Color:Shale

License:

Odometer:

Exterior Color:

State:

Condition:

Alternate Part Type	# Of Available Parts	# Of Parts Selected
Aftermarket	0	0
Optional OEM	0	0
Reconditioned	0	0
Recycled	0	0



## Estimate of Record

---

2005 CADI DeVille Livery 4D SED 8-4.6L Gasoline SFI

### RECALL INFO

2005 CADI DeVille Livery 4D SED 8-4.6L Gasoline SFI

VIN:	1G6KD54Y95U136222	Production Date:	09/2004	Interior Color:	Shale
License:		Odometer:		Exterior Color:	
State:		Condition:			

---

The National Highway Transportation and Safety Administration (NHTSA) has issued 1 safety-related recall notice(s) that may apply to the selected vehicle.

**NHTSA ID:** 14V355000      **Issued:** Jun 6, 14      **Number of Vehicles:** 03141731

**ELECTRICAL SYSTEM** This defect can affect the safe operation of the airbag system. Until this recall is performed, customers should remove all items from their key rings, leaving only the ignition key. The key fob (if applicable), should also be removed from the key ring. General Motors LLC (GM) is recalling certain model year 2005-2009 Buick LaCrosse, 2006-2011 Buick Lucerne, 2000-2005 Cadillac DeVille, 2006-2011 Cadillac DTS, 2006-2014 Chevrolet Impala, and 2006-2007 Chevrolet Monte Carlo vehicles. In the affected vehicles, the weight on the key ring and road conditions or some other jarring event may cause the ignition switch to move out of the run position, turning off the engine. If the key is not in the run position, the air bags may not deploy if the vehicle is involved in a crash, increasing the risk of injury. Additionally, a key knocked out of the run position could cause loss of engine power, power steering, and power braking, increasing the risk of a vehicle crash. GM will notify owners, and dealers will install two 13mm key rings and key insert into the vehicle's ignition keys, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact General Motors customer service at 1-800-521-7300 (Buick), 1-800-458-8006 (Cadillac), and 1-800-222-1020 (Chevrolet). GM's number for this recall is 14299.