

City of West Allis Matter Summary

7525 W. Greenfield Ave. West Allis, WI 53214

File Number		Title	Status		
	2004-0077	Communication	In Committee		
		Communication from City Engineer regard	ing the brick work on Fire Station No. 1.		
		Introduced: 2/3/2004	Controlling Body: Public Works Committee		

COMMITTEE	RECOMM	ENDATION _	approve	2			
ACTION DATE: 2-3-04	MOVER	SECONDER	Barczak Czaplewski Kopplin Lajsic Narlock Reinke Sengstock Trudell Vitale Weigel TOTAL	AYE	NO	PRESENT	EXCUSED
SIGNATURE O. Chair	F COMMIT	Vice-0		ER)	Membe	er	
COMMON CO	UNCIL AC	TION	pprove				
ACTION DATE: 2-3-04	MOVER	SECONDER	Barczak Czaplewski Kopplin Lajsic Narlock Reinke Sengstock Trudell Vitale Weigel TOTAL	AYE V V V P P P	NO	PRESENT	EXCUSED





MICHAEL G. LEWIS City Engineer

Engineering Department

February 3, 2004

Board of Public Works City of West Allis West Allis, WI 53214

RE: Status on Poor Brick Work on New Fire Station No. 1

Dear Board Members:

Attached is a letter which I would like the Board to review and approve to mail to WB Corporation regarding repair of the poor brick work on part of the east side and all of the long side of the new Fire Station No. 1.

Respectfully,

Michael G. Lewis City Engineer

MGL/mgl



CITY OF WEST ALLIS

WISCONSIN



MICHAEL G. LEWIS

City Engineer

Engineering Department

February 3, 2004

Dan Gonwa, Project Manager WB Corporation 2150 Stonebridge Road P.O. Box 934 West Bend, WI 53095

RE:

Poor Brick Work - North and Part of East Side

New Fire Station No. 1 2002 - Project 14

Dear Mr. Gonwa:

As you are aware, the West Allis Board of Public Works has been concerned about the poor appearance of the brick work on the north side and on part of the east side of the new Fire Station building for quite some time. Even though we have been patient and have been assured by your subcontractor that the appearance would improve with time, we have not seen any difference over the last year.

This issue was discussed again at the last Board of Public Works meeting. The Board agreed to try the proposed staining method. Last year, a trial 6' by 6' panel was done between the doors on the north side. The results were satisfactory and this is the end result we are expecting on the remainder of the work.

When work is scheduled, we will have representatives there at the start and periodically throughout the work to inspect the progress, but we are not anticipating having someone on site the entire time.

On a related matter, you have received a punchlist from the Architect. Most of this work deals with outside problems that will need to be repaired in spring. There are also a number of rough and final inspections that need to be completed by the West Allis Building Department. Keith Strege has told us that to his knowledge you have not yet scheduled these inspections. After a meeting with Fire Station representatives later this week, there may be other issues that will need to be addressed.



Engineering Department

mg Department
We are looking for you to submit a schedule for this work soon. If you have the property in the submit a schedule for this work soon. questions, please contact me.

Sincerely,

Michael G. Lewis City Engineer

Keith A. Kerwin, Plunkett Raysich Architects CC: Steven Hook, Fire Chief Martin King, Fire Inspection