



CLAIMANT CONTACT INFORMATION

Name: RONALD GORDON
Address: 7871 N FAIRWAY PLACE
MILWAUKEE WI 53223

Phone: 414-732-7091
Email: _____

INSTRUCTIONS

Complete this form and sign it, and serve a hard copy upon the West Allis City Clerk. If you have questions about how to fill out this form, please contact a private attorney who can assist you.

NOTICE OF CLAIM

Date of incident: NOVEMBER 18, 2022 Time of day: 430 AM
Location: 1231 S 71ST WEST ALLIS WISCONSIN

Describe the circumstances of your claim here. You may attach additional sheets or exhibits. Some helpful information may be the police report, pictures of the incident or damage, a diagram of the location, a list of injuries, a list of property damage, names and contact information for witnesses to the incident, and any other information relevant to the circumstances.

INCIDENT NARRATIVE IS ATTACHED.

POLICE REPORT ATTACHED 22.043392

PHOTOS OF DAMAGES ATTACHED

Check one:

- ☒ I am seeking damages at this time (complete Claim Amount section below)
☐ I am submitting this notice without a claim for damages. This claim is not complete and will not be processed until I submit a claim for damages on a later date.

Signed: _____

Date: 11/30/2022

CLAIM AMOUNT

To complete this claim, attach an itemized statement of damages sought. If any damages are for repair to property, include at least 2 estimates for repairs.

The total amount sought is: \$ 5827.89 / \$4965.33

2003 GMC Envoy accident.

I am submitting this claim regarding a motor vehicle accident, which resulted in damages to my parked 4 door white 2003 GMC Envoy VIN [REDACTED] WI plate [REDACTED] after my above noted parked vehicle was struck by a City of West Allis large truck with a sweeper attachment. The incident occurred on Friday 11/18/2022 at 4:30 AM. My above listed vehicle was parked on the street at 1231 S. 71st St when the accident occurred. The West Allis Police Department was notified by the City Of West Allis employee who was operating the large truck which struck my vehicle causing the damages to my vehicle. Upon arrival of the West Allis Police Officer Cooper (3rd shift) contacted my son Clifford L. Garner Jr PH 414-379-1552 by going to my son's residence 1231 S. 71st St and notifying my son that a city of West Allis owned/operated truck struck my parked vehicle causing damages. My son contacted me on 11/18/2022 at 4:54 AM and notified me of the accident after being notified by the West Allis Police Officer Cooper. My son also provided me with photos of the damages to my vehicle via cellphone. I could not go to the scene of the accident, due to my family left home hours earlier on vacation en-route to our Thanksgiving Holiday vacation destination. Upon returning home a week and a few days later, I physically observed the damaged to my above listed vehicle. I also obtained 2 estimates for the damages to my vehicle. The damages to my vehicle consist of the following. Front bumper damage, driver side front fender damage which is also causing the damaged metal fender to strike/rub against the driver side tire, damage to the hood, damage to the drivers door preventing entry to the driver's door due to the damage, driver side headlamp and turn signal and fog lamp assembly's. My vehicle is unsafe to drive at this time due to the listed damages and driver tire striking against the front driver side fender as well as the driver door possibly opening due to the damages. I can no longer operate my vehicle which I need to get to work daily. *REPORT # 22.043392*

Estimates are attached.

Tender Car \$4965.33

Collision Center of Milwaukee North 5827.89

Thank you

Ronald Gordon



West Allis Police Department



22.043392

Accident/PDO

Disposition **Update**
Unit **325**

Case #: 22-043392

11/18/22 04:3639

1225 S 71 St

Officer **JC3173**

CAD Comments

Dpw backed into a parked vehicle

Dispatched: 325

RO not in locals

On 11/18/2022 at 0436 hrs., officers were dispatched to 1225 S. 71 St. for a PDO. On scene investigation showed that West Allis Loader 2919 backed into a parked vehicle [REDACTED]. Due to the Loader being equipment, Tracs form was not filled out and information was given to the RO to further handle the process.

COLLISION CENTER

OF

MILWAUKEE NORTH

Collision Center of Milwaukee North

BMW Certified Collision Repair Center
1711 W FLORIST, MILWAUKEE, WI 53209
Phone: (414) 290-4360
FAX: (414) 290-4359

Workfile ID: b51f8fdb
PartsShare: 75cMj5
Federal ID: 81-0947183

Preliminary Estimate**Customer: Gordon, Ronald**

Written By: Hieronim Piotrowski

Insured: Gordon, Ronald
Type of Loss:
Point of Impact:

Policy #:
Date of Loss:

Claim #:
Days to Repair: 0

Owner:

Gordon, Ronald
(414) 732-7091 Cell

Inspection Location:

Collision Center of Milwaukee North
1711 W FLORIST
MILWAUKEE, WI 53209
Repair Facility
(414) 290-4360 Business

Insurance Company:**VEHICLE**

2003 GMC Envoy SLT 4WD 4D UTV 6-4.2L Gasoline SFI white

VIN: [REDACTED]	Interior Color:	Mileage In: 123	Vehicle Out:
License:	Exterior Color: white	Mileage Out:	
State: WI	Production Date:	Condition:	Job #:

TRANSMISSION

Automatic Transmission
Overdrive
4 Wheel Drive

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Heated Mirrors
Power Driver Seat
Power Passenger Seat
Memory Package

DECOR

Dual Mirrors

Body Side Moldings

Privacy Glass
Console/Storage
Overhead Console

CONVENIENCE

Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Message Center
Steering Wheel Touch Controls
Rear Window Wiper
Climate Control
Home Link

RADIO

AM Radio
FM Radio
Stereo
Search/Seek
CD Player

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Communications System

ROOF

Luggage/Roof Rack

SEATS

Bucket Seats

Reclining/Lounge Seats

Leather Seats

WHEELS

Aluminum/Alloy Wheels

PAINT

Clear Coat Paint

OTHER

Fog Lamps
Signal Integrated Mirrors

TRUCK

Rear Step Bumper
Trailer Hitch
Trailer Package
Power Trunk/Liftgate

Get live updates at www.carwise.com/e/4oy7vZ

Preliminary Estimate

Customer: Gordon, Ronald

2003 GMC Envoy SLT 4WD 4D UTV 6-4.2L Gasoline SFI white

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		FRONT BUMPER					
2		O/H bumper assy				1.8	
3	Repl	Bumper cover	88937036	1	320.25	Incl.	2.6
4		Add for Clear Coat					1.0
5		Add for fog lamps				0.4	
6		FRONT LAMPS					
7	Repl	LT Headlamp assy	15866071	1	209.17	0.4	
8		Aim headlamps				0.5	
9	R&I	RT Headlamp assy				0.4	
10	Repl	LT Fog lamp	15269042	1	60.42	Incl.	
11		Aim fog lamps				0.3	
12	Repl	LT Cornering lamp	15937713	1	49.75	Incl.	
13		HOOD					
14	Repl	Hood GMC	12478014	1	368.00	0.8	2.8
15		Add for Clear Coat					1.1
16		Add for Underside(Complete)					1.4
17		Add for Clear Coat					0.3
18	R&I	Insulator				Incl.	
19	R&I	Front seal				Incl.	
20	R&I	Front molding GMC				0.2	
21		FENDER					
22	Repl	LT Fender GMC	12477995	1	329.12	2.0	2.2
23		Overlap Major Adj. Panel					-0.4
24		Add for Clear Coat					0.4
25		Add for Edging					0.5
26		Add for Clear Coat					0.1
27	R&I	LT Fender liner				Incl.	
28		FRONT DOOR					
open	Repl	LT Door shell	88937088	1	710.98	5.3	3.4
30		Overlap Major Adj. Panel					-0.4
31		Add for Clear Coat					0.6
32	R&I	LT Belt w/strip				Incl.	
33	R&I	LT R&I side mldg				0.3	
34	Repl	LT Nameplate "ENVOY"	15123976	1	69.99	0.2	
35	R&I	LT Mirror assy w/power w/heated				Incl.	
36	R&I	LT Door glass GM				Incl.	
37	R&I	LT Handle, outside black				Incl.	
38	R&I	LT R&I trim panel				Incl.	
39		MISCELLANEOUS OPERATIONS					
40	#	Car Cover / Mask For Overspray Color And Clear		1	6.00		0.2
41	#	Car Cover / Mask For Overspray Priming		1	6.00		0.2

Preliminary Estimate

Customer: Gordon, Ronald

2003 GMC Envoy SLT 4WD 4D UTV 6-4.2L Gasoline SFI white

42	#	De-nib & Polish / Buff .5 Per Panel	1	5.00	1.5
43	#	Flex Additive	1	15.00	
44	#	Hazardous Waste Disposal	1	10.00	
45	#	Tint Color	1		0.5
46	#	**POSSIBLE HIDDEN DAMAGES - ADDITIONAL CHARGES MAY APPLY**	1		
47	#	Subl Pre-Scan	1	50.00	
48	**	Subl A/M Post scan - ALL OTHER BRANDS	1	125.00	
49	#	Drive time to sublet vendor	1		0.5 1
50	#	Test Fit New Panel	1		0.5
SUBTOTALS				2,334.68	13.6 18.0

NOTES

Prior Damage Notes:

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			2,334.68
Body Labor	13.1 hrs @	\$ 72.00 /hr	943.20
Paint Labor	18.0 hrs @	\$ 72.00 /hr	1,296.00
Aluminum	0.5 hrs @	\$ 100.00 /hr	50.00
Paint Supplies	18.0 hrs @	\$ 50.00 /hr	900.00
Subtotal			5,523.88
Sales Tax	\$ 5,523.88 @	5.5000 %	303.81
Grand Total			5,827.69
Deductible			0.00
CUSTOMER PAY			0.00
INSURANCE PAY			5,827.69

MyPriceLink Estimate ID / Quote ID:

1026962826939342848 / 115375018

MOTOR VEHICLE REPAIR PRACTICES ARE REGULATED BY CHAPTER ATCP 132, WIS. ADM. CODE, ADMINISTERED BY THE BUREAU OF CONSUMER PROTECTION, WISCONSIN DEPT. OF AGRICULTURE, TRADE AND CONSUMER PROTECTION, P.O. BOX 8911, MADISON, WISCONSIN 53708-8911.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE REPLACEMENT PARTS RATHER THAN BY THE MANUFACTURER OF YOUR MOTOR VEHICLE.

Preliminary Estimate

Customer: Gordon, Ronald

2003 GMC Envoy SLT 4WD 4D UTV 6-4.2L Gasoline SFI white

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DE1GN02, CCC Data Date 11/15/2022, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2023 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

Tender Car Auto Body
1825 S. Kinnickinnic Ave
Milwaukee, WI 53204
Tel: (414) 389-1014 Fax: (414) 389-1779
tendercar@gmail.com # 27-0157878

*** PRELIMINARY ESTIMATE ***

11/29/2022 03:42 PM

Owner

Owner: Ronald Gordon
Address:

Cell: (414)732-7091

Inspection

Inspection Date: 11/29/2022 03:42 PM

Inspection Type:

Company: Tender Car
Address: 8055 N 76th Street
City State Zip: Milwaukee, WI 53223
Email: tendercarnorth@gmail.com

Appraiser License # :
Work/Day: (414)433-9393
FAX:

Repairer

Repairer: Tender Car
Address: 1825 South Kinnickinnic
City State Zip: Milwaukee, WI 53204
Email: tendercar@gmail.com

Contact:
Work/Day: (414)389-1014
Work/Day:

Target Complete Date/Time:

Days To Repair: 9

Vehicle

OEM Part Price Quote ID: ****

2003 GMC Envoy SLT 4 DR Wagon
6cyl Gasoline 4.2
4 Speed Automatic

Lic Expire:
Prod Date: 05/2003
Veh Insp# :
Condition:
Ext. Color: Summit White
Ext. Refinish: Two-Stage
Ext. Paint Code: 50U

VIN: XXXXXXXXXX
Mileage:
Mileage Type: Actual
Code: U7213A
Int. Color: MEDIUM DARK PEWTER
Int. Refinish:
Int. Trim Code: 12V,92

Options - AudaVIN Information Received

4-Wheel Drive
Anti-Lock Brakes
Camper/Towing Package
Cruise Control
Dual Airbags
Fog Lights
Heated Power Mirrors
Leather Seats
OnStar System

AM/FM CD Player
Auto Locking Hubs (4WD)
Center Console
Driver Information Sys
Dual Power Seats
Garage Door Opener
Intermittent Wipers
Leather Steering Wheel
Overhead Console

Alarm System
Automatic Dimming Mirror
Climate Control For A/C
Dual Air Conditioning
Electronic Transfer Case
Heated Front Seats
Keyless Entry System
Lighted Entry System
Polished Alloy Wheels

MC	Message
13	INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

Estimate Total & Entries

OEM Parts		\$1,987.27	
Other Parts		\$13.00	
Paint & Materials	17.4 Hours @ \$42.00	\$730.80	
Parts & Material Total			\$2,731.07
Tax on Parts & Material	@ 5.500%		\$150.21

Labor	Rate	Replace Hrs	Repair Hrs	Total Hrs	
Sheet Metal (SM)	\$62.00	12.3		12.3	\$762.60
Mech/Elec (ME)	\$130.00				
Frame (FR)	\$95.00				
Refinish (RF)	\$62.00	16.4	1.0	17.4	\$1,078.80
Labor Total				29.7 Hours	\$1,841.40
Tax on Labor		@ 5.500%			\$101.28
Sublet Repairs					\$134.00
Tax on Sublet		@ 5.500%			\$7.37
Gross Total					\$4,965.33
Net Total					\$4,965.33

Alternate Parts Y/06/00/00/06/06 Cumulative 06/00/00/06/06 Zip Code: 53204 Default
OEM Part Prices DT 11/29/2022 03:42 PM EstimateID 1026972669788037120 QuoteID ****
Rate Name Default

Audatex Estimating 10.19.136 ES 11/29/2022 03:45 PM REL 10.19.136 DT 11/01/2022 DB 11/15/2022
State Disclosure:WI
© 2022 Audatex North America, Inc.

2.6 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.

Op Codes

* = User-Entered Value	^ = Labor Matches System Assigned Rates	E = Replace OEM
NG= Replace NAGS	EC= Replace Economy	OE = Replace PXN OE Srpls
UE = Replace OE Surplus	ET = Partial Replace Labor	EP = Replace PXN
EU = Replace Recycled	TE = Partial Replace Price	PM= Replace PXN Reman/Reblt
UM= Replace Reman/Rebuilt	L = Refinish	PC = Replace PXN Reconditioned
UC= Replace Reconditioned	TT = Two-Tone	SB = Sublet Repair
N = Additional Labor	BR = Blend Refinish	I = Repair
IT = Partial Repair	CG= Chipguard	RI = R & I Assembly
P = Check	AA = Appearance Allowance	RP = Related Prior Damage

Power Brakes	Power Door Locks	Power Steering
Power Windows	Privacy Glass	Rear Heater
Rear Seat Audio Controls	Rear Window Defroster	Rear Window Wiper/Washer
Rem Trunk-L/Gate Release	Roof/Luggage Rack	Split Folding Rear Seat
Strg Wheel Radio Control	Tachometer	Tilt Steering Wheel
Tinted Glass	Trailer Hitch	Trip Computer
Wood Interior Trim		

AudaVIN options are listed in bold-italic fonts

Damages

Line	Op	Guide	MC	Description	MFR.Part No.	Price	ADJ%	B%	Hours	R
Stripes And Mouldings										
1	RI	418		Mldg,Front Door Side LT	R & I Assembly				0.6	SM
Front Bumper										
2	E	6		Cover,Front Bumper	88937036 GM Part	\$320.25			1.9	SM
3	L	6	13	Cover,Front Bumper	Refinish				3.8	RF
					2.7 Surface					
					0.6 Two-stage setup					
					0.5 Two-stage					
Front End Panel And Lamps										
4	E	41		Headlamp Assy,Halogen LT	15866071 GM Part	\$209.17			0.3	SM
5	E	280		Lamp,Cornering LT	15937713 GM Part	\$49.75			INC	SM
6	RI	65		Lamp Assembly,Fog LT	R & I Assembly				INC	SM
7	RI	66		Lamp Assembly,Fog RT	R & I Assembly				INC	SM
Front Body And Windshield										
8	E	83		Panel,Hood	12478014 GM Part	\$368.00			1.8	SM
9	L	83		Panel,Hood	Refinish				4.8	RF
					3.0 Surface					
					1.2 Edge					
					0.6 Two-stage					
10	E	103		Fender,Front LT	12477995 GM Part	\$329.12			1.6	SM
11	L	103		Fender,Front LT	Refinish				2.9	RF
					2.0 Surface					
					0.5 Edge					
					0.4 Two-stage					
Front Doors										
12	E	207		Door Shell,Front LT	88937088 GM Part	\$710.98			5.8	SM
13	L	207		Door Shell,Front LT	Refinish				3.9	RF
					2.4 Surface					
					1.0 Edge					
					0.5 Two-stage					
14	RI	243		W/Strip,Belt Outer LT	R & I Assembly				INC	SM
15	RI	401		Applique,Frt Door Fram LT	R & I Assembly				0.3	SM
16	RI	229		Mirror,Outer R/C LT	R & I Assembly				INC	SM
17	RI	227		Handle,Front Door Otr LT	R & I Assembly				INC	SM
Manual Entries										
18	L			COLOR SAND AND BUFF	Refinish				1.0*	RF
19	EC			COVER CAR	Replace Economy	\$5.00*				SM
20	EC			FLEX ADDATIVE	Replace Economy	\$8.00*				SM
21	SB			4 WHEEL ALIGNMENT	Sublet Repair	\$129.00*				SM
22	SB			HAZARDUS WASTE REMOVAL	Sublet Repair	\$5.00*				SM
23	N			COLOR TINT	Additional Labor				1.0*	RF
23 Items										



This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

© 2022 Audatex North America, Inc.
AUDATEX is a trademark owned by Audatex
North America, Inc. All rights reserved.



