



## CLAIMANT CONTACT INFORMATION

Name: Donald Walker  
Address: 10531 W. Madison St.  
West Allis WI 53214

Phone: 414-550-7916  
Email: soundbustersdj@yaho.com

### INSTRUCTIONS

Complete this form, print and sign it, and serve a hard copy upon the West Allis City Clerk. If you have questions about how to fill out this form, please contact a private attorney who can assist you.

### NOTICE OF CLAIM

Date of incident: 03/25/2023  
Location: Front of my house

Time of day: 02:30 P.M.

Describe the circumstances of your claim here. You may attach additional sheets or exhibits. Some helpful information may be the police report, pictures of the incident or damage, a diagram of the location, a list of injuries, a list of property damage, names and contact information for witnesses to the incident, and any other information relevant to the circumstances.

I was parked on Madison St. Plow truck 820 was plowing and accidentally backed up into the left front of my vehicle. The supervisor came and took information.

Check one:

- ☒ ..... I am seeking damages at this time (complete Claim Amount section below)  
☐ ..... I am submitting this notice without a claim for damages. This claim is not complete and will not be processed until I submit a claim for damages on a later date.

Signed: Donald Walker

Date: 03/29/2023

### CLAIM AMOUNT

To complete this claim, attach an itemized statement of damages sought. If any damages are for repair to property, include at least 2 estimates for repairs.

The total amount sought is: \$ 2,279.64

SAVE

PRINT



## Boucher Auto Body & Paint- West Allis

We Ride With You Every Mile  
3161 S. 108th St, West Allis, WI 53227  
Phone: (414) 327-6000  
FAX: (414) 546-5825

Workfile ID: 782061ea  
PartsShare: 7gmD56  
Federal ID: 39-1275419

### Preliminary Estimate

**Customer: Walker, Donald**

Written By: COURTNEY WENTZEL

Insured: Walker, Donald  
Type of Loss:  
Point of Impact: 11 Left Front

Policy #:  
Date of Loss:

Claim #:  
Days to Repair: 0

**Owner:**

Walker, Donald  
10531 W MADISON ST  
West Allis, WI 53214  
(414) 550-7916 Cell

**Inspection Location:**

Boucher Auto Body & Paint- West Allis  
3161 S. 108th St  
West Allis, WI 53227  
Repair Facility  
(414) 327-6000 Business

**Insurance Company:**

### VEHICLE

2007 CHEV Uplander LT1 Extended WB 4D VAN 6-3.9L Gasoline SFI Blue

VIN: [REDACTED]	Interior Color:	Mileage In:	Vehicle Out:
License: [REDACTED]	Exterior Color: Blue	Mileage Out:	
State: WI	Production Date:	Condition:	Job #:

**TRANSMISSION**

Automatic Transmission  
Overdrive

**POWER**

Power Steering  
Power Brakes  
Power Windows  
Power Locks  
Power Mirrors  
Heated Mirrors  
Power Driver Seat

**DECOR**

Dual Mirrors  
Body Side Moldings

Privacy Glass

Console/Storage

**CONVENIENCE**

Air Conditioning  
Intermittent Wipers  
Tilt Wheel  
Cruise Control  
Rear Defogger  
Keyless Entry  
Rear Window Wiper  
Dual Air Condition  
Entertainment Center  
Power Sliding Door  
Home Link

**RADIO**

AM Radio  
FM Radio  
Stereo  
Search/Seek  
CD Player  
Auxiliary Audio Connection

**SAFETY**

Drivers Side Air Bag  
Passenger Air Bag  
Anti-Lock Brakes (4)  
4 Wheel Disc Brakes  
Traction Control  
Stability Control

Front Side Impact Air Bags  
Communications System  
Hands Free Device

**ROOF**

Luggage/Roof Rack

**SEATS**

Cloth Seats  
3rd Row Seat  
Captain Chairs (4)

**WHEELS**

Aluminum/Alloy Wheels

**PAINT**

Clear Coat Paint

Get live updates at [www.carwise.com/e/4txBCy](http://www.carwise.com/e/4txBCy)

## Preliminary Estimate

**Customer: Walker, Donald**

2007 CHEV Uplander LT1 Extended WB 4D VAN 6-3.9L Gasoline SFI Blue

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		<b>FRONT BUMPER</b>					
2	* <>	Rpr Bumper cover				3.0	2.6
3		Add for Clear Coat					1.0
4		Repl Mount panel	15798109	1	254.55	1.7	
5		O/H bumper assy				2.4	
6		<b>FRONT LAMPS</b>					
7		Repl LT Headlamp assy	25891660	1	269.85	Incl.	
8		Aim headlamps				0.5	
9		<b>HOOD</b>					
10	*	Algn Hood				1.5	
11		<b>FENDER</b>					
12		R&I LT Fender liner				0.4	
13	*	Rpr LT Fender				2.0	2.2
14		Overlap Major Non-Adj. Panel					-0.2
15		Add for Clear Coat					0.4
16		<b>MISCELLANEOUS OPERATIONS</b>					
17		Repl Cover car/bag		1		0.2	
18	#	Color tint / color match		1			0.5
19	#	Repl Corrosion protection primer		1	10.00 T		0.3
20	#	Repl Flex additive		1	5.00 T		
<b>SUBTOTALS</b>					<b>539.40</b>	<b>11.7</b>	<b>6.8</b>

### ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			524.40
Body Labor	11.7 hrs @	\$ 70.00 /hr	819.00
Paint Labor	6.8 hrs @	\$ 70.00 /hr	476.00
Paint Supplies	6.8 hrs @	\$ 48.00 /hr	326.40
Miscellaneous			15.00
Subtotal			2,160.80
Sales Tax	\$ 2,160.80 @	5.5000 %	118.84
<b>Grand Total</b>			<b>2,279.64</b>
Deductible			0.00
<b>CUSTOMER PAY</b>			<b>0.00</b>
<b>INSURANCE PAY</b>			<b>2,279.64</b>

**MyPriceLink Estimate ID / Quote ID:**

1069640516586446848 / 121042045